

Property Information

Address: 223 E Lincoln PIN: 05-26-434-021
 Building Names: Colonel Joel Walker Residence
 Important Dates: 1841 (construction date)
 Historic Function: Residence
 Current Function: Residence
 Color Code Criteria: Red
 Outbuildings
 Number: 1 Any Significant:
 Architectural Style: Greek Revival
 Property Type: Residential
 Approximate Age: 1840-1849
 Condition: Good
 Potential for Integrity?



Photo: 223_E_Lincoln_Ave_SURVEY_Photo.tif

Structure Information

Structure: Masonry
 Foundation: Stone Concrete Not Visible
 Brick Parged
 Cladding: Clapboard Asphalt
 Siding Stucco
 Shake Stone
 Board-and-Batten Brick
 Aluminum/Vinyl Concrete Block
 Asbestos Metal

Description

The Greek Revival, single family brick home is two stories with a cross-gabled roof and an L-shaped plan. The foundation is parged and the brick, though heavily painted, is cream colored. The walls, considered the first of brick construction in the city, are rudimentary but laid evenly in a makeshift common bond and stabilized by an iron tie rod with an "S" plate. The front gable end, facing north, spans three windows bays wide with the main entrance at one side. In combination with a central chimney stack, this suggests a side hall plan one-and-one-half rooms wide. The entry porch has a flat roof, bracketed cornice with dentils, chamfered corner posts and pilasters and a simple railing. This reconstructed porch mimics detailing found on a west side bay, but historic photographs reveal there was once a full-width porch. The main entry door is paneled with leaded glass sidelights, a full width transom, rope-like trim and floral corner blocks. The cornice, discontinuous across the gable ends, is wide with several bands of trim. Elliptical fan lites/vents are situation at the attic gable ends. Set back two window bays, the cross gabled section, running east and west, is similarly detailed. At the east, facing Main Street, is a side entrance with a porch similar to the front. At the west elevation, a three-sided window...

Additions

Type: Location:
 Historic Front Rear
 Non-Historic Side Roof

Porch

Type: Material:
 Enclosed Porte Cochere Stone Wood
 Stoop Wraparound Brick Concrete
 Veranda Multi-Story

Significance: Location:
 Historic Altered Front Rear
 Side Balcony

Doors

Leaf: One-Leaf
 Material: Wood
 Significance: Arrangement: Type:
 Historic Sidelights Paneled
 Replacement Transom Paneled w/Lights
 Glazed

Windows

Type: Material: Significance:
 Double-Hung Steel Original Windows
 Sliding Wood Original Storms
 Casement Vinyl Replaced Windows
 Fixed Aluminum Replaced Storms

Roof

Type: Material: Dormers:
 Gable Mansard Asphalt Gable
 Hipped Shed Metal Hipped
 Jerkinhead Flat Slate Shed
 Gambrel Shake Jerkin
 Clay Tile

Chimney

Material: Brick Concrete Block Stone

NR ELIGIBILITY

Individual Eligibility

District Eligibility:

District Name:

Belvidere Old Town NRHP District

Contributing:

Non-Contributing:

Events (NR-A)
 Persons (NR-B)
 Architecture (NR-C)
 Archaeology (NR-D)

LOCAL ELIGIBILITY

Individual Eligibility:

District Eligibility:

District Name:

Belvidere East Lincoln Local Historic District

Contributing:

Non-Contributing:

Events 2
 Persons 3
 Architecture 4, 5, 6, 8
 Archaeology
 Other 1, 7, 9, 10, 11

Property Information

Address: 226 E Lincoln PIN: 05-26-431-010
 Building Names:
 Important Dates:
 Historic Function: Residence
 Current Function: Residence
 Color Code Criteria: Yellow
 Outbuildings
 Number: 1 Any Significant:
 Architectural Style: Settlement
 Property Type: Residential
 Approximate Age: 1850-1859
 Condition: Good/Excellent
 Potential for Integrity?



Photo: 226_E_Lincoln_Ave_SURVEY_Photo.tif

Description

The single family shotgun dwelling is one story has a front and cross-gabled roof with a rectangular plan. The first floor is raised on rough-cut limestone foundation and the walls appear to be brick clad in siding. The primary façade, facing south, is symmetrical with a prominent front gable and a recessed front porch. The front gable is closed, and the porch has been altered with a slab stoop and plain square post supports. At the porch, the single-leaf main entrance door is flanked by two 1/1 double hung windows, all of which are replacements. To the north, a cross gable roof defines the rear elevation. Facing east, a recessed side porch contains an original door set with arch-top lites and paneling. Opposite on the west elevation, a small shed roof frame addition with various window types has been built. The tall, narrow 1/1 windows openings have rectangular sash and many have been replaced. Towards the northeast corner of the property, there is a gabled one car garage clad in siding with multi-pane windows. Though little to no detailing remains, historic photographs confirm that this modest shotgun dwelling likely had a Folk Victorian or Italianate style. However, much of the home's integrity has been lost.

Structure Information

Structure: Frame
 Foundation: Stone Concrete Not Visible
 Brick Parged
 Cladding: Clapboard Asphalt
 Siding Stucco
 Shake Stone
 Board-and-Batten Brick
 Aluminum/Vinyl Concrete Block
 Asbestos Metal

Additions

Type: Location:
 Historic Front Rear
 Non-Historic Side Roof

Porch

Type: Material:
 Enclosed Porte Cochere Stone Wood
 Stoop Wraparound Brick Concrete
 Veranda Multi-Story

Significance: Location:
 Historic Altered Front Rear
 Side Balcony

Doors

Leaf: One-Leaf
 Material: Wood
 Significance: Arrangement: Type:
 Historic Sidelights Paneled
 Replacement Transom Paneled w/Lights
 Glazed

Windows

Type: Material: Significance:
 Double-Hung Steel Original Windows
 Sliding Wood Original Storms
 Casement Vinyl Replaced Windows
 Fixed Aluminum Replaced Storms

Roof

Type: Material: Dormers:
 Gable Mansard Asphalt Gable
 Hipped Shed Metal Hipped
 Jerkinhead Flat Slate Shed
 Gambrel Shake Jerkin
 Clay Tile

Chimney

Material: Brick Concrete Block Stone

NR ELIGIBILITY

Individual Eligibility

District Eligibility:

District Name:

Belvidere Old Town NRHP District

Contributing:

Non-Contributing:

- Events (NR-A)
- Persons (NR-B)
- Architecture (NR-C)
- Archaeology (NR-D)

LOCAL ELIGIBILITY

Individual Eligibility:

District Eligibility:

District Name:

Contributing:

Non-Contributing:

- Events 2
- Persons 3
- Architecture 4, 5, 6, 8
- Archaeology
- Other 1, 7, 9, 10, 11

Property Information

Address: 303 E Lincoln PIN: 05-25-301-007
 Building Names: J C Foote Residence
 Important Dates: 1913 (date of construction)
 Historic Function: Residence
 Current Function: Residence
 Color Code Criteria: Red
 Outbuildings
 Number: 1 Any Significant:
 Architectural Style: Prairie Style
 Property Type: Residential
 Approximate Age: 1910-1919
 Condition: Good/Excellent
 Potential for Integrity?



Photo: 303_E_Lincoln_Ave_SURVEY_Photo.tif

Description

The Prairie Style, single family home is two-and-one-half stories tall with a low, hipped roof and rectangular massing. The foundation is coursed, rock-faced granite and the walls are tan brick with two story, shallow, half-timber and stucco window bays. The brick is corbelled at the deep eaves to simulate dentil moulding. The front façade, facing north, is symmetrical with centered, two story window bays, dormer and corbelled brick chimney. Low pitched hipped roof porches extend from the east and west elevations, completing a balanced assembly. The east façade, asymmetrical in layout, contains the primary entrance. Located below a large roof dormer, the entrance is accessed through an open porch. Squat, tapered, turned Doric columns sit atop a granite knee wall. Originally a porte-cochère, a concrete slab and steps have been poured raise the floor level. The entry door is paneled with simple wood inlay and leaded, beveled glass sidelights. Adjacent to the front entry and porch, an enclosed entry of brick and glass block was added for separate access to the basement. The east elevation porch, fitted with a granite foundation, is enclosed with large 9/1 double hung windows set between the squat Doric columns. The rear elevation, facing south, also has a columned entry porch, hipped...

Structure Information

Structure: Masonry
 Foundation: Stone Concrete Not Visible
 Brick Parged
 Cladding: Clapboard Asphalt
 Siding Stucco
 Shake Stone
 Board-and-Batten Brick
 Aluminum/Vinyl Concrete Block
 Asbestos Metal

Additions

Type: Historic Non-Historic
 Location: Front Rear
 Side Roof

Porch

Type: Enclosed Porte Cochere
 Stoop Wraparound
 Veranda Multi-Story
 Material: Stone Wood
 Brick Concrete
 Significance: Historic Altered
 Location: Front Rear
 Side Balcony

Doors

Leaf: One-Leaf
 Material: Wood
 Significance: Historic Replacement
 Arrangement: Sidelights Transom
 Type: Paneled
 Paneled w/Lights
 Glazed

Windows

Type: Double-Hung Sliding
 Casement Fixed
 Material: Steel Wood
 Vinyl Aluminum
 Significance: Original Windows
 Original Storms
 Replaced Windows
 Replaced Storms

Roof

Type: Gable Mansard
 Hipped Shed
 Jerkinhead Flat
 Gambrel
 Material: Asphalt
 Metal Slate
 Shake Clay Tile
 Dormers: Gable
 Hipped
 Shed
 Jerkin

Chimney

Material: Brick Concrete Block Stone

NR ELIGIBILITY

Individual Eligibility:

District Eligibility:

District Name:

Belvidere Old Town NRHP District

Contributing:

Non-Contributing:

- Events (NR-A)
- Persons (NR-B)
- Architecture (NR-C)
- Archaeology (NR-D)

LOCAL ELIGIBILITY

Individual Eligibility:

District Eligibility:

District Name:

Belvidere East Lincoln Local Historic District

Contributing:

Non-Contributing:

- Events 2
- Persons 3
- Architecture 4, 5, 6, 8
- Archaeology
- Other 1, 7, 9, 10, 11

Property Information

Address: 319 E Lincoln PIN: 05-25-301-008
 Building Names:
 Important Dates: 1954 Date of Construction
 Historic Function: Residence
 Current Function: Residence
 Color Code Criteria: Orange
 Outbuildings
 Number: 0 Any Significant:
 Architectural Style: Mid-Century
 Property Type: Residential
 Approximate Age: 1930-1939
 Condition: Good/Excellent
 Potential for Integrity?



Photo: 319_E_Lincoln_Ave_SURVEY_Photo.tif

Structure Information

Structure: Masonry
 Foundation: Stone Concrete Not Visible
 Brick Parged
 Cladding: Clapboard Asphalt
 Siding Stucco
 Shake Stone
 Board-and-Batten Brick
 Aluminum/Vinyl Concrete Block
 Asbestos Metal

Additions

Type: Historic Non-Historic
 Location: Front Rear
 Side Roof

Porch

Type: Enclosed Porte Cochere
 Stoop Wraparound
 Veranda Multi-Story
 Material: Stone Wood
 Brick Concrete
 Significance: Historic Altered
 Location: Front Rear
 Side Balcony

Doors

Leaf: One-Leaf
 Material: Wood
 Significance: Historic Replacement
 Arrangement: Sidelights Transom
 Type: Paneled Paneled w/Lights
 Glazed

Windows

Type: Double-Hung Sliding
 Casement Fixed
 Material: Steel Wood
 Vinyl Aluminum
 Significance: Original Windows
 Original Storms
 Replaced Windows
 Replaced Storms

Roof

Type: Gable Mansard
 Hipped Shed
 Jerkinhead Flat
 Gambrel
 Material: Asphalt Metal
 Slate Shake
 Clay Tile
 Dormers: Gable
 Hipped
 Shed
 Jerkin

Chimney

Material: Brick Concrete Block Stone

Description

This Minimal Traditional single family home is two stories tall with rectangular plan, side gabled roof and a one-car garage attached with a breezeway. Set on a concrete foundation, the walls are a yellow brick veneer and a broad brick chimney is located at the west gable end wall. The primary massing is three window bays wide by two bays deep with a small one story entrance at the southeast corner. The main entrance is on center off a concrete porch stoop that spans 2/3 of the front façade. The porch shed roof porch is supported by plain square posts and extends past the main massing to form a gable roof breezeway which merges into the garage roof. The original single leaf slab entrance door has one lite while the storm door features has multiple lites and cross-buck paneling below. Adjacent to the door is a small 2/2 window. Large 2/2 double hung windows wrap around the living area at the northwest corner, while smaller 2/2 windows appear at the second floor sleeping areas. The original 2/2 double-hung windows remain and have stone sills and faux shutters. Across the breezeway, the small one car garage is also built of brick and has a paneled garage door with lites. At the breezeway/garage roof there is a small cupola roof...

NR ELIGIBILITY

Individual Eligibility
 District Eligibility:
 District Name:
 Belvidere Old Town NRHP District
 Contributing:
 Non-Contributing:
 Events (NR-A)
 Persons (NR-B)
 Architecture (NR-C)
 Archaeology (NR-D)

LOCAL ELIGIBILITY

Individual Eligibility:
 District Eligibility:
 District Name:
 Belvidere East Lincoln Local Historic District
 Contributing:
 Non-Contributing:
 Events 2
 Persons 3
 Architecture 4, 5, 6, 8
 Archaeology
 Other 1, 7, 9, 10, 11

Property Information

Address: 401 E Lincoln PIN: 05-25-301-002
 Building Names: Old Dunton Home
 Important Dates:
 Historic Function: Residence
 Current Function: Residence
 Color Code Criteria: Red
 Outbuildings
 Number: 1 Any Significant:
 Architectural Style: Italianate
 Property Type: Residential
 Approximate Age: 1860-1869
 Condition: Good/Excellent
 Potential for Integrity?



Photo: 401_E_Lincoln_Ave_SURVEY_Photo.tif

Description

The Italianate, single family brick home is two stories with a low hipped roof, cupola, and tall, rectangular massing. The first floor is raised on a parged masonry foundation and the brick, laid in a running bond, has been painted. The cornice board is wide with single and paired brackets. A rear two story, gabled roof, brick kitchen wing extends to the south, and a two story enclosed side porch addition extends off the west elevation. The front façade, facing north, is three window bays wide with a one story entry porch to one side. This layout, including the kitchen wing, suggests an extended side hall floor plan. The main entrance is located under an unoriginal, flat roofed porch with simple trim, simple metal scroll-work supports and railings, and a concrete stoop. The stoop continues across the entire façade, forming a shallow veranda. The pair of entrance doors are paneled with lites and an overhead transom. Two tall first floor window openings extend to the veranda with French door and transoms. Historic photographs show a full width porch that wrapped around the west elevation. The original porch was bracketed with square chamfered posts, a short mansard, flat roof and a deck supported on square brick footings. The main roof is topped with a rectangular, hipped roof, cupola two...

Structure Information

Structure: Masonry
 Foundation: Stone Concrete Not Visible
 Brick Parged
 Cladding: Clapboard Asphalt
 Siding Stucco
 Shake Stone
 Board-and-Batten Brick
 Aluminum/Vinyl Concrete Block
 Asbestos Metal

Additions

Type: Historic Non-Historic
 Location: Front Rear
 Side Roof

Porch

Type: Enclosed Porte Cochere
 Stoop Wraparound
 Veranda Multi-Story
 Material: Stone Wood
 Brick Concrete
 Significance: Historic Altered
 Location: Front Rear
 Side Balcony

Doors

Leaf: Two-Leaf
 Material: Wood
 Significance: Historic Replacement
 Arrangement: Sidelights Transom
 Type: Paneled Paneled w/Lights
 Glazed

Windows

Type: Double-Hung Sliding
 Casement Fixed
 Material: Steel Wood
 Vinyl Aluminum
 Significance: Original Windows
 Original Storms
 Replaced Windows
 Replaced Storms

Roof

Type: Gable Hipped
 Jerkinhead Gambrel
 Mansard Shed Flat
 Material: Asphalt Metal
 Slate Shake Clay Tile
 Dormers: Gable Hipped
 Shed Jerkin

Chimney

Material: Brick Concrete Block Stone

NR ELIGIBILITY

Individual Eligibility

District Eligibility:

District Name:

Belvidere Old Town NRHP District

Contributing:

Non-Contributing:

- Events (NR-A)
- Persons (NR-B)
- Architecture (NR-C)
- Archaeology (NR-D)

LOCAL ELIGIBILITY

Individual Eligibility:

District Eligibility:

District Name:

Belvidere East Lincoln Local Historic District

Contributing:

Non-Contributing:

- Events 2
- Persons 3
- Architecture 4, 5, 6, 8
- Archaeology
- Other 1, 7, 9, 10, 11

Property Information

Address: 405 E Lincoln PIN: 05-25-301-003
 Building Names: Benjamin S. Herbert Residence
 Important Dates: 1895 (construction date)
 Historic Function: Residence
 Current Function: Residence
 Color Code Criteria: Red
 Outbuildings
 Number: 3 Any Significant:
 Architectural Style: Queen Anne
 Property Type: Residential
 Approximate Age: 1890-1899
 Condition: Excellent
 Potential for Integrity?



Photo: 405_E_Lincoln_Ave_SURVEY_Photo.tif

Description

The Queen Anne, single family frame house is two-and-one-half stories with a steeply pitched hipped roof with lower cross gables, giving each façade an asymmetrical appearance. The first floor is raised on a coursed, rock-faced limestone foundation, the exterior is clad in wood clapboard and the chimney stack is centrally located. At the primary elevation, facing north, a dominant gable-front section extends slightly forward from the hipped-roof section and a smaller gable at the northwest corner. The first and second floor windows are centered below the third level's closed gable ends, which are decorated with shaped shingles and Palladian inspired windows. Wrapping around the front and west, a one story, gabled and turreted roof porch is supported by slender turned columns. The porch is decorated with lacy, flat, jig-saw cut porch balusters, simple lattice and lacy appliqué in the gabled pediments. The single-leaf 1-lite paneled entrance door is set with a decorative, spindled screen door. At the west façade, the gabled bay is canted, with decorative brackets to support the overhanging corners. The single, tall, double-hung 1/1 windows have rectangular sash with simple wood framing. At the primary elevations, there are several picture windows with leaded glass transoms. Small rectangular 1-lite...

Structure Information

Structure: Frame
 Foundation: Stone Concrete Not Visible
 Brick Parged
 Cladding: Clapboard Asphalt
 Siding Stucco
 Shake Stone
 Board-and-Batten Brick
 Aluminum/Vinyl Concrete Block
 Asbestos Metal

Additions

Type: Historic Non-Historic
 Location: Front Rear
 Side Roof

Porch

Type: Enclosed Stoop Veranda
 Porte Cochere Wraparound Multi-Story
 Material: Stone Wood
 Brick Concrete

Significance: Historic Altered
 Location: Front Rear
 Side Balcony

Doors

Leaf: One-Leaf
 Material: Wood
 Significance: Historic Replacement
 Arrangement: Sidelights Transom
 Type: Paneled Paneled w/Lights
 Glazed

Windows

Type: Double-Hung Sliding Casement Fixed
 Material: Steel Wood Vinyl Aluminum
 Significance: Original Windows Original Storms Replaced Windows Replaced Storms

Roof

Type: Gable Hipped Jerkinhead Gambrel
 Mansard Shed Flat
 Material: Asphalt Metal Slate Shake Clay Tile
 Dormers: Gable Hipped Shed Jerkin

Chimney

Material: Brick Concrete Block Stone

NR ELIGIBILITY

Individual Eligibility:
 District Eligibility:
 District Name:
 Belvidere Old Town NRHP District
 Contributing:
 Non-Contributing:
 Events (NR-A)
 Persons (NR-B)
 Architecture (NR-C)
 Archaeology (NR-D)

LOCAL ELIGIBILITY

Individual Eligibility:
 District Eligibility:
 District Name:
 Belvidere East Lincoln Local Historic District
 Contributing:
 Non-Contributing:
 Events 2
 Persons 3
 Architecture 4, 5, 6, 8
 Archaeology
 Other 1, 7, 9, 10, 11

Property Information

Address: 406 E Lincoln PIN: 05-25-159-007
 Building Names:
 Important Dates: 1881 (construction date)
 Historic Function: Residence
 Current Function: Residence
 Color Code Criteria: Red
 Outbuildings
 Number: 1 Any Significant:
 Architectural Style: Queen Anne
 Property Type: Residential
 Approximate Age: 1880-1889
 Condition: Excellent
 Potential for Integrity?



Photo: 406_E_Lincoln_Ave_SURVEY_Photo.tif

Structure Information

Structure: Masonry
 Foundation: Stone Concrete Not Visible
 Brick Parged
 Cladding: Clapboard Asphalt
 Siding Stucco
 Shake Stone
 Board-and-Batten Brick
 Aluminum/Vinyl Concrete Block
 Asbestos Metal

Additions

Type: Location:
 Historic Front Rear
 Non-Historic Side Roof

Porch

Type: Material:
 Enclosed Porte Cochere Stone Wood
 Stoop Wraparound Brick Concrete
 Veranda Multi-Story
 Significance: Location:
 Historic Altered Front Rear
 Side Balcony

Doors

Leaf: Two-Leaf
 Material: Wood
 Significance: Arrangement: Type:
 Historic Sidelights Paneled w/Lights
 Replacement Transom Glazed

Windows

Type: Material: Significance:
 Double-Hung Steel Original Windows
 Sliding Wood Original Storms
 Casement Vinyl Replaced Windows
 Fixed Aluminum Replaced Storms

Roof

Type: Material: Dormers:
 Gable Mansard Asphalt Gable
 Hipped Shed Metal Hipped
 Jerkinhead Flat Slate Shed
 Gambrel Shake Jerkin
 Clay Tile

Chimney

Material: Brick Concrete Block Stone

Description

The Queen Anne, single family brick house is two-and-one-half stories with a steeply pitched hipped roof and cross-gabled massing with central and gable-end chimney stacks. The first floor is raised on a parged masonry foundation and water table, and the brick is painted. At the primary elevation, facing south, a gable-front section with centered window openings extends one window bay forward from the cross gable section. The cross gable ends extend one window bay beyond at the west and two bays at the east. The main entrance is situated at the south west corner under the hipped roof. Over the door, a bracketed, arched porch roof echoes the segmental curve of the entry transom, which is situated over a pair of paneled entrance doors with tall lites. A modern brick stoop and knee walls finish the front entrance. The west and east elevation gable end windows are also centered. At the first floor on the west, there is a three-sided frame window bay with a masonry foundation, paneled detail, a bracketed cornice and flat, short and sloping mansard roof. Single, tall and narrow double-hung, 1/1 windows have rectangular sash with segmental arch brick headers and stone lug sills. Small rectangular basement windows, now glass block, pierce the foundation and small, 1-lite oculus attic...

NR ELIGIBILITY

Individual Eligibility
 District Eligibility:
 District Name:
 Belvidere Old Town NRHP District
 Contributing:
 Non-Contributing:

- Events (NR-A)
- Persons (NR-B)
- Architecture (NR-C)
- Archaeology (NR-D)

LOCAL ELIGIBILITY

Individual Eligibility:
 District Eligibility:
 District Name:
 Belvidere East Lincoln Local Historic District
 Contributing:
 Non-Contributing:

- Events 2
- Persons 3
- Architecture 4, 5, 6, 8
- Archaeology
- Other 1, 7, 9, 10, 11

Property Information

Address: 410 E Lincoln PIN: 05-25-159-008
 Building Names: Wildflower House/Lampert Home
 Important Dates: 1837 (construction date)
 Historic Function: Residence
 Current Function: Residence
 Color Code Criteria: Red
 Outbuildings
 Number: 4 Any Significant:
 Architectural Style: Greek Revival
 Property Type: Residential
 Approximate Age: 1830-1839
 Condition: Excellent
 Potential for Integrity?



Photo: 410_E_Lincoln_Ave_SURVEY_Photo.tif

Description

The Greek Revival, single family frame house has upright-and-wing massing with a two-and-one-half story front facing gable and a one story side-gabled wing. The house is set on a rubble limestone foundation and is clad in wood clapboarding. Facing south, the upright section is two bays deep with a symmetrical façade of two windows flanking a central entrance. A central chimney is located at the rear gable end wall. The cornice, discontinuous across the gable ends, is wide with several bands of trim. The paneled front door is located under a small, hipped roof porch with a wide cornice band, large square, paneled columns, and simple railings and window seats.

Such a small porch is typical for Midwest examples of this style. However, the current porch dates to ca. 1870s. Square, chamfered posts and pilasters support a bracketed, low, hipped roof embellished with spear-shaped dentils. A simple railing terminates in ball-topped newel posts. The entrance door is paneled, with wide, simple wood trim at the door surround. On the rear elevation there is a full-width one story wing with a concrete foundation and a partial two story addition. ...

Structure Information

Structure: Frame
 Foundation: Stone Concrete Not Visible
 Brick Parged
 Cladding: Clapboard Asphalt
 Siding Stucco
 Shake Stone
 Board-and-Batten Brick
 Aluminum/Vinyl Concrete Block
 Asbestos Metal

Additions

Type: Location:
 Historic Front Rear
 Non-Historic Side Roof

Porch

Type: Material:
 Enclosed Porte Cochere Stone Wood
 Stoop Wraparound Brick Concrete
 Veranda Multi-Story

Significance: Location:
 Historic Altered Front Rear
 Side Balcony

Doors

Leaf: One-Leaf
 Material: Wood Type:
 Significance: Arrangement: Paneled
 Historic Sidelights Paneled w/Lights
 Replacement Transom Glazed

Windows

Type: Material: Significance:
 Double-Hung Steel Original Windows
 Sliding Wood Original Storms
 Casement Vinyl Replaced Windows
 Fixed Aluminum Replaced Storms

Roof

Type: Material: Dormers:
 Gable Mansard Asphalt Gable
 Hipped Shed Metal Hipped
 Jerkinhead Flat Slate Shed
 Gambrel Shake Jerkin
 Clay Tile

Chimney

Material: Brick Concrete Block Stone

NR ELIGIBILITY

Individual Eligibility

District Eligibility:

District Name:

Belvidere Old Town NRHP District

Contributing:

Non-Contributing:

- Events (NR-A)
- Persons (NR-B)
- Architecture (NR-C)
- Archaeology (NR-D)

LOCAL ELIGIBILITY

Individual Eligibility:

District Eligibility:

District Name:

Belvidere East Lincoln Local Historic District

Contributing:

Non-Contributing:

- Events 2
- Persons 3
- Architecture 4, 5, 6, 8
- Archaeology
- Other 1, 7, 9, 10, 11

Property Information

Address: 415 E Lincoln PIN: 05-25-301-004
 Building Names:
 Important Dates:
 Historic Function: Residence
 Current Function: Residence
 Color Code Criteria: None
 Outbuildings
 Number: 1 Any Significant:
 Architectural Style: Queen Anne
 Property Type: Residential
 Approximate Age: 1890-1899
 Condition: Good
 Potential for Integrity?



Photo: 415_E_Lincoln_Ave_SURVEY_Photo.tif

Description

The Queen Anne, single family frame house is two-and-one-half stories with a steeply pitched hipped and cross-gabled massing. The first floor is raised on a foundation of coursed limestone, the exterior is clad in siding and partial stone veneer, and the brick chimney is centrally located on the roof. The primary elevation, facing north, is asymmetrical with an open front gable. The cross gables face east and west with a gabled rear wing to the south. At the north elevation, a one story porch has a mansard and flat roof support by large fluted columns set at grade. A small concrete stoop and steps are located under the porch. Here the main entrance has been remodeled to a colonial revival assembly with sidelites and a broken scroll pediment. The mansard porch roof wraps around the west elevation and merges with a one story hipped roof addition and continues around the south elevation. The addition has a side entrance at grade with a short mansard and flat porch roof supported by square stone veneered columns. At the main body of the house, many of the original windows remain. Under the west gable a centered rectangular window bay is partially visible. Single and paired windows are centered under the open...

Structure Information

Structure: Frame
 Foundation: Stone Concrete Not Visible
 Brick Parged
 Cladding: Clapboard Asphalt
 Siding Stucco
 Shake Stone
 Board-and-Batten Brick
 Aluminum/Vinyl Concrete Block
 Asbestos Metal

Additions

Type: Historic Non-Historic
 Location: Front Rear
 Side Roof

Porch

Type: Enclosed Porte Cochere Stoop Wraparound Veranda Multi-Story
 Material: Stone Wood Brick Concrete

Significance: Historic Altered
 Location: Front Rear
 Side Balcony

Doors

Leaf: One-Leaf
 Material: Wood
 Significance: Historic Replacement
 Arrangement: Sidelights Transom
 Type: Paneled Paneled w/Lights Glazed

Windows

Type: Double-Hung Sliding Casement Fixed
 Material: Steel Wood Vinyl Aluminum
 Significance: Original Windows Original Storms Replaced Windows Replaced Storms

Roof

Type: Gable Hipped Jerkinhead Gambrel
 Mansard Shed Flat
 Material: Asphalt Metal Slate Shake Clay Tile
 Dormers: Gable Hipped Shed Jerkin

Chimney

Material: Brick Concrete Block Stone

NR ELIGIBILITY

Individual Eligibility

District Eligibility:

District Name:

Belvidere Old Town NRHP District

Contributing:

Non-Contributing:

- Events (NR-A)
- Persons (NR-B)
- Architecture (NR-C)
- Archaeology (NR-D)

LOCAL ELIGIBILITY

Individual Eligibility:

District Eligibility:

District Name:

Belvidere East Lincoln Local Historic District

Contributing:

Non-Contributing:

- Events 2
- Persons 3
- Architecture 4, 5, 6, 8
- Archaeology
- Other 1, 7, 9, 10, 11

Property Information

Address: 416 E Lincoln PIN: 05-25-159-009
 Building Names: E. Hopkins Residence
 Important Dates:
 Historic Function: Residence
 Current Function: Residence
 Color Code Criteria: Yellow
 Outbuildings
 Number: 0 Any Significant:
 Architectural Style: Queen Anne
 Property Type: Residential
 Approximate Age: 1890-1899
 Condition: Good/Excellent
 Potential for Integrity?



Photo: 416_E_Lincoln_Ave_SURVEY_Photo.tif

Description

The Queen Anne, single family frame house is two-and-one-half stories with a steeply pitched roof and cross-gabled massing. The first floor is raised on a foundation of dressed, rusticated limestone and the exterior is clad in siding. At the primary elevation, facing south, a gable-front section with centered window openings extends forward from the hipped roof section, where the main entry is placed at the southeast corner. The altered main entrance is situated on a concrete rock-faced block base under a small gabled porch roof supported by cast metal lattice posts. The single-leaf entrance door has been replaced, and directly adjacent is a canted first floor window bay. The south elevation gable end windows are centered with a cantilevered window bay at the first floor. The bays are bracketed with a shingled spandrel, scrollwork appliqué, a bracketed cornice and a short mansard roof. The front windows have decorative glass transoms over picture windows with a one-lite attic sash high in the gable end. The east and west gables have symmetrical window placement and the west gable's first floor is canted with a repeat of the south elevation's bay and large window layout. A small one-story enclosed side porch with...

Structure Information

Structure: Frame
 Foundation: Stone Concrete Not Visible
 Brick Parged
 Cladding: Clapboard Asphalt
 Siding Stucco
 Shake Stone
 Board-and-Batten Brick
 Aluminum/Vinyl Concrete Block
 Asbestos Metal

Additions

Type: Historic Front Rear
 Non-Historic Side Roof

Porch

Type: Enclosed Porte Cochere Stone Wood
 Stoop Wraparound Brick Concrete
 Veranda Multi-Story

Significance: Historic Altered Location: Front Rear
 Side Balcony

Doors

Leaf: One-Leaf
 Material: Metal Type: Paneled
 Significance: Historic Sidelights Paneled w/Lights
 Replacement Transom Glazed

Windows

Type: Double-Hung Steel Significance: Original Windows
 Sliding Wood Original Storms
 Casement Vinyl Replaced Windows
 Fixed Aluminum Replaced Storms

Roof

Type: Gable Mansard Material: Asphalt Dormers: Gable
 Hipped Shed Metal Hipped
 Jerkinhead Flat Slate Shed
 Gambrel Shake Jerkin
 Clay Tile

Chimney

Material: Brick Concrete Block Stone

NR ELIGIBILITY

Individual Eligibility
 District Eligibility:

District Name:

Belvidere Old Town NRHP District

Contributing:
 Non-Contributing:

- Events (NR-A)
- Persons (NR-B)
- Architecture (NR-C)
- Archaeology (NR-D)

LOCAL ELIGIBILITY

Individual Eligibility:
 District Eligibility:

District Name:

Belvidere East Lincoln Local Historic District

Contributing:
 Non-Contributing:

- Events 2
- Persons 3
- Architecture 4, 5, 6, 8
- Archaeology
- Other 1, 7, 9, 10, 11

Property Information

Address: 421 E Lincoln PIN: 05-25-301-005
 Building Names:
 Important Dates:
 Historic Function: Residence
 Current Function: Residence
 Color Code Criteria: None
 Outbuildings
 Number: 0 Any Significant:
 Architectural Style: None
 Property Type: Residential
 Approximate Age: 1930-1939
 Condition: Heavily Altered
 Potential for Integrity?



Photo: 421_E_Lincoln_Ave_SURVEY_Photo.tif

Structure Information

Structure: Frame
 Foundation: Stone Concrete Not Visible
 Brick Parged
 Cladding: Clapboard Asphalt
 Siding Stucco
 Shake Stone
 Board-and-Batten Brick
 Aluminum/Vinyl Concrete Block
 Asbestos Metal

Additions

Type: Location:
 Historic Front Rear
 Non-Historic Side Roof

Porch

Type: Material:
 Enclosed Porte Cochere Stone Wood
 Stoop Wraparound Brick Concrete
 Veranda Multi-Story
 Significance: Location:
 Historic Altered Front Rear
 Side Balcony

Doors

Leaf: One-Leaf
 Material: Type:
 Significance: Arrangement:
 Historic Sidelights Paneled
 Replacement Transom Paneled w/Lights
 Glazed

Windows

Type: Material: Significance:
 Double-Hung Steel Original Windows
 Sliding Wood Original Storms
 Casement Vinyl Replaced Windows
 Fixed Aluminum Replaced Storms

Roof

Type: Material: Dormers:
 Gable Mansard Asphalt Gable
 Hipped Shed Metal Hipped
 Jerkinhead Flat Slate Shed
 Gambrel Shake Jerkin
 Clay Tile

Chimney

Material: Brick Concrete Block Stone

Description

The single family frame house is two stories with a steeply pitched roof and front gabled massing. The first floor is raised on a concrete foundation, the exterior is clad in siding, and a broad brick chimney is located towards the south elevation. At the primary elevation, facing north, the first floor has a wide, centered window bay with double-hung windows and a hipped roof. Above, two double-hung windows with faux shutters are placed off center. The main entry is placed to the side on the east elevation where a wood deck and hipped roof is supported by a turned colonnette. The single-leaf entry door has been replaced. Opposite on the west elevation, a smaller wood deck is located at a side entrance. Typical windows have been replaced with single 1/1 double-hungs with rectangular sash and faux shutters. Small rectangular 3-lite basement windows pierce the foundation. The home's 1930s construction date, orientation and arrangement of features appear to place it in the Colonial Revival style. However, extensive remodeling has removed a majority of the home's original fabric and decorative elements, compromising its integrity.

NR ELIGIBILITY

Individual Eligibility
 District Eligibility:
 District Name:
 Belvidere Old Town NRHP District
 Contributing:
 Non-Contributing:
 Events (NR-A)
 Persons (NR-B)
 Architecture (NR-C)
 Archaeology (NR-D)

LOCAL ELIGIBILITY

Individual Eligibility:
 District Eligibility:
 District Name:
 Belvidere East Lincoln Local Historic District
 Contributing:
 Non-Contributing:
 Events 2
 Persons 3
 Architecture 4, 5, 6, 8
 Archaeology
 Other 1, 7, 9, 10, 11

Property Information

Address: 426 E Lincoln PIN: 05-25-159-010
 Building Names:
 Important Dates:
 Historic Function: Residence
 Current Function: Residence
 Color Code Criteria: Orange
 Outbuildings
 Number: 1 Any Significant:
 Architectural Style: Queen Anne
 Property Type: Residential
 Approximate Age: 1870-1879
 Condition: Good
 Potential for Integrity?



Photo: 426_E_Lincoln_Ave_SURVEY_Photo.tif

Description

The Victorian, single family frame house is two-and-one-half stories with a steeply pitched front gabled roof and a one-and-one-half story side gabled wing. The first floor is raised on a parged masonry foundation and the exterior is clad in asbestos siding. At the primary elevation, facing south, the gable-front section has centered window openings. A rectangular bay at the first floor has a short mansard roof accented with paired and single brackets, and a pair of windows is located above at the second floor. The main entry is placed at a concrete stoop in the southeast corner of the wing with two original floor-to-ceiling 2/2 double-hung windows adjacent. The single-leaf door is replaced, with a gabled canopy supported with simple braces. The wing's west elevation gable end window are original 2/2 double-hungs, evenly spaced with pedimented wood frames. The east elevation window placement is irregular with original 2/2 and 1/1 windows. Small rectangular basement windows pierce the foundation and are located high in the attic gable. Many of the original windows remain, though their framing details vary and replacement storm windows have been installed. At the rear elevation, a small...

Structure Information

Structure: Frame
 Foundation: Stone Concrete Not Visible
 Brick Parged
 Cladding: Clapboard Asphalt
 Siding Stucco
 Shake Stone
 Board-and-Batten Brick
 Aluminum/Vinyl Concrete Block
 Asbestos Metal

Additions

Type: Location:
 Historic Front Rear
 Non-Historic Side Roof

Porch

Type: Material:
 Enclosed Porte Cochere Stone Wood
 Stoop Wraparound Brick Concrete
 Veranda Multi-Story

Significance: Location:
 Historic Altered Front Rear
 Side Balcony

Doors

Leaf: One-Leaf
 Material: Wood Type:
 Significance: Arrangement:
 Historic Sidelights Paneled w/Lights
 Replacement Transom Glazed

Windows

Type: Material: Significance:
 Double-Hung Steel Original Windows
 Sliding Wood Original Storms
 Casement Vinyl Replaced Windows
 Fixed Aluminum Replaced Storms

Roof

Type: Material: Dormers:
 Gable Mansard Asphalt Gable
 Hipped Shed Metal Hipped
 Jerkinhead Flat Slate Shed
 Gambrel Shake Jerkin
 Clay Tile

Chimney

Material: Brick Concrete Block Stone

NR ELIGIBILITY

Individual Eligibility
 District Eligibility:

District Name:

Belvidere Old Town NRHP District

Contributing:

Non-Contributing:

- Events (NR-A)
- Persons (NR-B)
- Architecture (NR-C)
- Archaeology (NR-D)

LOCAL ELIGIBILITY

Individual Eligibility:
 District Eligibility:

District Name:

Belvidere East Lincoln Local Historic District

Contributing:

Non-Contributing:

- Events 2
- Persons 3
- Architecture 4, 5, 6, 8
- Archaeology
- Other 1, 7, 9, 10, 11

Property Information

Address: 505 E Lincoln PIN: 05-25-301-006
 Building Names:
 Important Dates:
 Historic Function: Residence
 Current Function: Residence
 Color Code Criteria: Orange
 Outbuildings
 Number: 0 Any Significant:
 Architectural Style: Mid-Century
 Property Type: Residential
 Approximate Age: 1950-1959
 Condition: Good/Excellent
 Potential for Integrity?



Photo: 505_E_Lincoln_Ave_SURVEY_Photo.tif

Structure Information

Structure: Frame/Masonry
 Foundation: Stone Concrete Not Visible
 Brick Parged
 Cladding: Clapboard Asphalt
 Siding Stucco
 Shake Stone
 Board-and-Batten Brick
 Aluminum/Vinyl Concrete Block
 Asbestos Metal

Description

The sprawling Ranch style single family home is one story with an "L" shaped plan, gabled roof and boxed eaves. Set on a concrete foundation, the walls are clad in siding and painted brick veneer. A brick chimney is centralized in the at the gable junction. The front façade is asymmetrical with a broad brick front gable and long side gabled wing. Two 8/12 double-hung windows are evenly spaced on the front gable. Spanning the entire length of the side wing is a recessed porch with a shed roof extension supported by square posts and stylized brackets with a simple balustrade. The main entrance, located at the inside corner, has a single-leaf door and one sidelite. Adjacent to the front door is a wide, shallow window bay with tall, narrow, multi-lite casements. An secondary entrance door, located further down the wing, has a multi-lite top with cross-buck paneling below. Other windows are short multi-lite casements or 6/6 double-hung windows with faux shutters. At the southwest corner of the property there is a front gabled one car garage clad in siding. The massing and plain details have been largely maintained, giving this modest Ranch home excellent integrity.

Additions

Type: Location:
 Historic Front Rear
 Non-Historic Side Roof

Porch

Type: Material:
 Enclosed Porte Cochere Stone Wood
 Stoop Wraparound Brick Concrete
 Veranda Multi-Story

Significance: Location:
 Historic Altered Front Rear
 Side Balcony

Doors

Leaf: One-Leaf
 Material: Metal Type:
 Significance: Arrangement: Paneled
 Historic Sidelights Paneled w/Lights
 Replacement Transom Glazed

Windows

Type: Material: Significance:
 Double-Hung Steel Original Windows
 Sliding Wood Original Storms
 Casement Vinyl Replaced Windows
 Fixed Aluminum Replaced Storms

Roof

Type: Material: Dormers:
 Gable Mansard Asphalt Gable
 Hipped Shed Metal Hipped
 Jerkinhead Flat Slate Shed
 Gambrel Shake Jerkin
 Clay Tile

Chimney

Material: Brick Concrete Block Stone

NR ELIGIBILITY

Individual Eligibility

District Eligibility:

District Name:

Belvidere Old Town NRHP District

Contributing:

Non-Contributing:

- Events (NR-A)
- Persons (NR-B)
- Architecture (NR-C)
- Archaeology (NR-D)

LOCAL ELIGIBILITY

Individual Eligibility:

District Eligibility:

District Name:

Belvidere East Lincoln Local Historic District

Contributing:

Non-Contributing:

- Events 2
- Persons 3
- Architecture 4, 5, 6, 8
- Archaeology
- Other 1, 7, 9, 10, 11

Property Information

Address: 509 E Lincoln PIN: 05-25-160-001
 Building Names:
 Important Dates:
 Historic Function: Residence
 Current Function: Residence
 Color Code Criteria: Orange
 Outbuildings
 Number: 1 Any Significant:
 Architectural Style: Cape Cod
 Property Type: Residential
 Approximate Age: 1950-1959
 Condition: Good/Excellent
 Potential for Integrity?



Photo: 509_E_Lincoln_Ave_SURVEY_Photo.tif

Structure Information

Structure: Frame
 Foundation: Stone Concrete Not Visible
 Brick Parged
 Cladding: Clapboard Asphalt
 Siding Stucco
 Shake Stone
 Board-and-Batten Brick
 Aluminum/Vinyl Concrete Block
 Asbestos Metal

Additions

Type: Location:
 Historic Front Rear
 Non-Historic Side Roof

Porch

Type: Material:
 Enclosed Porte Cochere Stone Wood
 Stoop Wraparound Brick Concrete
 Veranda Multi-Story

Significance: Location:
 Historic Altered Front Rear
 Side Balcony

Doors

Leaf: One-Leaf
 Material: Wood
 Significance: Arrangement: Type:
 Historic Sidelights Paneled w/Lights
 Replacement Transom Glazed

Windows

Type: Material: Significance:
 Double-Hung Steel Original Windows
 Sliding Wood Original Storms
 Casement Vinyl Replaced Windows
 Fixed Aluminum Replaced Storms

Roof

Type: Material: Dormers:
 Gable Mansard Asphalt Gable
 Hipped Shed Metal Hipped
 Jerkinhead Flat Slate Shed
 Gambrel Shake Jerkin
 Clay Tile

Chimney

Material: Brick Concrete Block Stone

Description

This charming, mid-century Colonial Revival cottage is one-and-one-half stories with a "T" shaped plan and steeply pitched gabled roof massing. Set on a concrete block foundation, the walls are clad in siding and the roof is covered in wood shingles. A brick chimney is centralized in the at the gable junction. The front section is composed of a one story side gabled section with an evenly spaced four bay window and door layout on the front facade. The 6/6 double-hung windows are original with shaped wood frames and shutters. The front door assembly is located at a concrete stoop with simple X-braced iron railings. The single-leaf door is paneled with 4 lites and a half-round fan light above. The assembly is accented with fluted pilasters and framing, and a keystone. At the east and west gable ends are identical window bays with low hipped roofs and tall, narrow multi-lite casement windows. Situated behind and perpendicular to the front section is a larger one-and-one-half story gabled section. The height difference forms a small front facing gable. At the broad gable roof, there are single and double shed roof dormers. The other windows along this section are irregularly spaced. At the rear elevation, facing...

NR ELIGIBILITY

Individual Eligibility
 District Eligibility:

District Name:
 Belvidere Old Town NRHP District

Contributing:
 Non-Contributing:

Events (NR-A)
 Persons (NR-B)
 Architecture (NR-C)
 Archaeology (NR-D)

LOCAL ELIGIBILITY

Individual Eligibility:
 District Eligibility:

District Name:
 Belvidere East Lincoln Local Historic District

Contributing:
 Non-Contributing:

Events 2
 Persons 3
 Architecture 4, 5, 6, 8
 Archaeology
 Other 1, 7, 9, 10, 11

Property Information

Address: 519 E Lincoln PIN: 05-25-160-002
 Building Names: Olney Residence
 Important Dates:
 Historic Function: Residence
 Current Function: Residence
 Color Code Criteria: Orange
 Outbuildings
 Number: 1 Any Significant:
 Architectural Style: None
 Property Type: Residential
 Approximate Age: 1900-1909
 Condition: Good/Excellent
 Potential for Integrity?



Photo: 519_E_Lincoln_Ave_SURVEY_Photo.tif

Description

The single-family brick home is two stories with a tall, steeply pitched hipped roof, and rectangular massing. The original hipped roof Italianate structure is located on the west section, and had a plan approximately 3 bays wide by two bays deep. This was added onto at the east elevation, altering the footprint and roof. At the original section, the first floor is raised on a parged masonry foundation and the brick, laid in a running bond, has been painted. Original window openings on the west elevation have painted stone sills and smooth stone lintels. No original windows survive. At the front elevation, facing north, two tall windows at the first floor and three above appear to have original locations, but have been altered. The large, two story brick addition to the east added two additional bays and projects out from the original section. The roof was enlarged to unite the two sections and its tall, oversized chateausque style gives the home a grandiose, albeit mismatched, appearance. Between the two sections, a one story brick porch was added at the entrance. The original entrance door location was built-out to align with the new addition. The current door is a single-leaf with sidelights. The porch's flat roof is supported by...

Structure Information

Structure: Masonry
 Foundation: Stone Concrete Not Visible
 Brick Parged
 Cladding: Clapboard Asphalt
 Siding Stucco
 Shake Stone
 Board-and-Batten Brick
 Aluminum/Vinyl Concrete Block
 Asbestos Metal

Additions

Type: Historic Non-Historic
 Location: Front Rear
 Side Roof

Porch

Type: Enclosed Porte Cochere
 Stoop Wraparound
 Veranda Multi-Story
 Material: Stone Wood
 Brick Concrete

Significance: Historic Altered
 Location: Front Rear
 Side Balcony

Doors

Leaf: One-Leaf
 Material: Metal
 Significance: Historic Replacement
 Arrangement: Sidelights Transom
 Type: Paneled
 Paneled w/Lights
 Glazed

Windows

Type: Double-Hung Sliding
 Casement Fixed
 Material: Steel Wood
 Vinyl Aluminum
 Significance: Original Windows
 Original Storms
 Replaced Windows
 Replaced Storms

Roof

Type: Gable Mansard
 Hipped Shed
 Jerkinhead Flat
 Gambrel
 Material: Asphalt
 Metal Slate
 Shake Clay Tile
 Dormers: Gable
 Hipped
 Shed
 Jerkin

Chimney

Material: Brick Concrete Block Stone

NR ELIGIBILITY

Individual Eligibility
 District Eligibility:

District Name:
 Belvidere Old Town NRHP
 District

Contributing:
 Non-Contributing:

- Events (NR-A)
- Persons (NR-B)
- Architecture (NR-C)
- Archaeology (NR-D)

LOCAL ELIGIBILITY

Individual Eligibility:
 District Eligibility:

District Name:
 Belvidere Courthouse Square
 Local Historic District

Contributing:
 Non-Contributing:

- Events 2
- Persons 3
- Architecture 4, 5, 6, 8
- Archaeology
- Other 1, 7, 9, 10, 11

Property Information

Address: 531 E Lincoln PIN: 05-25-160-003
 Building Names:
 Important Dates:
 Historic Function: Residence
 Current Function: Residence
 Color Code Criteria: Yellow
 Outbuildings
 Number: 1 Any Significant:
 Architectural Style: Greek Revival
 Property Type: Residential
 Approximate Age: 1860-1869
 Condition: Good
 Potential for Integrity?



Photo: 531_E_Lincoln_Ave_SURVEY_Photo.tif

Structure Information

Structure: Frame
 Foundation: Stone Concrete Not Visible
 Brick Parged
 Cladding: Clapboard Asphalt
 Siding Stucco
 Shake Stone
 Board-and-Batten Brick
 Aluminum/Vinyl Concrete Block
 Asbestos Metal

Additions

Type: Location:
 Historic Front Rear
 Non-Historic Side Roof

Porch

Type: Material:
 Enclosed Porte Cochere Stone Wood
 Stoop Wraparound Brick Concrete
 Veranda Multi-Story
 Significance: Location:
 Historic Altered Front Rear
 Side Balcony

Doors

Leaf: One-Leaf
 Material: Wood Type:
 Significance: Arrangement:
 Historic Sidelights Paneled w/Lights
 Replacement Transom Glazed

Windows

Type: Material: Significance:
 Double-Hung Steel Original Windows
 Sliding Wood Original Storms
 Casement Vinyl Replaced Windows
 Fixed Aluminum Replaced Storms

Roof

Type: Material: Dormers:
 Gable Mansard Asphalt Gable
 Hipped Shed Metal Hipped
 Jerkinhead Flat Slate Shed
 Gambrel Shake Jerkin
 Clay Tile

Chimney

Material: Brick Concrete Block Stone

Description

The Greek Revival, single family home is two stories with a low front gable roof and rectangular massing. The first floor is raised on a parged masonry foundation, the walls are clad in siding, and the internal brick chimney is located at the front gable end. An original one story rear kitchen wing with gabled roof extends south. At the northeast corner, a one story saltbox addition covers the entire east elevation. The front gabled massing, facing north, is two bays wide by three bays deep and there are remnants of cornice returns. The north elevation's first floor and side addition are clad in vertical boards. The front door is located to one side at a low concrete stoop. Though not original, the one-lite paneled door is Victorian. This layout, including the kitchen wing, suggests an extended side hall floor plan. At the west elevation, a three-sided window bay has replaced an original window opening. The original window openings clad frames and faux shutters, but many of the original 6/6 and later 1/1 double hung windows remain. The size, height and arrangement of features suggest that this was a middle-class settlement dwelling. However, many alterations have compromised the building's integrity.

NR ELIGIBILITY

Individual Eligibility
 District Eligibility:
 District Name:
 Belvidere Old Town NRHP District
 Contributing:
 Non-Contributing:
 Events (NR-A)
 Persons (NR-B)
 Architecture (NR-C)
 Archaeology (NR-D)

LOCAL ELIGIBILITY

Individual Eligibility:
 District Eligibility:
 District Name:
 Belvidere East Lincoln Local Historic District
 Contributing:
 Non-Contributing:
 Events 2
 Persons 3
 Architecture 4, 5, 6, 8
 Archaeology
 Other 1, 7, 9, 10, 11

Property Information

Address: 601 E Lincoln PIN: 05-25-160-004
 Building Names:
 Important Dates:
 Historic Function: Residence
 Current Function: Residence
 Color Code Criteria: Blue
 Outbuildings
 Number: 1 Any Significant:
 Architectural Style: Modern
 Property Type: Residential
 Approximate Age: 1970-1979
 Condition: Good/Excellent
 Potential for Integrity?



Photo: 601_E_Lincoln_Ave_SURVEY_Photo.tif

Description

The mid-century Contemporary single family home is one story tall with a walk-out basement level at the rear and an offset square plan. The roof is mostly flat with a prominent one-and-one-half story gabled entry placed on center and deep eaves. The walls are clad in vertical board and batten wood siding with areas of stone veneer. A brick chimney is located at the east end wall. The gabled entry, facing north, has a centered entry under a tall pair of one-lite windows triangular shaped heads that conform to the gable. The original double entry has slab doors with centered door knobs. A side entrance at the west elevation has a flat roof, wood deck, and simple wood railings and post supports. The original windows have simple frames and are either paired one-lite clerestory windows or pairs of one-lite casement windows. Much of the front elevation is obscured by large bushes. At the west edge of the property, a front gabled two car garage is has wood siding and the front façade is clad in stone veneer. This modest dwelling has retained excellent integrity and is a fine example of the mid-century gabled roof Contemporary style.

Structure Information

Structure: Frame/Masonry
 Foundation: Stone Concrete Not Visible
 Brick Parged
 Cladding: Clapboard Asphalt
 Siding Stucco
 Shake Stone
 Board-and-Batten Brick
 Aluminum/Vinyl Concrete Block
 Asbestos Metal

Additions

Type: Location:
 Historic Front Rear
 Non-Historic Side Roof

Porch

Type: Material:
 Enclosed Porte Cochere Stone Wood
 Stoop Wraparound Brick Concrete
 Veranda Multi-Story

Significance: Location:
 Historic Altered Front Rear
 Side Balcony

Doors

Leaf: Two-Leaf
 Material: Wood
 Significance: Arrangement: Type:
 Historic Sidelights Paneled
 Replacement Transom Paneled w/Lights
 Glazed

Windows

Type: Material: Significance:
 Double-Hung Steel Original Windows
 Sliding Wood Original Storms
 Casement Vinyl Replaced Windows
 Fixed Aluminum Replaced Storms

Roof

Type: Material: Dormers:
 Gable Mansard Asphalt Gable
 Hipped Shed Metal Hipped
 Jerkinhead Flat Slate Shed
 Gambrel Shake Jerkin
 Clay Tile

Chimney

Material: Brick Concrete Block Stone

NR ELIGIBILITY

Individual Eligibility
 District Eligibility:
 District Name:
 Belvidere Old Town NRHP

Contributing:
 Non-Contributing:

- Events (NR-A)
- Persons (NR-B)
- Architecture (NR-C)
- Archaeology (NR-D)

LOCAL ELIGIBILITY

Individual Eligibility:
 District Eligibility:
 District Name:

Contributing:
 Non-Contributing:

- Events 2
- Persons 3
- Architecture 4, 5, 6, 8
- Archaeology
- Other 1, 7, 9, 10, 11

Property Information

Address: 613 E Lincoln PIN: 05-25-160-005
 Building Names:
 Important Dates:
 Historic Function: Residence
 Current Function: Residence
 Color Code Criteria: None
 Outbuildings
 Number: 1 Any Significant:
 Architectural Style: Queen Anne
 Property Type: Residential
 Approximate Age: 1870-1879
 Condition: Heavily Altered
 Potential for Integrity?



Photo: 613_E_Lincoln_Ave_SURVEY_Photo.tif

Description

The single family dwelling is two stories with a steeply pitched cross-gabled roof and "T" shaped plan. The walls are clad in replacement siding. The primary façade, facing north, is symmetrical with a prominent front gable and centered window openings. A large wood porch with a hipped roof wraps around the front gable wing and the main entrance is located at the west elevation inside corner. A large, two story wing at the rear elevation has a low pitched gable roof. Window openings are centered under the side gables. All original window openings have been altered, and no original windows remain. Though the building is believed to have been constructed in the 19th century and likely had a Queen Anne style. However, little to no original fabric remains and the home's integrity has been lost.

Structure Information

Structure: Frame
 Foundation: Stone Concrete Not Visible
 Brick Parged
 Cladding: Clapboard Asphalt
 Siding Stucco
 Shake Stone
 Board-and-Batten Brick
 Aluminum/Vinyl Concrete Block
 Asbestos Metal

Additions

Type: Location:
 Historic Front Rear
 Non-Historic Side Roof

Porch

Type: Material:
 Enclosed Porte Cochere Stone Wood
 Stoop Wraparound Brick Concrete
 Veranda Multi-Story

Significance: Location:
 Historic Altered Front Rear
 Side Balcony

Doors

Leaf: One-Leaf
 Material: Wood
 Significance: Arrangement: Type:
 Historic Sidelights Paneled
 Replacement Transom Paneled w/Lights
 Glazed

Windows

Type: Material: Significance:
 Double-Hung Steel Original Windows
 Sliding Wood Original Storms
 Casement Vinyl Replaced Windows
 Fixed Aluminum Replaced Storms

Roof

Type: Material: Dormers:
 Gable Mansard Asphalt Gable
 Hipped Shed Metal Hipped
 Jerkinhead Flat Slate Shed
 Gambrel Shake Jerkin
 Clay Tile

Chimney

Material: Brick Concrete Block Stone

NR ELIGIBILITY

Individual Eligibility
 District Eligibility:

District Name:
 Belvidere Old Town NRHP

Contributing:
 Non-Contributing:

- Events (NR-A)
- Persons (NR-B)
- Architecture (NR-C)
- Archaeology (NR-D)

LOCAL ELIGIBILITY

Individual Eligibility:
 District Eligibility:

District Name:

Contributing:
 Non-Contributing:

- Events 2
- Persons 3
- Architecture 4, 5, 6, 8
- Archaeology
- Other 1, 7, 9, 10, 11

Property Information

Address: 621 E Lincoln PIN: 05-25-160-006
 Building Names:
 Important Dates:
 Historic Function: Residence
 Current Function: Apartments
 Color Code Criteria: None
 Outbuildings
 Number: 0 Any Significant:
 Architectural Style: None
 Property Type: Residential
 Approximate Age: 1880-1889
 Condition: Good
 Potential for Integrity?



Photo: 621_E_Lincoln_Ave_SURVEY_Photo.tif

Description

The single family dwelling is two stories with a low pitched cross-gabled roof and "T" shaped plan. The original 19th century side gabled I-house structure appears to have been modified and enlarged in the 20th century to incorporate Period Revival features. The walls are clad in replacement siding and stone veneer. The primary façade, facing north, is asymmetrical with a prominent, uneven stone veneered gable on the side gabled massing. A large stone chimney is located next to the front gable, and a two story gabled wing extends to the south. A two story rounded bay and enclosed porch are also located on the south elevation. The primary entrance, on the north elevation, is located off a low concrete stoop with simple iron railings and posts support a metal awning. The single-leaf front door has been replaced. Above, a multi-lite door leads out to a wood Juliet balcony. Two first floor windows at the front elevation have stone sills and 6/6 double-hung wood windows while the others have been replaced and their frames clad. A large window bay clad in stone was added to the east elevation and has 6/6 double-hung wood windows. Other replaced windows are centered on the gable...

Structure Information

Structure: Frame/Masonry
 Foundation: Stone Concrete Not Visible
 Brick Parged
 Cladding: Clapboard Asphalt
 Siding Stucco
 Shake Stone
 Board-and-Batten Brick
 Aluminum/Vinyl Concrete Block
 Asbestos Metal

Additions

Type: Historic Non-Historic
 Location: Front Rear
 Side Roof

Porch

Type: Enclosed Porte Cochere
 Stoop Wraparound
 Veranda Multi-Story
 Material: Stone Wood
 Brick Concrete

Significance: Historic Altered
 Location: Front Rear
 Side Balcony

Doors

Leaf: One-Leaf
 Material: Metal
 Significance: Historic Replacement
 Arrangement: Sidelights Transom
 Type: Paneled Paneled w/Lights
 Glazed

Windows

Type: Double-Hung Sliding
 Casement Fixed
 Material: Steel Wood
 Vinyl Aluminum
 Significance: Original Windows
 Original Storms
 Replaced Windows
 Replaced Storms

Roof

Type: Gable Mansard
 Hipped Shed
 Jerkinhead Flat
 Gambrel
 Material: Asphalt Metal
 Slate Shake
 Clay Tile
 Dormers: Gable
 Hipped
 Shed
 Jerkin

Chimney

Material: Brick Concrete Block Stone

NR ELIGIBILITY

Individual Eligibility
 District Eligibility:
 District Name:
 Belvidere Old Town NRHP

Contributing:
 Non-Contributing:

- Events (NR-A)
- Persons (NR-B)
- Architecture (NR-C)
- Archaeology (NR-D)

LOCAL ELIGIBILITY

Individual Eligibility:
 District Eligibility:
 District Name:

Contributing:
 Non-Contributing:

- Events 2
- Persons 3
- Architecture 4, 5, 6, 8
- Archaeology
- Other 1, 7, 9, 10, 11

Property Information

Address: 210 E Hurlbut PIN: 05-26-287-008
 Building Names:
 Important Dates:
 Historic Function: Residence
 Current Function: Residence
 Color Code Criteria: Yellow
 Outbuildings
 Number: 0 Any Significant:
 Architectural Style: Craftsman
 Property Type: Residential
 Approximate Age: 1910-1919
 Condition: Good
 Potential for Integrity?



Photo: 210_E_Hurlbut_Ave_SURVEY_Photo.tif

Description

The one story frame Bungalow has a rectangular footprint and a hipped roof with small front & rear shed dormers. The first floor is raised on a rock-faced concrete block foundation. The front elevation is symmetrical; the full-width front porch has been enclosed with two pairs of 1/1 vinyl windows with faux shutters. All original windows have been replaced with 1/1 vinyl windows. On the west elevation, concrete stoops with metal railings give access to the front and rear porches. The entire house has been re-clad in vinyl siding.

Structure Information

Structure: Frame
 Foundation: Stone Concrete Not Visible
 Brick Parged
 Cladding: Clapboard Asphalt
 Siding Stucco
 Shake Stone
 Board-and-Batten Brick
 Aluminum/Vinyl Concrete Block
 Asbestos Metal

Additions

Type: Historic Non-Historic
 Location: Front Rear
 Side Roof

Porch

Type: Enclosed Stoop Veranda
 Porte Cochere Wraparound Multi-Story
 Material: Stone Wood
 Brick Concrete
 Significance: Historic Altered
 Location: Front Rear
 Side Balcony

Doors

Leaf: One-Leaf
 Material: Metal
 Significance: Historic Replacement
 Arrangement: Sidelights Transom
 Type: Paneled
 Paneled w/Lights
 Glazed

Windows

Type: Double-Hung Sliding
 Casement Fixed
 Material: Steel Wood
 Vinyl Aluminum
 Significance: Original Windows
 Original Storms
 Replaced Windows
 Replaced Storms

Roof

Type: Gable Hipped
 Jerkinhead Gambrel
 Mansard Shed Flat
 Material: Asphalt
 Metal Slate
 Shake Clay Tile
 Dormers: Gable
 Hipped
 Shed
 Jerkin

Chimney

Material: Brick Concrete Block Stone

NR ELIGIBILITY

Individual Eligibility

District Eligibility:

District Name:

Belvidere Old Town NRHP District

Contributing:

Non-Contributing:

- Events (NR-A)
- Persons (NR-B)
- Architecture (NR-C)
- Archaeology (NR-D)

LOCAL ELIGIBILITY

Individual Eligibility:

District Eligibility:

District Name:

Contributing:

Non-Contributing:

- Events 2
- Persons 3
- Architecture 4, 5, 6, 8
- Archaeology
- Other 1, 7, 9, 10, 11

Property Information

Address: 216 E Hurlbut PIN: 05-26-287-009
 Building Names:
 Important Dates:
 Historic Function: Residence
 Current Function: Residence
 Color Code Criteria: Orange
 Outbuildings
 Number: 0 Any Significant:
 Architectural Style: Mid-Century
 Property Type: Residential
 Approximate Age: 1960-1969
 Condition: Good
 Potential for Integrity?



Photo: 216_E_Hurlbut_Ave_SURVEY_Photo.tif

Description

The box ranch, single-family frame home is one story with an asymmetric plan, hipped roof and boxed eaves. The first floor is raised on a rock-faced concrete block foundation and clad in wide siding. The front façade has an off-set footprint for the sleeping & living areas. While the entrance is centered between the two, the living room has a large picture window and the bedroom has a ganged pair of 1/1 windows. Other windows are typically single 1/1 double-hungs. Set back at the northeast corner of the house is a one-car attached garage. The front and side entrances have original slab wood doors with lites. The front stoop is modern concrete with wood railings.

Structure Information

Structure: Frame
 Foundation: Stone Concrete Not Visible
 Brick Parged
 Cladding: Clapboard Asphalt
 Siding Stucco
 Shake Stone
 Board-and-Batten Brick
 Aluminum/Vinyl Concrete Block
 Asbestos Metal

Additions

Type: Historic Non-Historic
 Location: Front Rear
 Side Roof

Porch

Type: Enclosed Porte Cochere Stoop Wraparound Veranda Multi-Story
 Material: Stone Wood Brick Concrete

Significance: Historic Altered
 Location: Front Rear
 Side Balcony

Doors

Leaf: One-Leaf
 Material: Wood
 Significance: Historic Replacement
 Arrangement: Sidelights Transom
 Type: Paneled Paneled w/Lights Glazed

Windows

Type: Double-Hung Sliding Casement Fixed
 Material: Steel Wood Vinyl Aluminum
 Significance: Original Windows Original Storms Replaced Windows Replaced Storms

Roof

Type: Gable Hipped Jerkinhead Gambrel
 Mansard Shed Flat
 Material: Asphalt Metal Slate Shake Clay Tile
 Dormers: Gable Hipped Shed Jerkin

Chimney

Material: Brick Concrete Block Stone

NR ELIGIBILITY

Individual Eligibility
 District Eligibility:

District Name:

Belvidere Old Town NRHP District

Contributing:
 Non-Contributing:

- Events (NR-A)
- Persons (NR-B)
- Architecture (NR-C)
- Archaeology (NR-D)

LOCAL ELIGIBILITY

Individual Eligibility:
 District Eligibility:

District Name:

Contributing:
 Non-Contributing:

- Events 2
- Persons 3
- Architecture 4, 5, 6, 8
- Archaeology
- Other 1, 7, 9, 10, 11

Property Information

Address: 217 E Hurlbut PIN: 05-26-431-012
 Building Names: Holy Trinity Parsonage
 Important Dates:
 Historic Function: Residence
 Current Function: Residence
 Color Code Criteria: Orange
 Outbuildings
 Number: 0 Any Significant:
 Architectural Style: Queen Anne
 Property Type: Residential
 Approximate Age: 1880-1889
 Condition: Good/Excellent
 Potential for Integrity?



Photo: 17_E_Hurlbut_Ave_SURVEY_Photo_PARSONAGE.tif

Structure Information

Structure: Masonry
 Foundation: Stone Concrete Not Visible
 Brick Parged
 Cladding: Clapboard Asphalt
 Siding Stucco
 Shake Stone
 Board-and-Batten Brick
 Aluminum/Vinyl Concrete Block
 Asbestos Metal

Additions

Type: Historic Non-Historic
 Location: Front Rear
 Side Roof

Porch

Type: Enclosed Porte Cochere Stoop Wraparound Veranda Multi-Story
 Material: Stone Wood
 Brick Concrete

Significance: Historic Altered
 Location: Front Rear
 Side Balcony

Doors

Leaf: One-Leaf
 Material: Wood
 Significance: Historic Replacement
 Arrangement: Sidelights Transom
 Type: Paneled Paneled w/Lights
 Glazed

Windows

Type: Double-Hung Sliding Casement Fixed
 Material: Steel Wood Vinyl Aluminum
 Significance: Original Windows Original Storms
 Replaced Windows Replaced Storms

Roof

Type: Gable Mansard Hipped Shed Jerkinhead Flat Gambrel
 Material: Asphalt Metal Slate Shake Clay Tile
 Dormers: Gable Hipped Shed Jerkin

Chimney

Material: Brick Concrete Block Stone

Description

The Italianate, single-family brick house is two stories with front-facing T-gable and wing massing and a tall, steeply pitched roof. The first floor is raised on a fieldstone foundation of local limestone with a dressed-stone water table. The main entrance is currently located on the north façade, but it appears that original door openings in the southwest corner have been bricked up or converted to windows. Ghosts on the brick indicate there was once a one-story porch at the original entrance. The west and north gabled elevations have symmetrical façades of two window bays. Set back two window bays from the west, the north-south cross-gabled section extends one window bay wider than the west wing. At the south façade, a full-height tower one window bay deep accesses each floor and the attic with an entrance at grade level. The rear wing, extending to the east, is one story tall with a gabled roof. A modern one-car garage of brick with a concrete foundation was attached east of the rear wing, continuing the same roofline. Built early in the Italianate period, the remaining details are simple. The tall, narrow 1/1 windows have rectangular sash with segmental-arch brick heads and stone sills, and small rectangular 3-lite basement windows pierce the limestone foundation. At the north façade's...

NR ELIGIBILITY

Individual Eligibility
 District Eligibility:
 District Name:
 Belvidere Old Town NRHP District
 Contributing:
 Non-Contributing:
 Events (NR-A)
 Persons (NR-B)
 Architecture (NR-C)
 Archaeology (NR-D)

LOCAL ELIGIBILITY

Individual Eligibility:
 District Eligibility:
 District Name:
 Contributing:
 Non-Contributing:
 Events 2
 Persons 3
 Architecture 4, 5, 6, 8
 Archaeology
 Other 1, 7, 9, 10, 11

Property Information

Address: 217 E Hurlbut PIN: 05-26-431-013
 Building Names: Holy Trinity Episcopal Church
 Important Dates: 1856
 Historic Function: Church
 Current Function: Church
 Color Code Criteria: Red
 Outbuildings
 Number: 0 Any Significant:
 Architectural Style: Gothic Revival
 Property Type: Institutional
 Approximate Age: 1850-1859
 Condition: Good/Excellent
 Potential for Integrity?



Photo: 217_E_Hurlbut_Ave_SURVEY_Photo_CHURCH.tif

Description

The Carpenter Gothic church has frame construction, a steeply pitched gable roof, central tower and rectangular massing. The building is clad in vertical board-and-batten siding with wide cornice boards at the roofline. A one-and-one-half story sanctuary level is raised on a low foundation of rubble limestone, and the steepled tower rises three stories. The front gabled façade, facing west, is dominated by an engaged central tower with a square footprint and shallow diagonal (French) buttresses. Above the second floor roofline, the corner buttresses are topped with steepled pinnacles and the tower parapet is castellated. A third floor belfry with Gothic arch louvers is set back inside the parapets and topped with a double-pitched steeple and cross finial. The main entrance is centered at the tower's first floor. A pair of large batten doors sits in a Gothic arch opening, with small, pointed arch art glass windows at each side on the main façade. At the main entrance, a wood stoop is decorated with saw-tooth shingles, flat, jig-saw cut balusters and newels in Gothic tracery designs. Above the tower entrance is a small rose window set with wood tracery and art glass. The main, rectangular massing of the sanctuary is also set with diagonal corner buttresses which are capped with gabled pinnacles and wood shingles.

Structure Information

Structure: Frame
 Foundation: Stone Concrete Not Visible
 Brick Parged
 Cladding: Clapboard Asphalt
 Siding Stucco
 Shake Stone
 Board-and-Batten Brick
 Aluminum/Vinyl Concrete Block
 Asbestos Metal

Additions

Type: Location:
 Historic Front Rear
 Non-Historic Side Roof

Porch

Type: Material:
 Enclosed Porte Cochere Stone Wood
 Stoop Wraparound Brick Concrete
 Veranda Multi-Story

Significance: Location:
 Historic Altered Front Rear
 Side Balcony

Doors

Leaf: Two-Leaf
 Material: Wood
 Significance: Arrangement: Type:
 Historic Sidelights Paneled
 Replacement Transom Paneled w/Lights
 Glazed

Windows

Type: Material: Significance:
 Double-Hung Steel Original Windows
 Sliding Wood Original Storms
 Casement Vinyl Replaced Windows
 Fixed Aluminum Replaced Storms

Roof

Type: Material: Dormers:
 Gable Mansard Asphalt Gable
 Hipped Shed Metal Hipped
 Jerkinhead Flat Slate Shed
 Gambrel Shake Jerkin
 Clay Tile

Chimney

Material: Brick Concrete Block Stone

NR ELIGIBILITY

Individual Eligibility
 District Eligibility:
 District Name:
 Belvidere Old Town NRHP District
 Contributing:
 Non-Contributing:

Events (NR-A)
 Persons (NR-B)
 Architecture (NR-C)
 Archaeology (NR-D)

LOCAL ELIGIBILITY

Individual Eligibility:
 District Eligibility:
 District Name:
 Contributing:
 Non-Contributing:

Events 2
 Persons 3
 Architecture 4, 5, 6, 8
 Archaeology
 Other 1, 7, 9, 10, 11

Property Information

Address: 222 E Hurlbut PIN: 05-26-287-010
 Building Names:
 Important Dates:
 Historic Function: Residence
 Current Function: Residence
 Color Code Criteria: Yellow
 Outbuildings
 Number: 0 Any Significant:
 Architectural Style: Greek Revival
 Property Type: Residential
 Approximate Age: 1850-1859
 Condition: Poor
 Potential for Integrity?



Photo: 222_E_Hurlbut_Ave_SURVEY_Photo.tif

Structure Information

Structure: Frame
 Foundation: Stone Concrete Not Visible
 Brick Parged
 Cladding: Clapboard Asphalt
 Siding Stucco
 Shake Stone
 Board-and-Batten Brick
 Aluminum/Vinyl Concrete Block
 Asbestos Metal

Additions

Type: Historic Non-Historic
 Location: Front Rear
 Side Roof

Porch

Type: Enclosed Porte Cochere Stoop Wraparound Veranda Multi-Story
 Material: Stone Wood Brick Concrete

Significance: Historic Altered
 Location: Front Rear
 Side Balcony

Doors

Leaf: One-Leaf
 Material: Metal
 Significance: Historic Replacement
 Arrangement: Sidelights Transom
 Type: Paneled Paneled w/Lights Glazed

Windows

Type: Double-Hung Sliding Casement Fixed
 Material: Steel Wood Vinyl Aluminum
 Significance: Original Windows Original Storms Replaced Windows Replaced Storms

Roof

Type: Gable Hipped Jerkinhead Gambrel
 Mansard Shed Flat
 Material: Asphalt Metal Slate Shake Clay Tile
 Dormers: Gable Hipped Shed Jerkin

Chimney

Material: Brick Concrete Block Stone

Description

The single-family home is two stories with upright and wing massing. The upright section has a front facing gable and is two bays wide and deep. The side-gabled wing spans two bays wide and two bay deep with a gabled roof addition at the rear elevation and a small hipped roof addition at the wing. The first floor is set on a parged foundation, the walls are clad in asbestos siding, and a partial brick chimney stack is located at the upright and wing junction. At the front gable façade, facing south, the single 1/1 double-hung windows are centered. At the wing, a hipped roof porch is set on a concrete stoop and supported with turned wood columns. A second floor wall dormer with a pair of windows is centered above. The replacement entrance door is paneled with multiple lites above. Adjacent to the door there is a 1/1 double hung window. All original windows have been replaced with 1/1 double hung windows, and the wood frames have altered or clad. A shed roof one car garage clad in siding is attached to the rear wing. The size and arrangement of features suggest a settlement dwelling, but many alterations and missing elements have compromised the structure's integrity.

NR ELIGIBILITY

Individual Eligibility:
 District Eligibility:
 District Name:
 Belvidere Old Town NRHP District
 Contributing:
 Non-Contributing:
 Events (NR-A)
 Persons (NR-B)
 Architecture (NR-C)
 Archaeology (NR-D)

LOCAL ELIGIBILITY

Individual Eligibility:
 District Eligibility:
 District Name:
 Contributing:
 Non-Contributing:
 Events 2
 Persons 3
 Architecture 4, 5, 6, 8
 Archaeology
 Other 1, 7, 9, 10, 11

Property Information

Address: 310 E Hurlbut PIN: 05-26-288-006
 Building Names:
 Important Dates:
 Historic Function: Apartments
 Current Function: Apartment
 Color Code Criteria: Yellow
 Outbuildings
 Number: 1 Any Significant:
 Architectural Style: Queen Anne
 Property Type: Residential
 Approximate Age: 1890-1899
 Condition: Fair
 Potential for Integrity?



Photo: 310_E_Hurlbut_Ave_SURVEY_Photo.tif

Description

The Queen Anne, multi-unit dwelling is two stories with a steeply pitched hipped roof and prominent front gable. A two story hipped roof wing extends north at the rear, with an addition small one story shed and gabled roof section at the rear. The first floor is raised on dressed coursed limestone foundation and the walls are clad in stone veneer and asbestos siding. The original wood siding is partially exposed. The primary façade, facing south, is symmetrical with a prominent front gable extending out from the center of the hipped roof. Under the gable there is a double height wood entry porch. Two original single-leaf entrance doors are placed side by side, denoting the vertical separation of the front two units. The first porch level has a short mansard roof, and two additional original doors lead out onto the second floor deck. The balcony railing has been removed and the underside of the gable is braced with plain supports. The main massing is canted at the front elevation, and tall 1/1 double-hung and landscape windows are placed evenly around the east and west elevations. At the west façade, an original side entrance leading to the two story rear unit wing. The original windows continue on the wing, and its hipped roof extends out, echoing...

Structure Information

Structure: Frame
 Foundation: Stone Concrete Not Visible
 Brick Parged
 Cladding: Clapboard Asphalt
 Siding Stucco
 Shake Stone
 Board-and-Batten Brick
 Aluminum/Vinyl Concrete Block
 Asbestos Metal

Additions

Type: Location:
 Historic Front Rear
 Non-Historic Side Roof

Porch

Type: Material:
 Enclosed Porte Cochere Stone Wood
 Stoop Wraparound Brick Concrete
 Veranda Multi-Story

Significance: Location:
 Historic Altered Front Rear
 Side Balcony

Doors

Leaf: One-Leaf
 Material: Wood
 Significance: Arrangement: Type:
 Historic Sidelights Paneled w/Lights
 Replacement Transom Glazed

Windows

Type: Material: Significance:
 Double-Hung Steel Original Windows
 Sliding Wood Original Storms
 Casement Vinyl Replaced Windows
 Fixed Aluminum Replaced Storms

Roof

Type: Material: Dormers:
 Gable Mansard Asphalt Gable
 Hipped Shed Metal Hipped
 Jerkinhead Flat Slate Shed
 Gambrel Shake Jerkin
 Clay Tile

Chimney

Material: Brick Concrete Block Stone

NR ELIGIBILITY

Individual Eligibility
 District Eligibility:

District Name:
 Belvidere Old Town NRHP District

Contributing:
 Non-Contributing:

- Events (NR-A)
- Persons (NR-B)
- Architecture (NR-C)
- Archaeology (NR-D)

LOCAL ELIGIBILITY

Individual Eligibility:
 District Eligibility:

District Name:

Contributing:
 Non-Contributing:

- Events 2
- Persons 3
- Architecture 4, 5, 6, 8
- Archaeology
- Other 1, 7, 9, 10, 11

Property Information

Address: 319 E Hurlbut PIN: 05-26-291-001
 Building Names:
 Important Dates:
 Historic Function: Residence
 Current Function: Residence
 Color Code Criteria: Yellow
 Outbuildings
 Number: 1 Any Significant:
 Architectural Style: Greek Revival
 Property Type: Residential
 Approximate Age: 1860-1869
 Condition: Fair
 Potential for Integrity?



Photo: 319_E_Hurlbut_Ave_SURVEY_Photo.tif

Structure Information

Structure: Frame
 Foundation: Stone Concrete Not Visible
 Brick Parged
 Cladding: Clapboard Asphalt
 Siding Stucco
 Shake Stone
 Board-and-Batten Brick
 Aluminum/Vinyl Concrete Block
 Asbestos Metal

Additions

Type: Location:
 Historic Front Rear
 Non-Historic Side Roof

Porch

Type: Material:
 Enclosed Porte Cochere Stone Wood
 Stoop Wraparound Brick Concrete
 Veranda Multi-Story

Significance: Location:
 Historic Altered Front Rear
 Side Balcony

Doors

Leaf: One-Leaf
 Material: Metal
 Significance: Arrangement: Type:
 Historic Sidelights Paneled
 Replacement Transom Paneled w/Lights
 Glazed

Windows

Type: Material: Significance:
 Double-Hung Steel Original Windows
 Sliding Wood Original Storms
 Casement Vinyl Replaced Windows
 Fixed Aluminum Replaced Storms

Roof

Type: Material: Dormers:
 Gable Mansard Asphalt Gable
 Hipped Shed Metal Hipped
 Jerkinhead Flat Slate Shed
 Gambrel Shake Jerkin
 Clay Tile

Chimney

Material: Brick Concrete Block Stone

Description

The single-family I-house is one-and-one-half stories with a side-gabled roof and a rectangular plan spanning three windows bays wide and two bays deep. The foundation is not visible and the walls are clad in siding. The front façade, facing north, is symmetrical with paired windows flanking the central entrance. The single-leaf door has been replaced, and is located at a low concrete stoop. Over the door is a short mansard porch canopy supported by elaborately turned brackets. The centered door and off-center internal brick chimney suggests a central passage plan. The first floor windows around the east, west and north elevations are original pairs of tall, narrow 2/2 double-hung wood windows. The same widow openings occur in the gable ends, but the windows have been replaced. They retain their simple wood framing. On the rear elevation there is a one story gabled addition with a concrete foundation and walls clad in siding. Set at the west edge of the lot is a mid-century, two-car, front gabled garage clad in siding. The massing and remaining features of this I-House are relatively intact, and the remaining details suggest an early application of Victorian decoration.

NR ELIGIBILITY

Individual Eligibility
 District Eligibility:

District Name:
 Belvidere Old Town NRHP District

Contributing:
 Non-Contributing:

- Events (NR-A)
- Persons (NR-B)
- Architecture (NR-C)
- Archaeology (NR-D)

LOCAL ELIGIBILITY

Individual Eligibility:
 District Eligibility:

District Name:

Contributing:
 Non-Contributing:

- Events 2
- Persons 3
- Architecture 4, 5, 6, 8
- Archaeology
- Other 1, 7, 9, 10, 11

Property Information

Address: 320 E Hurlbut PIN: 05-26-288-007
 Building Names:
 Important Dates:
 Historic Function: Residence
 Current Function: Residence
 Color Code Criteria: Orange
 Outbuildings
 Number: 1 Any Significant:
 Architectural Style: Craftsman
 Property Type: Residential
 Approximate Age: 1920-1929
 Condition: Good/Excellent
 Potential for Integrity?



Photo: 320_E_Hurlbut_Ave_SURVEY_Photo.tif

Structure Information

Structure: Masonry
 Foundation: Stone Concrete Not Visible
 Brick Parged
 Cladding: Clapboard Asphalt
 Siding Stucco
 Shake Stone
 Board-and-Batten Brick
 Aluminum/Vinyl Concrete Block
 Asbestos Metal

Additions

Type: Location:
 Historic Front Rear
 Non-Historic Side Roof

Porch

Type: Material:
 Enclosed Porte Cochere Stone Wood
 Stoop Wraparound Brick Concrete
 Veranda Multi-Story

Significance: Location:
 Historic Altered Front Rear
 Side Balcony

Doors

Leaf: One-Leaf
 Material: Wood
 Significance: Arrangement: Type:
 Historic Sidelights Paneled w/Lights
 Replacement Transom Glazed

Windows

Type: Material: Significance:
 Double-Hung Steel Original Windows
 Sliding Wood Original Storms
 Casement Vinyl Replaced Windows
 Fixed Aluminum Replaced Storms

Roof

Type: Material: Dormers:
 Gable Mansard Asphalt Gable
 Hipped Shed Metal Hipped
 Jerkinhead Flat Slate Shed
 Gambrel Shake Jerkin
 Clay Tile

Chimney

Material: Brick Concrete Block Stone

Description

The one-and-one-half story brick Bungalow has a hipped roof and a front gabled entry with a chimney on the west elevation. The brown brick walls are laid in a running bond with recessed spandrel panels under windows and decorative accents at vertical spaces. The front elevation, facing south, has a centralized gable roof entry porch and an asymmetrical layout. The entry porch is set on a brick stoop with tall arched openings and the original multi-lite full lite door remains. To the west, the living area projects out and is wrapped with pairs of double-hung 1/1 windows. To the east there is a single 1/1 double hung window. The windows continue to be single and paired double-hungs with stone lug sills, and the majority of them have been replaced. At the rear roof hips there are small shed gables clad in siding with 2-lite windows. At the northeast corner of the lot, there is a brick two-car garage with a hipped roof. The home has maintained relatively good integrity, and the prominent front entrance, plan arrangement, and size make this a unique middle-class example of a brick Bungalow.

NR ELIGIBILITY

Individual Eligibility
 District Eligibility:

District Name:

Belvidere Old Town NRHP District

Contributing:
 Non-Contributing:

- Events (NR-A)
- Persons (NR-B)
- Architecture (NR-C)
- Archaeology (NR-D)

LOCAL ELIGIBILITY

Individual Eligibility:
 District Eligibility:

District Name:

Contributing:
 Non-Contributing:

- Events 2
- Persons 3
- Architecture 4, 5, 6, 8
- Archaeology
- Other 1, 7, 9, 10, 11

Property Information

Address: 322 E Hurlbut PIN: 05-26-288-008
 Building Names:
 Important Dates:
 Historic Function: Residence
 Current Function: Residence
 Color Code Criteria: Yellow
 Outbuildings
 Number: 1 Any Significant:
 Architectural Style: Queen Anne
 Property Type: Residential
 Approximate Age: 1880-1889
 Condition: Fair
 Potential for Integrity?



Photo: 322_E_Hurlbut_Ave_SURVEY_Photo.tif

Description

The two story Queen Anne residence has an Upright-and-wing form with several one story additions at the rear elevation. The first floor is raised on a foundation of rough-cut limestone, the house is clad in contemporary vinyl siding, and original cornice boards are still visible. A brick chimney is located at the upright and wing junction. The main front gabled massing, facing south, is two stories tall with a centered, three-sided windows bay that the first floor with a pair of windows above. The bay has a low hipped roof accented with brackets. The windows, thought not original, are 3/1 wood double-hungs from the early 20th century. The one-and-one-half side gabled wing, has three symmetrical bays at the first floor with two small attic windows above. At the wing there is an open front porch with a hipped roof and concrete slab with contemporary iron roof supports and railings. Consistent with a variation of this farm house type, there are two entrance doors off the porch. One is located on the south elevation of the main front gabled massing (a parlor entrance), and another is centered at the south elevation of the side gabled kitchen wing. Both have been replaced. The window framing is clad and...

Structure Information

Structure: Frame
 Foundation: Stone Concrete Not Visible
 Brick Parged
 Cladding: Clapboard Asphalt
 Siding Stucco
 Shake Stone
 Board-and-Batten Brick
 Aluminum/Vinyl Concrete Block
 Asbestos Metal

Additions

Type: Location:
 Historic Front Rear
 Non-Historic Side Roof

Porch

Type: Material:
 Enclosed Porte Cochere Stone Wood
 Stoop Wraparound Brick Concrete
 Veranda Multi-Story

Significance: Location:
 Historic Altered Front Rear
 Side Balcony

Doors

Leaf: One-Leaf
 Material: Metal
 Significance: Arrangement: Type:
 Historic Sidelights Paneled
 Replacement Transom Paneled w/Lights
 Glazed

Windows

Type: Material: Significance:
 Double-Hung Steel Original Windows
 Sliding Wood Original Storms
 Casement Vinyl Replaced Windows
 Fixed Aluminum Replaced Storms

Roof

Type: Material: Dormers:
 Gable Mansard Asphalt Gable
 Hipped Shed Metal Hipped
 Jerkinhead Flat Slate Shed
 Gambrel Shake Jerkin
 Clay Tile

Chimney

Material: Brick Concrete Block Stone

NR ELIGIBILITY

Individual Eligibility
 District Eligibility:

District Name:

Belvidere Old Town NRHP District

Contributing:

Non-Contributing:

- Events (NR-A)
- Persons (NR-B)
- Architecture (NR-C)
- Archaeology (NR-D)

LOCAL ELIGIBILITY

Individual Eligibility:
 District Eligibility:

District Name:

Contributing:

Non-Contributing:

- Events 2
- Persons 3
- Architecture 4, 5, 6, 8
- Archaeology
- Other 1, 7, 9, 10, 11

Property Information

Address: 402 E Hurlbut PIN: 05-26-289-006
 Building Names:
 Important Dates: 1955 (date of construction)
 Historic Function: Residence
 Current Function: Residence
 Color Code Criteria: Orange
 Outbuildings
 Number: 0 Any Significant:
 Architectural Style: Mid-Century
 Property Type: Residential
 Approximate Age: 1950-1959
 Condition: Excellent
 Potential for Integrity?



Photo: 402_E_Hurlbut_Ave_SURVEY_Photo.tif

Structure Information

Structure: Masonry
 Foundation: Stone Concrete Not Visible
 Brick Parged
 Cladding: Clapboard Asphalt
 Siding Stucco
 Shake Stone
 Board-and-Batten Brick
 Aluminum/Vinyl Concrete Block
 Asbestos Metal

Additions

Type: Location:
 Historic Front Rear
 Non-Historic Side Roof

Porch

Type: Material:
 Enclosed Porte Cochere Stone Wood
 Stoop Wraparound Brick Concrete
 Veranda Multi-Story

Significance: Location:
 Historic Altered Front Rear
 Side Balcony

Doors

Leaf: One-Leaf
 Material: Wood Type:
 Significance: Arrangement: Paneled
 Historic Sidelights Paneled w/Lights
 Replacement Transom Glazed

Windows

Type: Material: Significance:
 Double-Hung Steel Original Windows
 Sliding Wood Original Storms
 Casement Vinyl Replaced Windows
 Fixed Aluminum Replaced Storms

Roof

Type: Material: Dormers:
 Gable Mansard Asphalt Gable
 Hipped Shed Metal Hipped
 Jerkinhead Flat Slate Shed
 Gambrel Clay Tile Jerkin

Chimney

Material: Brick Concrete Block Stone

Description

This mid-century Period Revival single-family home is one story tall with a boxy plan, hipped roof, and front facing gable. The walls are set on a concrete slab and constructed of buff colored brick laid in a running bond. The primary massing is hipped with a prominent front gable at the south façade and a central, internal brick chimney. The off-center gable gives the façade an asymmetrical layout and a large window assembly composed of a picture window flanked by 2/2 double-hungs is centered below the gable at the first floor. Adjacent to this, the main entrance is centered on the façade and located off a small concrete stoop with simple metal railings. The original single-leaf entrance door has two horizontal lites with panels below. The original single 2/2 double-hung windows have cast stone slip sills, faux shutters, and are spaced evenly around each secondary façade. A short pair of one-lite windows is located at the kitchen. At the north elevation, an enclosed breezeway leads to a one car garage. The garage is front gabled with a concrete foundation and walls clad in siding. The size, massing and original features have excellent integrity, making this a fine example of a modest Minimal Traditional home.

NR ELIGIBILITY

Individual Eligibility:
 District Eligibility:
 District Name:
 Belvidere Old Town NRHP District
 Contributing:
 Non-Contributing:
 Events (NR-A)
 Persons (NR-B)
 Architecture (NR-C)
 Archaeology (NR-D)

LOCAL ELIGIBILITY

Individual Eligibility:
 District Eligibility:
 District Name:
 Contributing:
 Non-Contributing:
 Events 2
 Persons 3
 Architecture 4, 5, 6, 8
 Archaeology
 Other 1, 7, 9, 10, 11

Property Information

Address: 409 E Hurlbut PIN: 05-25-159-001
 Building Names:
 Important Dates:
 Historic Function: Residence
 Current Function: Residence
 Color Code Criteria: Yellow
 Outbuildings
 Number: 0 Any Significant:
 Architectural Style: Gothic Revival
 Property Type: Residential
 Approximate Age: 1880-1889
 Condition: Fair
 Potential for Integrity?



Photo: 409_E_Hurlbut_Ave_SURVEY_Photo.tif

Structure Information

Structure: Frame
 Foundation: Stone Concrete Not Visible
 Brick Parged
 Cladding: Clapboard Asphalt
 Siding Stucco
 Shake Stone
 Board-and-Batten Brick
 Aluminum/Vinyl Concrete Block
 Asbestos Metal

Additions

Type: Location:
 Historic Front Rear
 Non-Historic Side Roof

Porch

Type: Material:
 Enclosed Porte Cochere Stone Wood
 Stoop Wraparound Brick Concrete
 Veranda Multi-Story
 Significance: Location:
 Historic Altered Front Rear
 Side Balcony

Doors

Leaf: One-Leaf
 Material: Wood
 Significance: Arrangement: Type:
 Historic Sidelights Paneled w/Lights
 Replacement Transom Glazed

Windows

Type: Material: Significance:
 Double-Hung Steel Original Windows
 Sliding Wood Original Storms
 Casement Vinyl Replaced Windows
 Fixed Aluminum Replaced Storms

Roof

Type: Material: Dormers:
 Gable Mansard Asphalt Gable
 Hipped Shed Metal Hipped
 Jerkinhead Flat Slate Shed
 Gambrel Shake Jerkin
 Clay Tile

Chimney

Material: Brick Concrete Block Stone

Description

The two story Victorian cottage has a rectangular plan with side gabled massing and a centered gable. The first floor is raised on a parged masonry foundation, the house is clad in contemporary siding, and a brick chimney is centrally located. At the front elevation, facing north, a pair of windows is centered in the front gable with a small 1/1 sash to one side. The main entrance door is located to one side at a concrete stoop. The single-leaf entry door is original with detailed stickwork casing and an arch-top half lite. At the first floor, a wide Chicago style window with faux shutters has been retrofitted. Windows at the secondary elevations are tall 1/1 double hungs and are evenly spaced. They appear to be original with simple wood frames. The massing, roofline and remaining original features suggest that this Victorian cottage had additional Queen Anne style stickwork or spindlework detailing. However, various modifications and alterations have removed much of the dwelling's integrity.

NR ELIGIBILITY

Individual Eligibility:
 District Eligibility:
 District Name:
 Belvidere Old Town NRHP District
 Contributing:
 Non-Contributing:
 Events (NR-A)
 Persons (NR-B)
 Architecture (NR-C)
 Archaeology (NR-D)

LOCAL ELIGIBILITY

Individual Eligibility:
 District Eligibility:
 District Name:
 Contributing:
 Non-Contributing:
 Events 2
 Persons 3
 Architecture 4, 5, 6, 8
 Archaeology
 Other 1, 7, 9, 10, 11

Property Information

Address: 410 E Hurlbut PIN: 05-26-289-007
 Building Names:
 Important Dates:
 Historic Function: Residence
 Current Function: Residence
 Color Code Criteria: Orange
 Outbuildings
 Number: 1 Any Significant:
 Architectural Style: Craftsman
 Property Type: Residential
 Approximate Age: 1920-1929
 Condition: Excellent
 Potential for Integrity?



Photo: 410_E_Hurlbut_Ave_SURVEY_Photo.tif

Description

The American Foursquare single-family residence is two-and-one-half stories with a square plan and side gabled massing. The first floor is raised on a rock-faced concrete block foundation and the house is clad in siding. The side gables are closed with pent roofs. At the front elevation, facing south, two window bays are placed symmetrically with two pented gable dormers at the roof. A full width enclosed porch obscures the first floor of the primary elevation. The main house foundation continues at the shed porch, and the entrance door is located slightly off-center at a concrete stoop. The porch is lined with groupings of wood 1/1 double hung windows with faux shutters. The single-leaf main entry door is original with a lite and panels. At the east elevation, four windows step up from front to back, suggesting an entrance room and a prominent interior stairway. At the west elevation's first floor there is a one story, three-sided window bay to the south and a grouping of three windows to the north. These windows have had large fabric awnings installed which obscures the windows. High in the pented side gables are pairs of 1/1 double hung windows. Almost all the original 1/1 double-hung wood windows are original, with simple...

Structure Information

Structure: Frame
 Foundation: Stone Concrete Not Visible
 Brick Parged
 Cladding: Clapboard Asphalt
 Siding Stucco
 Shake Stone
 Board-and-Batten Brick
 Aluminum/Vinyl Concrete Block
 Asbestos Metal

Additions

Type: Location:
 Historic Front Rear
 Non-Historic Side Roof

Porch

Type: Material:
 Enclosed Porte Cochere Stone Wood
 Stoop Wraparound Brick Concrete
 Veranda Multi-Story

Significance: Location:
 Historic Altered Front Rear
 Side Balcony

Doors

Leaf: One-Leaf
 Material: Wood
 Significance: Arrangement: Type:
 Historic Sidelights Paneled
 Replacement Transom Paneled w/Lights
 Glazed

Windows

Type: Material: Significance:
 Double-Hung Steel Original Windows
 Sliding Wood Original Storms
 Casement Vinyl Replaced Windows
 Fixed Aluminum Replaced Storms

Roof

Type: Material: Dormers:
 Gable Mansard Asphalt Gable
 Hipped Shed Metal Hipped
 Jerkinhead Flat Slate Shed
 Gambrel Clay Tile Shake Jerkin

Chimney

Material: Brick Concrete Block Stone

NR ELIGIBILITY

Individual Eligibility
 District Eligibility:

District Name:
 Belvidere Old Town NRHP District

Contributing:
 Non-Contributing:

- Events (NR-A)
- Persons (NR-B)
- Architecture (NR-C)
- Archaeology (NR-D)

LOCAL ELIGIBILITY

Individual Eligibility:
 District Eligibility:

District Name:

Contributing:
 Non-Contributing:

- Events 2
- Persons 3
- Architecture 4, 5, 6, 8
- Archaeology
- Other 1, 7, 9, 10, 11

Property Information

Address: 413 E Hurlbut PIN: 05-25-159-003
 Building Names:
 Important Dates:
 Historic Function: Residence
 Current Function: Residence
 Color Code Criteria: Yellow
 Outbuildings
 Number: 1 Any Significant:
 Architectural Style: Queen Anne
 Property Type: Residential
 Approximate Age: 1890-1899
 Condition: Good
 Potential for Integrity?



Photo: 413_E_Hurlbut_Ave_SURVEY_Photo.tif

Structure Information

Structure: Frame
 Foundation: Stone Concrete Not Visible
 Brick Parged
 Cladding: Clapboard Asphalt
 Siding Stucco
 Shake Stone
 Board-and-Batten Brick
 Aluminum/Vinyl Concrete Block
 Asbestos Metal

Description

The single-family frame cottage is two stories with a steeply pitched roof and front gabled massing. The first floor is raised on a foundation of rusticated limestone that has been parged and the exterior is clad in vinyl siding. At the primary elevation, facing north, there is a full width enclosed porch with gabled roof that wraps around the east elevation. The porch is set on rock-faced concrete blocks that rise to half the porch's height. The porch is lined with replacement windows sided, with partially visible corner posts. On center at the front gable's second floor is a pair of 1/1 double-hung windows. Single 1/1 windows continue around the secondary façades, with a large picture window on the west elevation. At rear elevation, extending south, there is a one story gabled wing with small 1/1 windows. Small 1-lite rectangular windows pierce the foundation. A majority of the original windows have been replaced. Built at the turn of the century with modest Queen Anne detailing, this house has lost a significant amount of integrity due to subsequent alterations.

Additions

Type: Location:
 Historic Front Rear
 Non-Historic Side Roof

Porch

Type: Material:
 Enclosed Porte Cochere Stone Wood
 Stoop Wraparound Brick Concrete
 Veranda Multi-Story
 Significance: Location:
 Historic Altered Front Rear
 Side Balcony

Doors

Leaf: One-Leaf
 Material: Wood
 Significance: Arrangement: Type:
 Historic Sidelights Paneled w/Lights
 Replacement Transom Glazed

Windows

Type: Material: Significance:
 Double-Hung Steel Original Windows
 Sliding Wood Original Storms
 Casement Vinyl Replaced Windows
 Fixed Aluminum Replaced Storms

Roof

Type: Material: Dormers:
 Gable Mansard Asphalt Gable
 Hipped Shed Metal Hipped
 Jerkinhead Flat Slate Shed
 Gambrel Clay Tile Shake Jerkin

Chimney

Material: Brick Concrete Block Stone

NR ELIGIBILITY

Individual Eligibility:
 District Eligibility:
 District Name:
 Belvidere Old Town NRHP District
 Contributing:
 Non-Contributing:
 Events (NR-A)
 Persons (NR-B)
 Architecture (NR-C)
 Archaeology (NR-D)

LOCAL ELIGIBILITY

Individual Eligibility:
 District Eligibility:
 District Name:
 Contributing:
 Non-Contributing:
 Events 2
 Persons 3
 Architecture 4, 5, 6, 8
 Archaeology
 Other 1, 7, 9, 10, 11

Property Information

Address: 416 E Hurlbut PIN: 05-26-289-008
 Building Names:
 Important Dates:
 Historic Function: Residence
 Current Function: Residence
 Color Code Criteria: Yellow
 Outbuildings
 Number: 1 Any Significant:
 Architectural Style: Queen Anne
 Property Type: Residential
 Approximate Age: 1890-1899
 Condition: Fair
 Potential for Integrity?



Photo: 416_E_Hurlbut_Ave_SURVEY_Photo.tif

Description

The Queen Anne, single-family frame house is two-and-one-half stories with a steeply pitched roof and cross-gabled massing. The first floor is raised on a foundation of coursed rock-faced limestone, the exterior is clad in siding and the chimney is centrally located on the roof hip. At the primary elevation, facing south, a gable-front section with centered window openings extends forward from the hipped roof section, where the main entry is placed at the southeast corner. The main entry porch is wood with a hipped roof, gabled accent, and slim colonnettes set on pedestals. The railing is simple, the cornice is decorated with brackets and the gable accent is clad in fish scale shingles. The single-leaf entrance door has a half lite with panels below. Directly adjacent is a canted first floor window bay. The south elevation gable end windows are centered with large windows at the first and second floors with a one-lite attic sash high in the gable end. The east and west gables have symmetrical window placement and a one-sided canted bay at the first floor is accented with decorative brackets. A one-story gabled wing is located at the rear elevation. Typical windows are single, tall, 1/1 double-hungs with rectangular sash and plain...

Structure Information

Structure: Frame
 Foundation: Stone Concrete Not Visible
 Brick Parged
 Cladding: Clapboard Asphalt
 Siding Stucco
 Shake Stone
 Board-and-Batten Brick
 Aluminum/Vinyl Concrete Block
 Asbestos Metal

Additions

Type: Location:
 Historic Front Rear
 Non-Historic Side Roof

Porch

Type: Material:
 Enclosed Porte Cochere Stone Wood
 Stoop Wraparound Brick Concrete
 Veranda Multi-Story

Significance: Location:
 Historic Altered Front Rear
 Side Balcony

Doors

Leaf: One-Leaf
 Material: Wood
 Significance: Arrangement: Type:
 Historic Sidelights Paneled w/Lights
 Replacement Transom Glazed

Windows

Type: Material: Significance:
 Double-Hung Steel Original Windows
 Sliding Wood Original Storms
 Casement Vinyl Replaced Windows
 Fixed Aluminum Replaced Storms

Roof

Type: Material: Dormers:
 Gable Mansard Asphalt Gable
 Hipped Shed Metal Hipped
 Jerkinhead Flat Slate Shed
 Gambrel Shake Jerkin
 Clay Tile

Chimney

Material: Brick Concrete Block Stone

NR ELIGIBILITY

Individual Eligibility:
 District Eligibility:
 District Name:
 Belvidere Old Town NRHP District
 Contributing:
 Non-Contributing:
 Events (NR-A)
 Persons (NR-B)
 Architecture (NR-C)
 Archaeology (NR-D)

LOCAL ELIGIBILITY

Individual Eligibility:
 District Eligibility:
 District Name:
 Contributing:
 Non-Contributing:
 Events 2
 Persons 3
 Architecture 4, 5, 6, 8
 Archaeology
 Other 1, 7, 9, 10, 11

Property Information

Address: 417 E Hurlbut PIN: 05-25-159-004
 Building Names:
 Important Dates:
 Historic Function: Residence
 Current Function: Residence
 Color Code Criteria: Yellow
 Outbuildings
 Number: 1 Any Significant:
 Architectural Style: Queen Anne
 Property Type: Residential
 Approximate Age: 1900-1909
 Condition: Good/Excellent
 Potential for Integrity?



Photo: 417_E_Hurlbut_Ave_SURVEY_Photo.tif

Structure Information

Structure: Frame
 Foundation: Stone Concrete Not Visible
 Brick Parged
 Cladding: Clapboard Asphalt
 Siding Stucco
 Shake Stone
 Board-and-Batten Brick
 Aluminum/Vinyl Concrete Block
 Asbestos Metal

Additions

Type: Location:
 Historic Front Rear
 Non-Historic Side Roof

Porch

Type: Material:
 Enclosed Porte Cochere Stone Wood
 Stoop Wraparound Brick Concrete
 Veranda Multi-Story
 Significance: Location:
 Historic Altered Front Rear
 Side Balcony

Doors

Leaf: One-Leaf
 Material: Metal
 Significance: Arrangement: Type:
 Historic Sidelights Paneled
 Replacement Transom Paneled w/Lights
 Glazed

Windows

Type: Material: Significance:
 Double-Hung Steel Original Windows
 Sliding Wood Original Storms
 Casement Vinyl Replaced Windows
 Fixed Aluminum Replaced Storms

Roof

Type: Material: Dormers:
 Gable Mansard Asphalt Gable
 Hipped Shed Metal Hipped
 Jerkinhead Flat Slate Shed
 Gambrel Shake Jerkin
 Clay Tile

Chimney

Material: Brick Concrete Block Stone

Description

The Queen Anne, single-family dwelling is two stories with a steeply pitched cross-gabled roof and "T" shaped plan. The first floor is raised on parged limestone foundation and the walls are clad in siding with plain cornice and corner boards. A brick chimney is located on center. The primary façade, facing north, has a prominent front gable and centered window openings. The main entrance is located at the northwest inside corner off a modified gable roof porch with added concrete block walls and a slab stoop. The single-leaf front door is not original. The window openings at the front gable have been altered. At the first floor, a wide band of 1/1 double-hung windows stretches the full width, with groupings continuing around the corners. A pair of windows at the second floor have been replaced with two-lite slider. The east and west projecting cross gable elevations have centered windows. A rear wing, extending to the south, is one story tall with a gabled roof. Many of the tall, narrow 1/1 windows have been replaced, and small rectangular basement windows pierce the foundation. Little to no Queen Anne detailing remains, and much of the home's integrity has been lost due to alterations.

NR ELIGIBILITY

Individual Eligibility
 District Eligibility:
 District Name:
 Belvidere Old Town NRHP District
 Contributing:
 Non-Contributing:
 Events (NR-A)
 Persons (NR-B)
 Architecture (NR-C)
 Archaeology (NR-D)

LOCAL ELIGIBILITY

Individual Eligibility:
 District Eligibility:
 District Name:
 Contributing:
 Non-Contributing:
 Events 2
 Persons 3
 Architecture 4, 5, 6, 8
 Archaeology
 Other 1, 7, 9, 10, 11

Property Information

Address: 421 E Hurlbut PIN: 05-25-159-005
 Building Names:
 Important Dates:
 Historic Function: Residence
 Current Function: Residence
 Color Code Criteria: Yellow
 Outbuildings
 Number: 0 Any Significant:
 Architectural Style: Queen Anne
 Property Type: Residential
 Approximate Age: 1900-1909
 Condition: Good
 Potential for Integrity?



Photo: 421_E_Hurlbut_Ave_SURVEY_Photo.tif

Description

The Queen Anne, single family frame house is two stories with a steeply pitched hipped roof and cross-gabled massing. The first floor is raised on a parged foundation, the exterior is clad in siding and the chimney is centrally located at the roof junction. At the primary elevation, facing north, a clipped gable section with centered window openings extends forward from the cross-gabled roof section, where the main entry is placed at the northeast corner. The main entry porch is wood with a short mansard roof supported by square wood posts on a wood deck. The railings are simple, and two original engaged turned posts survive at the façade. The single-leaf entrance door has been replaced, and a cast metal storm door has been installed. The north elevation gable end windows are centered with a large window at the first and a pair of windows as the second floor. The first floor is canted with 1/1 double hung windows and decorative brackets. The east and west cross gables have paired windows on center. The hipped roof extends back, and a one-story gabled two-car garage is located at the rear elevation. Typical windows are single, tall, 1/1 double-hungs with rectangular sash and plain wood framing. Many...

Structure Information

Structure: Frame
 Foundation: Stone Concrete Not Visible
 Brick Parged
 Cladding: Clapboard Asphalt
 Siding Stucco
 Shake Stone
 Board-and-Batten Brick
 Aluminum/Vinyl Concrete Block
 Asbestos Metal

Additions

Type: Location:
 Historic Front Rear
 Non-Historic Side Roof

Porch

Type: Material:
 Enclosed Porte Cochere Stone Wood
 Stoop Wraparound Brick Concrete
 Veranda Multi-Story

Significance: Location:
 Historic Altered Front Rear
 Side Balcony

Doors

Leaf: One-Leaf
 Material: Metal
 Significance: Arrangement: Type:
 Historic Sidelights Paneled
 Replacement Transom Paneled w/Lights
 Glazed

Windows

Type: Material: Significance:
 Double-Hung Steel Original Windows
 Sliding Wood Original Storms
 Casement Vinyl Replaced Windows
 Fixed Aluminum Replaced Storms

Roof

Type: Material: Dormers:
 Gable Mansard Asphalt Gable
 Hipped Shed Metal Hipped
 Jerkinhead Flat Slate Shed
 Gambrel Clay Tile Shake Jerkin

Chimney

Material: Brick Concrete Block Stone

NR ELIGIBILITY

Individual Eligibility:
 District Eligibility:

District Name:
 Belvidere Old Town NRHP District

Contributing:
 Non-Contributing:

Events (NR-A)
 Persons (NR-B)
 Architecture (NR-C)
 Archaeology (NR-D)

LOCAL ELIGIBILITY

Individual Eligibility:
 District Eligibility:

District Name:

Contributing:
 Non-Contributing:

Events 2
 Persons 3
 Architecture 4, 5, 6, 8
 Archaeology
 Other 1, 7, 9, 10, 11

Property Information

Address: 424 E Hurlbut PIN: 05-25-157-001
 Building Names:
 Important Dates:
 Historic Function: Residence
 Current Function: Residence
 Color Code Criteria: None
 Outbuildings
 Number: 1 Any Significant:
 Architectural Style: Settlement
 Property Type: Residential
 Approximate Age: 1850-1859
 Condition: Good
 Potential for Integrity?



Photo: 424_E_Hurlbut_Ave_SURVEY_Photo.tif

Structure Information

Structure: Frame
 Foundation: Stone Concrete Not Visible
 Brick Parged
 Cladding: Clapboard Asphalt
 Siding Stucco
 Shake Stone
 Board-and-Batten Brick
 Aluminum/Vinyl Concrete Block
 Asbestos Metal

Additions

Type: Location:
 Historic Front Rear
 Non-Historic Side Roof

Porch

Type: Material:
 Enclosed Porte Cochere Stone Wood
 Stoop Wraparound Brick Concrete
 Veranda Multi-Story

Significance: Location:
 Historic Altered Front Rear
 Side Balcony

Doors

Leaf: One-Leaf
 Material: Type:
 Significance: Arrangement: Paneled
 Historic Sidelights Paneled w/Lights
 Replacement Transom Glazed

Windows

Type: Material: Significance:
 Double-Hung Steel Original Windows
 Sliding Wood Original Storms
 Casement Vinyl Replaced Windows
 Fixed Aluminum Replaced Storms

Roof

Type: Material: Dormers:
 Gable Mansard Asphalt Gable
 Hipped Shed Metal Hipped
 Jerkinhead Flat Slate Shed
 Gambrel Shake Jerkin
 Clay Tile

Chimney

Material: Brick Concrete Block Stone

Description

The single-family upright and wing dwelling is one-and-one-half stories with a gabled roof and several one story shed and hipped roof additions. The primary front-gabled massing has a rectangular plan spanning two windows bays wide and two bays deep. The first floor is set on a rock-face concrete block foundation, the walls are clad in siding and stone veneer, and the brick chimney is centrally located on the side wing. The front gable, facing south, has even window placement at the second floor and an unoriginal grouping of three windows and the first floor. At the two bay wide side wing there is a wood porch with a hipped roof that merges into the wing's shed roof and is supported by turned posts. The single-leaf entrance door has been replaced. Windows at the east elevation are evenly spaced. The original double-hung windows have been replaced. On the rear elevation there is a one story gabled wing and another shed roof addition. Set at the north edge of the lot is a one-car, clipped gabled garage clad in siding. The features of this house suggest a Folk Victorian or Queen Anne style, but multiple alterations and modifications have compromised much of its integrity.

NR ELIGIBILITY

Individual Eligibility:
 District Eligibility:
 District Name:
 Belvidere Old Town NRHP District
 Contributing:
 Non-Contributing:
 Events (NR-A)
 Persons (NR-B)
 Architecture (NR-C)
 Archaeology (NR-D)

LOCAL ELIGIBILITY

Individual Eligibility:
 District Eligibility:
 District Name:
 Contributing:
 Non-Contributing:
 Events 2
 Persons 3
 Architecture 4, 5, 6, 8
 Archaeology
 Other 1, 7, 9, 10, 11

Property Information

Address: 115 E Madison PIN: 05-26-427-005
 Building Names:
 Important Dates:
 Historic Function: Residence
 Current Function: Apartments
 Color Code Criteria: Yellow
 Outbuildings
 Number: 0 Any Significant:
 Architectural Style: Queen Anne
 Property Type: Residential
 Approximate Age: 1900-1909
 Condition: Good
 Potential for Integrity?



Photo: 115_E_Madison_St_SURVEY_Photo.tif

Description

The Queen Anne, multi-unit house is two-and-one-half stories with a steeply pitched hipped roof and cross-gabled massing. It appears that the structure was moved a half block east from its original location fronting State St. The first floor is raised on a concrete block foundation, the exterior is clad in siding and the brick chimney is located at the rear elevation. The current street elevation, facing north, is the side of the house. The formal front elevation, facing west, has a gable-front section which projects slightly beyond the hipped roof section (now flattened). The floors below the closed, pented gable are canted, and several modifications have been made to the window layout. Remnants of the hipped porch roof remain, though it has been converted into an open car port. The north/south cross gables are also pented, and there are remnants of Palladian windows at the attic level. Below the north gable there is a tall, shallow oriel bay with large multi-story window openings that have been highly altered. At grade there is an enclosed entry vestibule with an uneven gable roof. The rear hipped roof section extends west and has a shed roof dormer. At grade is an additional enclosed entry vestibule with...

Structure Information

Structure: Frame
 Foundation: Stone Concrete Not Visible
 Brick Parged
 Cladding: Clapboard Asphalt
 Siding Stucco
 Shake Stone
 Board-and-Batten Brick
 Aluminum/Vinyl Concrete Block
 Asbestos Metal

Additions

Type: Location:
 Historic Front Rear
 Non-Historic Side Roof

Porch

Type: Material:
 Enclosed Porte Cochere Stone Wood
 Stoop Wraparound Brick Concrete
 Veranda Multi-Story

Significance: Location:
 Historic Altered Front Rear
 Side Balcony

Doors

Leaf: One-Leaf
 Material: Metal
 Significance: Arrangement: Type:
 Historic Sidelights Paneled w/Lights
 Replacement Transom Glazed

Windows

Type: Material: Significance:
 Double-Hung Steel Original Windows
 Sliding Wood Original Storms
 Casement Vinyl Replaced Windows
 Fixed Aluminum Replaced Storms

Roof

Type: Material: Dormers:
 Gable Mansard Asphalt Gable
 Hipped Shed Metal Hipped
 Jerkinhead Flat Slate Shed
 Gambrel Shake Jerkin
 Clay Tile

Chimney

Material: Brick Concrete Block Stone

NR ELIGIBILITY

Individual Eligibility
 District Eligibility:

District Name:

Belvidere Old Town NRHP District

Contributing:

Non-Contributing:

- Events (NR-A)
- Persons (NR-B)
- Architecture (NR-C)
- Archaeology (NR-D)

LOCAL ELIGIBILITY

Individual Eligibility:
 District Eligibility:

District Name:

Contributing:

Non-Contributing:

- Events 2
- Persons 3
- Architecture 4, 5, 6, 8
- Archaeology
- Other 1, 7, 9, 10, 11

Property Information

Address: 120 E Madison PIN:
 Building Names: Herrick and Wing Carriage Factory
 Important Dates: 1851 (date of construction)
 Historic Function: Carriage Factory
 Current Function: Apartments
 Color Code Criteria: Orange
 Outbuildings
 Number: 0 Any Significant:
 Architectural Style: Settlement
 Property Type: Residential
 Approximate Age: 1850-1859
 Condition: Fair
 Potential for Integrity?



Photo: 120_E_Madison_St_SURVEY_Photo.tif

Structure Information

Structure: Masonry
 Foundation: Stone Concrete Not Visible
 Brick Parged
 Cladding: Clapboard Asphalt
 Siding Stucco
 Shake Stone
 Board-and-Batten Brick
 Aluminum/Vinyl Concrete Block
 Asbestos Metal

Additions

Type: Historic Non-Historic
 Location: Front Rear
 Side Roof

Porch

Type: Enclosed Porte Cochere Stoop Veranda Multi-Story
 Stoop Wraparound
 Material: Stone Wood Brick Concrete
 Significance: Historic Altered
 Location: Front Rear
 Side Balcony

Doors

Leaf: One-Leaf
 Material: Metal
 Significance: Historic Replacement
 Arrangement: Sidelights Transom
 Type: Paneled Paneled w/Lights Glazed

Windows

Type: Double-Hung Sliding Casement Fixed
 Material: Steel Wood Vinyl Aluminum
 Significance: Original Windows Original Storms Replaced Windows Replaced Storms

Roof

Type: Gable Hipped Jerkinhead Gambrel
 Mansard Shed Flat
 Material: Asphalt Metal Slate Shake Clay Tile
 Dormers: Gable Hipped Shed Jerkin

Chimney

Material: Brick Concrete Block Stone

Description

The settlement era factory building, now remodeled as apartments, is three stories tall with rectangular massing and a flat roof. The main massing is four window bays wide by two window bays deep. A rear, two story section of the same width is two window bays deep with a flat roof. The building, constructed of limestone, has been parged with stucco, and short mansard roofs of clay tile line the main and rear roof parapets. Two brick chimney stacks are located on the east, with one brick stack and one vent on the west. The main entrance, located at grade on the south façade, is a single leaf, square topped, paneled door set into a shallow brick wall projecting from the main façade. A small, shortened window is set adjacent in the brick projection. Above, the projection is topped with a shallow, clay tile mansard porch roof. The replacement windows, arranged symmetrically on the front façade, are 1/1 double hungs with brick slip sills. At the east and west elevations, one of the two window bays have been altered to incorporate a shallow, projecting window bay. Just two stories tall, they have brick foundation walls with frame construction. Between the bay floors is a flared section decorated with scalloped shingles. The bay is topped with a shallow, clay tile mansard roof and decorative brackets.

NR ELIGIBILITY

Individual Eligibility:
 District Eligibility:
 District Name:
 Belvidere Old Town NRHP District
 Contributing:
 Non-Contributing:
 Events (NR-A)
 Persons (NR-B)
 Architecture (NR-C)
 Archaeology (NR-D)

LOCAL ELIGIBILITY

Individual Eligibility:
 District Eligibility:
 District Name:
 Contributing:
 Non-Contributing:
 Events 2
 Persons 3
 Architecture 4, 5, 6, 8
 Archaeology
 Other 1, 7, 9, 10, 11

Property Information

Address: 214 E Madison PIN: 05-26-282-006
 Building Names:
 Important Dates:
 Historic Function: Residence
 Current Function: Residence
 Color Code Criteria: Yellow
 Outbuildings
 Number: 1 Any Significant:
 Architectural Style: Settlement
 Property Type: Residential
 Approximate Age: 1850-1859
 Condition: Good
 Potential for Integrity?



Photo: 214_E_Madison_St_SURVEY_Photo.tif

Structure Information

Structure: Frame
 Foundation: Stone Concrete Not Visible
 Brick Parged
 Cladding: Clapboard Asphalt
 Siding Stucco
 Shake Stone
 Board-and-Batten Brick
 Aluminum/Vinyl Concrete Block
 Asbestos Metal

Additions

Type: Location:
 Historic Front Rear
 Non-Historic Side Roof

Porch

Type: Material:
 Enclosed Porte Cochere Stone Wood
 Stoop Wraparound Brick Concrete
 Veranda Multi-Story

Significance: Location:
 Historic Altered Front Rear
 Side Balcony

Doors

Leaf: One-Leaf
 Material: Wood
 Significance: Arrangement: Type:
 Historic Sidelights Paneled w/Lights
 Replacement Transom Glazed

Windows

Type: Material: Significance:
 Double-Hung Steel Original Windows
 Sliding Wood Original Storms
 Casement Vinyl Replaced Windows
 Fixed Aluminum Replaced Storms

Roof

Type: Material: Dormers:
 Gable Mansard Asphalt Gable
 Hipped Shed Metal Hipped
 Jerkinhead Flat Slate Shed
 Gambrel Shake Jerkin
 Clay Tile

Chimney

Material: Brick Concrete Block Stone

Description

The single-family home is one-and-one-half stories tall with a front-gabled roof and a rectangular plan spanning three bays wide and deep. The first floor is raised on a rough-cut limestone foundation, the walls are clad in siding, and a brick chimney is located at the west wall. The front façade, facing south, is symmetrical with window bays flanking a centered one story enclosed entry porch with two windows centered above. The Victorian era front porch is set at a low concrete stoop with a short mansard roof and a bracketed cornice. Windows are set in the sided walls, and the front door is not original. Another longer side porch of the same construction and detailing is located at the east elevation. A window bay at the northeast corner has been partially incorporated into this enclosed side porch. At the northwest corner there is a concrete stoop at side porch with a flat roof supported by square wood posts. On the rear elevation there is a full-width one story wing clad in siding with a low gabled roof. All the original windows have been replaced with 1/1 double-hungs. Set back at the northwest corner of the lot is a three-car gabled garage clad in siding and a small gabled shed. The size and configuration suggest...

NR ELIGIBILITY

Individual Eligibility:
 District Eligibility:
 District Name:
 Belvidere Old Town NRHP District
 Contributing:
 Non-Contributing:
 Events (NR-A)
 Persons (NR-B)
 Architecture (NR-C)
 Archaeology (NR-D)

LOCAL ELIGIBILITY

Individual Eligibility:
 District Eligibility:
 District Name:
 Contributing:
 Non-Contributing:
 Events 2
 Persons 3
 Architecture 4, 5, 6, 8
 Archaeology
 Other 1, 7, 9, 10, 11

Property Information

Address: 309 E Madison PIN: 05-26-288-002
 Building Names:
 Important Dates:
 Historic Function: Residence
 Current Function: Apartments
 Color Code Criteria: Yellow
 Outbuildings
 Number: 0 Any Significant:
 Architectural Style: Greek Revival
 Property Type: Residential
 Approximate Age: 1860-1869
 Condition: Poor
 Potential for Integrity?



Photo: 309_E_Madison_St_SURVEY_Photo.tif

Structure Information

Structure: Frame
 Foundation: Stone Concrete Not Visible
 Brick Parged
 Cladding: Clapboard Asphalt
 Siding Stucco
 Shake Stone
 Board-and-Batten Brick
 Aluminum/Vinyl Concrete Block
 Asbestos Metal

Additions

Type: Location:
 Historic Front Rear
 Non-Historic Side Roof

Porch

Type: Material:
 Enclosed Porte Cochere Stone Wood
 Stoop Wraparound Brick Concrete
 Veranda Multi-Story

Significance: Location:
 Historic Altered Front Rear
 Side Balcony

Doors

Leaf: One-Leaf
 Material: Wood
 Significance: Arrangement: Type:
 Historic Sidelights Paneled
 Replacement Transom Paneled w/Lights
 Glazed

Windows

Type: Material: Significance:
 Double-Hung Steel Original Windows
 Sliding Wood Original Storms
 Casement Vinyl Replaced Windows
 Fixed Aluminum Replaced Storms

Roof

Type: Material: Dormers:
 Gable Mansard Asphalt Gable
 Hipped Shed Metal Hipped
 Jerkinhead Flat Slate Shed
 Gambrel Clay Tile Shake Jerkin

Chimney

Material: Brick Concrete Block Stone

Description

The single-family home is two stories tall with upright and wing massing and a "T" shaped plan. The front-gabled massing spans two bays wide and deep, and the side gabled wing spans three bays wide by one bay deep. The first floor set on a low limestone foundation, the walls are clad in siding, and a brick chimney is located on center in the wing. The front gable, facing north, has remnants of a short cornice return. A Chicago style window at the first floor and two 1/1 double-hung windows at the second floor on centered on the gable. A one story enclosed entry porch is situated on a concrete slab at the wing's north elevation. Its shed roof is accented with a gable over the doorway, and the walls are clad in plywood and lined with double-hung windows. The three window bays are unevenly spaced, and the second floor windows are 2/2 wood double-hungs. At the side gable elevation, there is a single off-center window at the first floor and a pair of centered windows at the second floor. Several of the original windows have been replaced with 1/1 double-hungs and the windows have simple wood frames. The size and configuration suggest that this is a settlement dwelling with Greek Revival detailing. The remaining...

NR ELIGIBILITY

Individual Eligibility:
 District Eligibility:
 District Name:
 Belvidere Old Town NRHP District
 Contributing:
 Non-Contributing:
 Events (NR-A)
 Persons (NR-B)
 Architecture (NR-C)
 Archaeology (NR-D)

LOCAL ELIGIBILITY

Individual Eligibility:
 District Eligibility:
 District Name:
 Contributing:
 Non-Contributing:
 Events 2
 Persons 3
 Architecture 4, 5, 6, 8
 Archaeology
 Other 1, 7, 9, 10, 11

Property Information

Address: 315 E Madison PIN: 05-26-288-004
 Building Names:
 Important Dates:
 Historic Function: Residence
 Current Function: Residence
 Color Code Criteria: Yellow
 Outbuildings
 Number: 1 Any Significant:
 Architectural Style: Queen Anne
 Property Type: Residential
 Approximate Age: 1880-1889
 Condition: Fair
 Potential for Integrity?



Photo: 315_E_Madison_St_SURVEY_Photo.tif

Structure Information

Structure: Frame
 Foundation: Stone Concrete Not Visible
 Brick Parged
 Cladding: Clapboard Asphalt
 Siding Stucco
 Shake Stone
 Board-and-Batten Brick
 Aluminum/Vinyl Concrete Block
 Asbestos Metal

Additions

Type: Location:
 Historic Front Rear
 Non-Historic Side Roof

Porch

Type: Material:
 Enclosed Porte Cochere Stone Wood
 Stoop Wraparound Brick Concrete
 Veranda Multi-Story

Significance: Location:
 Historic Altered Front Rear
 Side Balcony

Doors

Leaf: One-Leaf
 Material: Wood
 Significance: Arrangement: Type:
 Historic Sidelights Paneled
 Replacement Transom Paneled w/Lights
 Glazed

Windows

Type: Material: Significance:
 Double-Hung Steel Original Windows
 Sliding Wood Original Storms
 Casement Vinyl Replaced Windows
 Fixed Aluminum Replaced Storms

Roof

Type: Material: Dormers:
 Gable Mansard Asphalt Gable
 Hipped Shed Metal Hipped
 Jerkinhead Flat Slate Shed
 Gambrel Clay Tile Shake Jerkin

Chimney

Material: Brick Concrete Block Stone

Description

The Queen Anne, single-family frame house is two stories with a steeply pitched roof and cross-gabled massing with an "L" shaped plan. The first floor is raised on a parged masonry foundation and the exterior is clad in siding. At the primary elevation, facing north, the front gable section has centered window openings with a cantilevered window bay at the first floor. The bay is bracketed with a shingled spandrel, a bracketed cornice and a short hipped roof. A pair of double-hung windows is centered above with a decorated wood frame. Two evenly spaced double-hung windows are located at the first floor on the west elevation. The gabled ell extends to the east and the main entry is placed to one side on the north elevation. This section has various window types, including pairs of short windows at the eaves. The main entrance is a gabled, enclosed vestibule that projects out at a concrete stoop. Typical windows are single or paired, 1/1 double-hungs with rectangular sash and plain wood framing. Many of these windows have been replaced. At the southwest corner of the lot there is a gabled two-car garage clad in siding with vertical siding in the gable end. The massing and remaining elements suggest a Queen Anne style. However, the...

NR ELIGIBILITY

Individual Eligibility
 District Eligibility:
 District Name:
 Belvidere Old Town NRHP District
 Contributing:
 Non-Contributing:

- Events (NR-A)
- Persons (NR-B)
- Architecture (NR-C)
- Archaeology (NR-D)

LOCAL ELIGIBILITY

Individual Eligibility:
 District Eligibility:
 District Name:
 Contributing:
 Non-Contributing:

- Events 2
- Persons 3
- Architecture 4, 5, 6, 8
- Archaeology
- Other 1, 7, 9, 10, 11

**Belvidere Historic Resources Inventory:
Courthouse Square Area**

No. 122
Survey Date: 4/12/2014

Property Information

Address: 321 E Madison PIN: 05-26-288-004
 Building Names: Henry Haywood Residence
 Important Dates:
 Historic Function: Residence
 Current Function: Residence
 Color Code Criteria: Red
 Outbuildings
 Number: 1 Any Significant:
 Architectural Style: Queen Anne
 Property Type: Residential
 Approximate Age: 1890-1899
 Condition: Good
 Potential for Integrity?



Photo: 321_E_Madison_St_SURVEY_Photo.tif

Description

The Queen Anne, single-family frame house is two-and-one-half stories with a steeply pitched roof and cross-gabled massing. The first floor is raised on a foundation of dressed, rusticated limestone, the exterior is clad in wood clapboard and two brick chimney stacks are centrally located. At the primary elevation, facing north, a gable-front section, with centered window openings, projects slightly beyond the hipped roof section. The east/west cross gables extend one window bay beyond the main hipped roof massing. A pair of paneled and lited entry doors is situated at the northwest corner under a wood porch that wraps around the north and east sides. The porch is raised on rock-faced blocks, mimicking the main foundation, and extends out as knee walls along the porch steps. Its shed roof, with triangular pediments over the north and east entrances, is supported by slender turned colonnettes. Set as singles or in groups, they rest on paneled, boxy pedestals. Currently, there is no railing installed, though the porch appears to be under repair. The east elevation gable end has a two story canted window bay accentuated with corner bracketing and decoration. At the bay's first floor, there is a single leaf side entrance door. The attic level gables are enclosed with pent roofs and...

Structure Information

Structure: Frame
 Foundation: Stone Concrete Not Visible
 Brick Parged
 Cladding: Clapboard Asphalt
 Siding Stucco
 Shake Stone
 Board-and-Batten Brick
 Aluminum/Vinyl Concrete Block
 Asbestos Metal

Additions

Type: Location:
 Historic Front Rear
 Non-Historic Side Roof

Porch

Type: Material:
 Enclosed Porte Cochere Stone Wood
 Stoop Wraparound Brick Concrete
 Veranda Multi-Story

Significance: Location:
 Historic Altered Front Rear
 Side Balcony

Doors

Leaf: Two-Leaf
 Material: Wood Type:
 Significance: Arrangement: Paneled
 Historic Sidelights Paneled w/Lights
 Replacement Transom Glazed

Windows

Type: Material: Significance:
 Double-Hung Steel Original Windows
 Sliding Wood Original Storms
 Casement Vinyl Replaced Windows
 Fixed Aluminum Replaced Storms

Roof

Type: Material: Dormers:
 Gable Mansard Asphalt Gable
 Hipped Shed Metal Hipped
 Jerkinhead Flat Slate Shed
 Gambrel Shake Jerkin
 Clay Tile

Chimney

Material: Brick Concrete Block Stone

NR ELIGIBILITY

Individual Eligibility

District Eligibility:

District Name:

Belvidere Old Town NRHP District

Contributing:

Non-Contributing:

- Events (NR-A)
- Persons (NR-B)
- Architecture (NR-C)
- Archaeology (NR-D)

LOCAL ELIGIBILITY

Individual Eligibility:

District Eligibility:

District Name:

Contributing:

Non-Contributing:

- Events 2
- Persons 3
- Architecture 4, 5, 6, 8
- Archaeology
- Other 1, 7, 9, 10, 11

Property Information

Address: 401 E Madison PIN: 05-26-289-001
 Building Names:
 Important Dates:
 Historic Function: Residence
 Current Function: Apartments
 Color Code Criteria: None
 Outbuildings
 Number: 1 Any Significant:
 Architectural Style: Queen Anne
 Property Type: Residential
 Approximate Age: 1910-1919
 Condition: Good
 Potential for Integrity?



Photo: 401_E_Madison_St_SURVEY_Photo.tif

Description

The Queen Anne, multi-unit frame house is two stories with a steeply pitched roof and cross-gabled massing with an "L" shaped plan. The first floor is raised on a parged limestone foundation, the exterior is clad in siding and a brick chimney is located at the south end wall. The street elevation is the side of the house, with the formal front facing west. At the west gable there are evenly spaced window openings with a partially enclosed porch at the first floor. The porch's hipped roof is supported by colonnettes set on a high rock-faced concrete wall. The entrance door is replaced. At the street elevation, the added entrance door is centered and flanked by two windows to the sides and above. A small braced canopy was added over the door. All the original windows have been replaced with 2 lite sliders or 1/1 double-hungs. A small one story gabled addition was added at the east elevation. At the east edge of the lot there is a one car gabled garage clad in siding. The massing suggests a Queen Anne style. However, there have been significant alterations made to the structure which severely compromise its integrity.

Structure Information

Structure: Frame
 Foundation: Stone Concrete Not Visible
 Brick Parged
 Cladding: Clapboard Asphalt
 Siding Stucco
 Shake Stone
 Board-and-Batten Brick
 Aluminum/Vinyl Concrete Block
 Asbestos Metal

Additions

Type: Location:
 Historic Front Rear
 Non-Historic Side Roof

Porch

Type: Material:
 Enclosed Porte Cochere Stone Wood
 Stoop Wraparound Brick Concrete
 Veranda Multi-Story

Significance: Location:
 Historic Altered Front Rear
 Side Balcony

Doors

Leaf: One-Leaf
 Material: Metal Type:
 Significance: Arrangement: Paneled
 Historic Sidelights Paneled w/Lights
 Replacement Transom Glazed

Windows

Type: Material: Significance:
 Double-Hung Steel Original Windows
 Sliding Wood Original Storms
 Casement Vinyl Replaced Windows
 Fixed Aluminum Replaced Storms

Roof

Type: Material: Dormers:
 Gable Mansard Asphalt Gable
 Hipped Shed Metal Hipped
 Jerkinhead Flat Slate Shed
 Gambrel Shake Jerkin
 Clay Tile

Chimney

Material: Brick Concrete Block Stone

NR ELIGIBILITY

Individual Eligibility
 District Eligibility:
 District Name:

Contributing:
 Non-Contributing:

- Events (NR-A)
- Persons (NR-B)
- Architecture (NR-C)
- Archaeology (NR-D)

LOCAL ELIGIBILITY

Individual Eligibility:
 District Eligibility:
 District Name:

Contributing:
 Non-Contributing:

- Events 2
- Persons 3
- Architecture 4, 5, 6, 8
- Archaeology
- Other 1, 7, 9, 10, 11

Property Information

Address: 403 E Madison PIN: 05-26-289-002
 Building Names:
 Important Dates:
 Historic Function: Residence
 Current Function: Residence
 Color Code Criteria: Yellow
 Outbuildings
 Number: 1 Any Significant:
 Architectural Style: Queen Anne
 Property Type: Residential
 Approximate Age: 1890-1899
 Condition: Good
 Potential for Integrity?



Photo: 403_E_Madison_St_SURVEY_Photo.tif

Structure Information

Structure: Frame
 Foundation: Stone Concrete Not Visible
 Brick Parged
 Cladding: Clapboard Asphalt
 Siding Stucco
 Shake Stone
 Board-and-Batten Brick
 Aluminum/Vinyl Concrete Block
 Asbestos Metal

Additions

Type: Location:
 Historic Front Rear
 Non-Historic Side Roof

Porch

Type: Material:
 Enclosed Porte Cochere Stone Wood
 Stoop Wraparound Brick Concrete
 Veranda Multi-Story
 Significance: Location:
 Historic Altered Front Rear
 Side Balcony

Doors

Leaf: One-Leaf
 Material: Type:
 Significance: Arrangement: Paneled
 Historic Sidelights Paneled w/Lights
 Replacement Transom Glazed

Windows

Type: Material: Significance:
 Double-Hung Steel Original Windows
 Sliding Wood Original Storms
 Casement Vinyl Replaced Windows
 Fixed Aluminum Replaced Storms

Roof

Type: Material: Dormers:
 Gable Mansard Asphalt Gable
 Hipped Shed Metal Hipped
 Jerkinhead Flat Slate Shed
 Gambrel Shake Jerkin
 Clay Tile

Chimney

Material: Brick Concrete Block Stone

Description

The Queen Anne, single-family frame house is two stories with a steeply pitched roof and cross-gabled massing with an "L" shaped plan. The first floor is raised on a parged limestone foundation, the exterior is clad in siding, and an internal brick chimney is centrally located on the front gable. At the primary elevation, facing north, the front gable section has two centered window bays. The one-and-one-half gabled ell extends to the west with a concrete slab stoop and hipped roof canopy are set at the ell's inside corner. Here the main entry is placed on the northwest corner of the front gable massing. The entry door has been replaced. The north elevation of the ell has been clad in vertical siding and a group of three 1/1 double-hung windows has been added at the first floor. The ell's gable end has evenly spaced windows. A small shed roof enclosure clad in vertical boards was added at the rear southwest corner. Typical windows are single 1/1 double-hungs with rectangular sash and plain wood framing that has been partially clad. Many of these windows have been replaced. At the southwest corner of the lot there is a gabled one-car garage clad in siding with cornice and corner boards. The massing and feature configuration...

NR ELIGIBILITY

Individual Eligibility:
 District Eligibility:
 District Name:
 Belvidere Old Town NRHP District
 Contributing:
 Non-Contributing:
 Events (NR-A)
 Persons (NR-B)
 Architecture (NR-C)
 Archaeology (NR-D)

LOCAL ELIGIBILITY

Individual Eligibility:
 District Eligibility:
 District Name:
 Contributing:
 Non-Contributing:
 Events 2
 Persons 3
 Architecture 4, 5, 6, 8
 Archaeology
 Other 1, 7, 9, 10, 11

Property Information

Address: 404 E Madison PIN: 05-26-284-007
 Building Names:
 Important Dates:
 Historic Function: Residence
 Current Function: Residence
 Color Code Criteria: Yellow
 Outbuildings
 Number: 0 Any Significant:
 Architectural Style: Queen Anne
 Property Type: Residential
 Approximate Age: 1890-1899
 Condition: Good/Excellent
 Potential for Integrity?



Photo: 404_E_Madison_St_SURVEY_Photo.tif

Description

The Queen Anne, single-family frame house is two-and-one-half stories with a steeply pitched hipped roof and cross-gabled massing. The first floor is raised on a foundation of coursed rock-faced limestone and the exterior is clad in siding. At the primary elevation, facing south, there is a gable-front section with centered window openings and a full width front porch. The front has a rock-faced concrete block base and knee walls with a hipped roof. Squat turned columns sit on concrete block pedestals and additional blocks are also used as a baluster. The main entry is placed at the southwest corner, and the double-front doors are not original. Directly adjacent is a large landscape window with a multi-lite Queen Anne transom. The west elevation gable end is canted and the windows are centered with a large landscape window and transom at each floor. A small double-hung attic sash is placed high in the gable end. The east gable has centered pairs of windows placement and several other openings have decorative Queen Anne sashes. A one-and-one-half story gabled wing is located at the rear elevation. Typical windows are single, tall, 1/1 double-hungs with rectangular sash. Many of the original windows remain, but the frames...

Structure Information

Structure: Frame
 Foundation: Stone Concrete Not Visible
 Brick Parged
 Cladding: Clapboard Asphalt
 Siding Stucco
 Shake Stone
 Board-and-Batten Brick
 Aluminum/Vinyl Concrete Block
 Asbestos Metal

Additions

Type: Location:
 Historic Front Rear
 Non-Historic Side Roof

Porch

Type: Material:
 Enclosed Porte Cochere Stone Wood
 Stoop Wraparound Brick Concrete
 Veranda Multi-Story

Significance: Location:
 Historic Altered Front Rear
 Side Balcony

Doors

Leaf: Two-Leaf
 Material: Wood
 Significance: Arrangement: Type:
 Historic Sidelights Paneled
 Replacement Transom Paneled w/Lights
 Glazed

Windows

Type: Material: Significance:
 Double-Hung Steel Original Windows
 Sliding Wood Original Storms
 Casement Vinyl Replaced Windows
 Fixed Aluminum Replaced Storms

Roof

Type: Material: Dormers:
 Gable Mansard Asphalt Gable
 Hipped Shed Metal Hipped
 Jerkinhead Flat Slate Shed
 Gambrel Shake Jerkin
 Clay Tile

Chimney

Material: Brick Concrete Block Stone

NR ELIGIBILITY

Individual Eligibility
 District Eligibility:

District Name:
 Belvidere Old Town NRHP District

Contributing:
 Non-Contributing:

- Events (NR-A)
- Persons (NR-B)
- Architecture (NR-C)
- Archaeology (NR-D)

LOCAL ELIGIBILITY

Individual Eligibility:
 District Eligibility:

District Name:

Contributing:
 Non-Contributing:

- Events 2
- Persons 3
- Architecture 4, 5, 6, 8
- Archaeology
- Other 1, 7, 9, 10, 11

Property Information

Address: 410 E Madison PIN: 05-26-284-008
 Building Names:
 Important Dates:
 Historic Function: Residence
 Current Function: Residence
 Color Code Criteria: Yellow
 Outbuildings
 Number: 1 Any Significant:
 Architectural Style: Queen Anne
 Property Type: Residential
 Approximate Age: 1880-1889
 Condition: Good/Excellent
 Potential for Integrity?



Photo: 410_E_Madison_St_SURVEY_Photo.tif

Description

The Queen Anne, single-family frame house is two-and-one-half stories with a steeply pitched cross-gabled roof. The first floor is raised on a parged masonry foundation, the exterior is clad in asbestos siding, and a brick chimney is located at the west elevation. At the primary elevation, facing south, there is a gable-front section with centered window openings and a one-story front porch to the east side. The front gable has a bowed first and second floor with a bracketed, closed gable above. A large picture window with transom is at the first floor, two 1/1 double-hung windows are at the second floor and a small 1-lite window is placed at the attic level. The wood side porch has turned posts with decorative corner brackets and a flared, front gabled roof. The main front gable roof extends down to merge with the porch roof. The main entrance is obstructed by the screened front porch. The east and west elevation gable windows are typically centered. A one-and-one-half story gabled wing is located at the rear elevation and a recessed porch and the half walls have turned column supports. Typical windows are single, tall, 1/1 double-hungs with rectangular sash, many of which have been replaced. The frames have been clad and small...

Structure Information

Structure: Frame
 Foundation: Stone Concrete Not Visible
 Brick Parged
 Cladding: Clapboard Asphalt
 Siding Stucco
 Shake Stone
 Board-and-Batten Brick
 Aluminum/Vinyl Concrete Block
 Asbestos Metal

Additions

Type: Location:
 Historic Front Rear
 Non-Historic Side Roof

Porch

Type: Material:
 Enclosed Porte Cochere Stone Wood
 Stoop Wraparound Brick Concrete
 Veranda Multi-Story

Significance: Location:
 Historic Altered Front Rear
 Side Balcony

Doors

Leaf: One-Leaf
 Material: Wood
 Significance: Arrangement: Type:
 Historic Sidelights Paneled
 Replacement Transom Paneled w/Lights
 Glazed

Windows

Type: Material: Significance:
 Double-Hung Steel Original Windows
 Sliding Wood Original Storms
 Casement Vinyl Replaced Windows
 Fixed Aluminum Replaced Storms

Roof

Type: Material: Dormers:
 Gable Mansard Asphalt Gable
 Hipped Shed Metal Hipped
 Jerkinhead Flat Slate Shed
 Gambrel Shake Jerkin
 Clay Tile

Chimney

Material: Brick Concrete Block Stone

NR ELIGIBILITY

Individual Eligibility

District Eligibility:

District Name:

Belvidere Old Town NRHP District

Contributing:

Non-Contributing:

- Events (NR-A)
- Persons (NR-B)
- Architecture (NR-C)
- Archaeology (NR-D)

LOCAL ELIGIBILITY

Individual Eligibility:

District Eligibility:

District Name:

Contributing:

Non-Contributing:

- Events 2
- Persons 3
- Architecture 4, 5, 6, 8
- Archaeology
- Other 1, 7, 9, 10, 11

Property Information

Address: 414 E Madison PIN: 05-26-284-009
 Building Names:
 Important Dates:
 Historic Function: Residence
 Current Function: Residence
 Color Code Criteria: Yellow
 Outbuildings
 Number: 0 Any Significant:
 Architectural Style: Queen Anne
 Property Type: Residential
 Approximate Age: 1900-1909
 Condition: Good
 Potential for Integrity?



Photo: 414_E_Madison_St_SURVEY_Photo.tif

Description

The Queen Anne, single-family frame house is two-and-one-half stories with a steeply pitched hipped roof with lower cross gables and a prominent gabled wall dormer. The first floor is raised on a coursed rock-faced limestone foundation and the exterior is clad in siding. At the primary elevation, facing south, has an overhanging second floor with brackets and a one story full-width front porch. The short mansard roof is supported with square wood posts and has a simple wood railing and enclosed base. The original entrance door is paneled with a half lite. Two windows at the porch have decorative Queen Anne diamond-lite transoms with their lower sash replaced. Above the porch, a pair of windows is centered on the large front gabled dormer. The window pair is framed in simplified pilasters and topped with a half-round lunette and keystone. The dormer takes on the form of a pediment with short pented returns at the eaves. The east and west cross gables are closed at the third floor with a pent roof and the first floor at the west gable is canted with decorative brackets. Windows are placed symmetrically on the overall asymmetrical elements. Additional porches are found at the east and rear elevations. The single, tall, double-hung 1/1...

Structure Information

Structure: Frame
 Foundation: Stone Concrete Not Visible
 Brick Parged
 Cladding: Clapboard Asphalt
 Siding Stucco
 Shake Stone
 Board-and-Batten Brick
 Aluminum/Vinyl Concrete Block
 Asbestos Metal

Additions

Type: Location:
 Historic Front Rear
 Non-Historic Side Roof

Porch

Type: Material:
 Enclosed Porte Cochere Stone Wood
 Stoop Wraparound Brick Concrete
 Veranda Multi-Story

Significance: Location:
 Historic Altered Front Rear
 Side Balcony

Doors

Leaf: One-Leaf
 Material: Wood
 Significance: Arrangement: Type:
 Historic Sidelights Paneled w/Lights
 Replacement Transom Glazed

Windows

Type: Material: Significance:
 Double-Hung Steel Original Windows
 Sliding Wood Original Storms
 Casement Vinyl Replaced Windows
 Fixed Aluminum Replaced Storms

Roof

Type: Material: Dormers:
 Gable Mansard Asphalt Gable
 Hipped Shed Metal Hipped
 Jerkinhead Flat Slate Shed
 Gambrel Shake Jerkin
 Clay Tile

Chimney

Material: Brick Concrete Block Stone

NR ELIGIBILITY

Individual Eligibility
 District Eligibility:

District Name:
 Belvidere Old Town NRHP District

Contributing:
 Non-Contributing:

- Events (NR-A)
- Persons (NR-B)
- Architecture (NR-C)
- Archaeology (NR-D)

LOCAL ELIGIBILITY

Individual Eligibility:
 District Eligibility:

District Name:

Contributing:
 Non-Contributing:

- Events 2
- Persons 3
- Architecture 4, 5, 6, 8
- Archaeology
- Other 1, 7, 9, 10, 11

Property Information

Address: 415 E Madison PIN: 05-26-289-003
 Building Names:
 Important Dates:
 Historic Function: Residence
 Current Function: Residence
 Color Code Criteria: Yellow
 Outbuildings
 Number: 1 Any Significant:
 Architectural Style: Queen Anne
 Property Type: Residential
 Approximate Age: 1900-1909
 Condition: Good
 Potential for Integrity?



Photo: 415_E_Madison_St_SURVEY_Photo.tif

Structure Information

Structure: Frame
 Foundation: Stone Concrete Not Visible
 Brick Parged
 Cladding: Clapboard Asphalt
 Siding Stucco
 Shake Stone
 Board-and-Batten Brick
 Aluminum/Vinyl Concrete Block
 Asbestos Metal

Additions

Type: Location:
 Historic Front Rear
 Non-Historic Side Roof

Porch

Type: Material:
 Enclosed Porte Cochere Stone Wood
 Stoop Wraparound Brick Concrete
 Veranda Multi-Story
 Significance: Location:
 Historic Altered Front Rear
 Side Balcony

Doors

Leaf: One-Leaf
 Material: Wood
 Significance: Arrangement: Type:
 Historic Sidelights Paneled w/Lights
 Replacement Transom Glazed

Windows

Type: Material: Significance:
 Double-Hung Steel Original Windows
 Sliding Wood Original Storms
 Casement Vinyl Replaced Windows
 Fixed Aluminum Replaced Storms

Roof

Type: Material: Dormers:
 Gable Mansard Asphalt Gable
 Hipped Shed Metal Hipped
 Jerkinhead Flat Slate Shed
 Gambrel Shake Jerkin
 Clay Tile

Chimney

Material: Brick Concrete Block Stone

Description

The Queen Anne, single-family frame house is two stories with a steeply pitched cross-gabled roof. The first floor is raised on a parged limestone foundation, the exterior is clad in siding, and a brick chimney is centrally located. At the primary elevation, facing north, there is a gable-front section with centered window openings and a one-story front porch to the east side. A large 1/1 double-hung window is at the first floor, with a smaller 1/1 double-hung window at the second floor. The front porch is enclosed and lined with double-hung windows. It has a concrete block base punctured with small rectangular 1-lite windows and a flared, front gabled roof. The main front gable roof extends down to merge with the porch roof. The main entrance is obstructed by the front porch, which is accessed from the east side at a small concrete stoop. The east and west elevation gable windows are typically centered. A one story gabled wing is located at the rear elevation. Typical windows are single, tall, 1/1 double-hungs with rectangular sash, many of which have been replaced. Surviving details suggest that this house is a folk Victorian sub-type of the Queen Anne style, though many decorative elements have been altered.

NR ELIGIBILITY

Individual Eligibility
 District Eligibility:

District Name:

Belvidere Old Town NRHP District

Contributing:
 Non-Contributing:

- Events (NR-A)
- Persons (NR-B)
- Architecture (NR-C)
- Archaeology (NR-D)

LOCAL ELIGIBILITY

Individual Eligibility:
 District Eligibility:

District Name:

Contributing:
 Non-Contributing:

- Events 2
- Persons 3
- Architecture 4, 5, 6, 8
- Archaeology
- Other 1, 7, 9, 10, 11

Property Information

Address: 420 E Madison PIN: 05-26-284-010
 Building Names:
 Important Dates:
 Historic Function: Residence
 Current Function: Residence
 Color Code Criteria: Red
 Outbuildings
 Number: 0 Any Significant:
 Architectural Style: Lustron
 Property Type: Residential
 Approximate Age: 1940-1949
 Condition: Good
 Potential for Integrity?



Photo: 420_E_Madison_St_SURVEY_Photo.tif

Structure Information

Structure: Metal (Lustron)
 Foundation: Stone Concrete Not Visible
 Brick Parged
 Cladding: Clapboard Asphalt
 Siding Stucco
 Shake Stone
 Board-and-Batten Brick
 Aluminum/Vinyl Concrete Block
 Asbestos Metal

Additions

Type: Location:
 Historic Front Rear
 Non-Historic Side Roof

Porch

Type: Material:
 Enclosed Porte Cochere Stone Wood
 Stoop Wraparound Brick Concrete
 Veranda Multi-Story

Significance: Location:
 Historic Altered Front Rear
 Side Balcony

Doors

Leaf: One-Leaf
 Material: Wood
 Significance: Arrangement: Type:
 Historic Sidelights Paneled w/Lights
 Replacement Transom Glazed

Windows

Type: Material: Significance:
 Double-Hung Steel Original Windows
 Sliding Wood Original Storms
 Casement Vinyl Replaced Windows
 Fixed Aluminum Replaced Storms

Roof

Type: Material: Dormers:
 Gable Mansard Asphalt Gable
 Hipped Shed Metal Hipped
 Jerkinhead Flat Slate Shed
 Gambrel Shake Jerkin
 Clay Tile

Chimney

Material: Brick Concrete Block Stone

Description

This Lustron, single-family home is one story tall with a low-pitched, side-gabled main section with rectangular massing and central chimney stack. Extending out to form an overall L-shaped arrangement is a shed roofed hyphen and a front gabled garage, all constructed of "Desert Tan" colored Lustron. It has a concrete foundation with rectangular porcelain-enameled wall panels. The gable ends, projecting to form shallow eaves, are clad in vertical porcelain-enameled panels. The shingle-style roof tiles, gutters and eaves are also porcelain-enameled. The main entrance, a single leaf lighted door, is recessed at the southwest corner with one simple "zig-zag" metal support. The main façade, facing south, has two large metal window assemblies, each composed of a large picture window flanked by 4-lite casements. The centered window grouping is set in a shallow projecting bay of ivory colored enameled tile. This signature feature was only available on the "Westchester Deluxe" Lustron model. The three-window grouping also appears next to the entrance on the west façade. Along the east façade, two pairs of 3-lite metal casements are placed symmetrically. The window headers are accentuated with a simple rolled panel. At the north façade, a one story enclosed porch with rear...

NR ELIGIBILITY

Individual Eligibility
 District Eligibility:

District Name:

Belvidere Old Town NRHP District

Contributing:
 Non-Contributing:

- Events (NR-A)
- Persons (NR-B)
- Architecture (NR-C)
- Archaeology (NR-D)

LOCAL ELIGIBILITY

Individual Eligibility:
 District Eligibility:

District Name:

Contributing:
 Non-Contributing:

- Events 2
- Persons 3
- Architecture 4, 5, 6, 8
- Archaeology
- Other 1, 7, 9, 10, 11