**Courthouse Square Area** 

**Property Information** Address: 421 E Madison PIN: 05-26-289-004 **Building Names:** Important Dates: Historic Function: Residence Current Function: Residence Color Code Criteria: Yellow Outbuildings Number: 2 Any Significant: Architectural Style: Greek Revival Property Type: Residential

Approximate Age: 1860-1869  Condition: Fair
Potential for Integrity?
Structure Information
Structure: Frame
Foundation: Stone Concrete Not Visible  Brick Parged
Cladding: Clapboard Asphalt Siding Stucco Shake Stone Board-and-Batten Brick Aluminum/Vinyl Concrete Block Asbestos Metal
Additions
Type: Location:
☐ Historic ☐ Front ☐ Rear ☐ Non-Historic ☐ Side ☐ Roof
Porch Type: Material:
☐ Enclosed ☐ Porte Cochere ☐ Stone ☐ Wood ☐ Brick ☐ Concrete ☐ Veranda ☐ Multi-Story
Significance: Location: ☐ Front ☐ Rear
Doors ⊠ Side ☐ Balcony
Leaf: One-Leaf  Material: Wood Type:
Material: Wood Type: Significance: Arrangement: Paneled
Historic Sidelights Paneled w/Lights
Replacement Transom Glazed
Windows
Type: Material: Significance:
Double-Hung ☐ Steel ☐ Original Windows
☐ Sliding ☐ Wood ☐ Original Storms
Casement Vinyl Replaced Windows
Fixed Aluminum Replaced Storms
Roof Type: Material: Dormers:
☐ Gable ☐ Mansard ☐ Asphalt ☐ Gable
Hipped Shed Metal Hipped
☐ Jerkinhead ☐ Flat ☐ Slate ☐ Shed
Gambrel Shake Jerkin
Chimney Clay Tile
Material: Rrick Concrete Block Stone



130

No.

Photo: 421\_E\_Madison\_St\_SURVEY\_Photo.tif Description

The multi-unit frame house is one-and-one-half stories with upright and wing massing, "T" shaped plan and a gabled addition. The street elevation is the side of the house, with the formal front elevation facing east. The front gabled plan spans two bays wide by four bays deep. The first floor is set on a parged masonry foundation and the walls are clad in siding. An internal brick chimney is located on center at the roof junction. The upright façade, facing east, is symmetrical with two windows at the first floor and a pair of windows in the gable. The arrangement is repeated at the west gable end wall. Along the north elevation are two irregularly spaced single-leaf entrance doors, two pairs of windows and two small eave windows. The wing is three bays wide by two bays deep. At the northeast inside corner, a single-leaf door has been replaced and is located at a low concrete stoop. Over the door there is a short mansard porch canopy supported by an elaborately turned bracket. Many of the windows have been replaced, with some 6/1 double -hung wood windows remaining at the northwest corner. On the rear elevation there is a one story gabled addition that is possibly an original kitchen wing. Set at the south...

NR ELIGIBILITY Individual Eligibility District Eligibility:	LOCAL ELIGIBILITY Individual Eligibility: District Eligibility:
Belvidere Old Town NRHP District	
Contributing:	Contributing:
Non-Contributing:  Events (NR-A)  Persons (NR-B)  Architecture (NR-C)  Archaeology (NR-D)	Non-Contributing:  Events 2  Persons 3  Architecture 4, 5, 6, 8  Archaeology

Property information	
Address: 114 E Perry	PIN: 05-26-280-006
Building Names:	
Important Dates:	
Historic Function: Residence	
Current Function: Residence	
Color Code Criteria: None	
Outbuildings	
	gnificant:
Architectural Style: Queen Anne	-
	<b>3</b>
Property Type: Residential	
Approximate Age: 1890-1899	
Condition: Good	
Potential for Integrity?	
Structure Information	
Structure: Frame	
	Al-+\/iaibla
	rete  Not Visible
☐ Brick ☒ Parge	ed
Cladding: Clapboard	Asphalt
Siding	Stucco
Shake	Stone
_	
☐ Board-and-Batten	Brick
☐ Aluminum/Vinyl	Concrete Block
☐ Asbestos	☐ Metal
Additions	
Type: Location	
☐ Historic ⊠ Front	t 🗌 Rear
⊠ Non-Historic	Roof
Barah	
Porch Type:	
Type:	Material:
Type:  Enclosed Porte Coche	Material:
Type:  Enclosed Porte Coche Stoop Wraparound	Material:
Type:  Enclosed Porte Coche	Material:
Type:  Enclosed Porte Coche Stoop Wraparound Veranda Multi-Story	Material:
Type:  Enclosed Porte Coche Stoop Wraparound Veranda Multi-Story Significance:	Material: ere Stone Wood Brick Concrete  Location:
Type:  Enclosed Porte Coche Stoop Wraparound Veranda Multi-Story  Significance: Historic Altered	Material:  ere Stone Wood  Brick Concrete  Location:  Front Rear
Type:  Enclosed Porte Coche Stoop Wraparound Veranda Multi-Story  Significance: Historic Altered  Doors	Material: ere Stone Wood Brick Concrete  Location:
Type:  Enclosed Porte Coche Stoop Wraparound Veranda Multi-Story  Significance: Historic Altered  Doors Leaf: One-Leaf	Material:  ere Stone Wood Brick Concrete  Location: Front Rear Side Balcony
Type:  Enclosed Porte Coche Stoop Wraparound Veranda Multi-Story  Significance: Historic Altered  Doors  Leaf: One-Leaf Material: Wood	Material:  ere Stone Wood Brick Concrete  Location: Front Rear Side Balcony  Type:
Type:  Enclosed Porte Coche Stoop Wraparound Veranda Multi-Story  Significance: Historic Altered  Doors  Leaf: One-Leaf Material: Wood Significance: Arranger	Material:  ere Stone Wood  Brick Concrete  Location:  Front Rear  Side Balcony  Type:  ment: Paneled
Type:  Enclosed Porte Coche Stoop Wraparound Veranda Multi-Story  Significance: Historic Altered  Doors Leaf: One-Leaf Material: Wood Significance: Arranger Historic Sidel	Material:  ere Stone Wood  Brick Concrete  Location: Front Rear Side Balcony  Type: ment: Paneled  lights Paneled w/Lights
Type:  Enclosed Porte Coche Stoop Wraparound Veranda Multi-Story  Significance: Historic Altered  Doors  Leaf: One-Leaf Material: Wood Significance: Arranger	Material:  ere Stone Wood  Brick Concrete  Location: Front Rear Side Balcony  Type: ment: Paneled  Paneled w/Lights
Type:  Enclosed Porte Coche Stoop Wraparound Veranda Multi-Story  Significance: Historic Altered  Doors Leaf: One-Leaf Material: Wood Significance: Arranger Historic Replacement Sidel Trans  Windows	Material:  ere Stone Wood Brick Concrete  Location: Front Rear Side Balcony  Type:  ment:  Material:
Type:  Enclosed Porte Coche Stoop Wraparound Veranda Multi-Story  Significance: Historic Altered  Doors Leaf: One-Leaf Material: Wood Significance: Arranger Historic Sidel Replacement Trans  Windows Type: Material:	Material:  ere Stone Wood Brick Concrete  Location: Front Rear Side Balcony  Type:  ment: Paneled Paneled w/Lights som Glazed  Significance:
Type:  Enclosed Porte Coche Stoop Wraparound Veranda Multi-Story  Significance: Historic Altered  Doors Leaf: One-Leaf Material: Wood Significance: Arranger Historic Replacement Sidel Trans  Windows	Material:  ere Stone Wood Brick Concrete  Location: Front Rear Side Balcony  Type:  ment:  Material:
Type:  Enclosed Porte Coche Stoop Wraparound Veranda Multi-Story  Significance: Historic Altered  Doors  Leaf: One-Leaf Material: Wood Significance: Arranger Historic Replacement Sidel Trans  Windows Type: Material: Double-Hung Steel	Material:  ere Stone Wood  Brick Concrete  Location:  Front Rear  Side Balcony  Type:  Paneled Paneled w/Lights som Glazed  Significance:  Original Windows
Type:  Enclosed Porte Coche Stoop Wraparound Veranda Multi-Story  Significance: Historic Altered  Doors  Leaf: One-Leaf Material: Wood Significance: Arranger Historic Sidel Replacement Trans  Windows Type: Material:  Double-Hung Steel Sliding Wood	Material:  ere Stone Wood  Brick Concrete  Location: Front Rear Side Balcony  Type: Paneled Ights Som Glazed  Significance: Original Windows Original Storms
Type:  Enclosed Porte Coche Stoop Wraparound Veranda Multi-Story  Significance: Historic Altered  Doors  Leaf: One-Leaf Material: Wood Significance: Arranger Historic Sidel Replacement Trans  Windows Type: Material: Double-Hung Steel Sliding Wood Casement Vinyl	Material:  ere Stone Wood Brick Concrete  Location: Front Rear Side Balcony  Type: Paneled lights som Glazed  Significance: Original Windows Coriginal Storms Replaced Windows
Type:    Enclosed	Material:  ere Stone Wood Brick Concrete  Location: Front Rear Side Balcony  Type: Paneled lights som Glazed  Significance: Original Windows Original Storms Replaced Windows
Type:  Enclosed Porte Coche Stoop Wraparound Veranda Multi-Story  Significance: Historic Altered  Doors Leaf: One-Leaf Material: Wood Significance: Arranger Historic Sidel Replacement Trans  Windows Type: Material: Double-Hung Steel Sliding Wood Casement Vinyl Fixed Aluminus	Material:  ere Stone Wood Brick Concrete  Location: Front Rear Side Balcony  Type: Paneled WLights som Glazed  Significance: Original Windows Original Storms Replaced Windows Replaced Storms
Type:  Enclosed Porte Coche Stoop Wraparound Veranda Multi-Story  Significance: Historic Altered  Doors  Leaf: One-Leaf Material: Wood Significance: Arranger Historic Sidel Replacement Trans  Windows  Type: Material: Double-Hung Steel Sliding Wood Casement Fixed Aluminum  Roof Type:	Material:  ere Stone Wood  Brick Concrete  Location: Front Rear Side Balcony  Type: Paneled Paneled w/Lights som Glazed  Significance: Original Windows Original Storms Replaced Windows Replaced Storms  Material: Dormers:
Type:  Enclosed Porte Coche Stoop Wraparound Veranda Multi-Story  Significance: Historic Altered  Doors  Leaf: One-Leaf Material: Wood Significance: Arranger Historic Sidel Replacement Trans  Windows Type: Material: Sliding Steel Sliding Wood Casement Vinyl Fixed Aluminus  Roof Type: Gable Mansard	Material:  ere Stone Wood  Brick Concrete  Location: Front Rear Side Balcony  Type: Paneled Paneled w/Lights Som Glazed  Significance: Original Windows Original Storms Replaced Windows Replaced Storms  Material: Dormers: Asphalt Gable
Type:  Enclosed Porte Coche Stoop Wraparound Veranda Multi-Story  Significance: Historic Altered  Doors  Leaf: One-Leaf Material: Wood Significance: Arranger Historic Sidel Replacement Trans  Windows  Type: Material: Double-Hung Steel Sliding Wood Casement Fixed Aluminum  Roof Type:	Material:  ere Stone Wood  Brick Concrete  Location: Front Rear Side Balcony  Type: Paneled Paneled w/Lights som Glazed  Significance: Original Windows Original Storms Replaced Windows Replaced Storms  Material: Dormers:
Type:  Enclosed Porte Coche Stoop Wraparound Veranda Multi-Story  Significance: Historic Altered  Doors  Leaf: One-Leaf Material: Wood Significance: Arranger Historic Sidel Replacement Trans  Windows Type: Material: Sliding Steel Sliding Wood Casement Vinyl Fixed Aluminus  Roof Type: Gable Mansard	Material:  ere Stone Wood  Brick Concrete  Location: Front Rear Side Balcony  Type: Paneled Paneled w/Lights Som Glazed  Significance: Original Windows Original Storms Replaced Windows Replaced Storms  Material: Dormers: Asphalt Gable
Type:  Enclosed Porte Coche Stoop Wraparound Veranda Multi-Story  Significance: Historic Altered  Doors Leaf: One-Leaf Material: Wood Significance: Arranger Historic Sidel Replacement Trans  Windows Type: Material: Double-Hung Steel Sliding Wood Casement Vinyl Fixed Aluminus  Roof  Type: Gable Mansard Hipped Shed Jerkinhead Flat	Material:  ere Stone Wood  Brick Concrete  Location: Front Rear Side Balcony  Type: Paneled lights Som Glazed  Significance: Original Windows Original Storms Replaced Windows Replaced Storms  Material: Dormers: Material: Dormers: Material: Gable Metal Hipped Slate Shed
Type:  Enclosed Porte Coche Stoop Wraparound Veranda Multi-Story  Significance: Historic Altered  Doors  Leaf: One-Leaf Material: Wood Significance: Arranger Historic Sidel Replacement Trans  Windows Type: Material: Double-Hung Steel Sliding Wood Casement Vinyl Fixed Aluminum  Roof  Type: Gable Mansard Hipped Shed Jerkinhead Flat Gambrel	Material:  ere Stone Wood  Brick Concrete  Location: Front Rear Side Balcony  Type: Paneled W/Lights som Glazed  Significance: Original Windows Original Storms Replaced Windows Replaced Storms  Material: Dormers: Asphalt Gable Metal Hipped Slate Shed Shake Jerkin
Type:  Enclosed Porte Coche Stoop Wraparound Veranda Multi-Story  Significance: Historic Altered  Doors Leaf: One-Leaf Material: Wood Significance: Arranger Historic Sidel Replacement Trans  Windows Type: Material: Double-Hung Steel Sliding Wood Casement Vinyl Fixed Aluminus  Roof  Type: Gable Mansard Hipped Shed Jerkinhead Flat	Material:  ere Stone Wood  Brick Concrete  Location: Front Rear Side Balcony  Type: Paneled lights Som Glazed  Significance: Original Windows Original Storms Replaced Windows Replaced Storms  Material: Dormers: Material: Dormers: Material: Gable Metal Hipped Slate Shed



Photo: 114\_E\_Perry\_St\_SURVEY\_Photo.tif **Description** 

The multi-unit frame house is one-and-one-half stories with upright and wing massing, "T" shaped plan and a gabled addition. The street elevation is the side of the house, with the formal front elevation facing east. The front gabled plan spans two bays wide by four bays deep. The first floor is set on a parged masonry foundation and the walls are clad in siding. An internal brick chimney is located on center at the roof junction. The upright façade, facing east, is symmetrical with two windows at the first floor and a pair of windows in the gable. The arrangement is repeated at the west gable end wall. Along the north elevation are two irregularly spaced single-leaf entrance doors, two pairs of windows and two small eave windows. The wing is three bays wide by two bays deep. At the northeast inside corner, a single-leaf door has been replaced and is located at a low concrete stoop. Over the door there is a short mansard porch canopy supported by an elaborately turned bracket. Many of the windows have been replaced, with some 6/1 double -hung wood windows remaining at the northwest corner. On the rear elevation there is a one story gabled addition that is possibly an original kitchen wing. Set at the south...

NR ELIGIBILITY Individual Eligibility  District Eligibility:  District Name:	LOCAL ELIGIBILITY Individual Eligibility:  District Eligibility:
Belvidere Old Town NRHP District	Belvidere Courthouse Square Local District
Contributing:  Non-Contributing:	Contributing:   Non-Contributing:
☐ Events (NR-A) ☐ Persons (NR-B) ☐ Architecture (NR-C) ☐ Archaeology (NR-D)	☐ Events 2 ☐ Persons 3 ☐ Architecture 4, 5, 6, 8 ☐ Archaeology ☐ Other 1, 7, 9, 10, 11

**Belvidere Historic Resources Inventory:** Courthouse Square Area **Property Information** PIN: 05-26-281-005 Address: 119 E Perry **Building Names:** Important Dates: Historic Function: Residence Current Function: Residence Color Code Criteria: Yellow Outbuildings Number: 1 Any Significant: Architectural Style: Queen Anne Property Type: Residential Approximate Age: 1890-1899 Condition: Good/Excellent Potential for Integrity? Structure Information Structure: Frame Foundation: Stone Concrete Not Visible Brick Parged Asphalt Siding Stucco Shake Stone Board-and-Batten Brick Concrete Block Asbestos Metal Additions Location: Type: Historic ☐ Front ⊠ Rear Non-Historic Side Roof **Porch** Type: Material: Wood Enclosed Porte Cochere Stone Stoop Wraparound Brick Concrete Multi-Story Veranda Significance: Location: Historic ⊠ Altered ⊠ Front Rear **Doors** Side Balcony Leaf: One-Leaf Material: Wood Type: Significance: Arrangement: □ Paneled Historic ⊠ Sidelights Paneled w/Lights Replacement Transom Glazed Windows Material: Significance: Type: Double-Hung Steel **Original Windows** Wood Original Storms Sliding ⊠ Vinyl Replaced Windows Casement ⊠ Fixed Aluminum Replaced Storms Roof Type: Material: Dormers: ⊠ Gable Mansard X Asphalt ⊠ Gable

Hipped

Gambrel

Material:

Chimney

Jerkinhead

Shed

Flat

Metal

Slate

Shake

Clay Tile

Hipped

Shed

Jerkin

Stone

No. 132

Survey Date: 3/30/2014



Photo: 119\_E\_Perry\_St\_SURVEY\_Photo.tif

#### Description

The Queen Anne, single-family frame house is two stories with a steeply pitched cross-gabled roof and a side-facing "T" shaped plan. The first floor is raised on a coursed limestone foundation, the exterior is clad in siding, and an internal brick chimney is centrally located. At the primary elevation, facing north, a gable-front section with centered window openings and a canted bay projects out. To the east, the two-story side gable wing has a gabled wall dormer and canted first floor. Below the dormer, the main entrance is located at a concrete stoop. The single-leaf entrance was remodeled as a mid-century Colonial Revival assembly with sidelights, fluted pilasters and large dentils. The east and south elevation gable windows are typically centered with a canted first floor at the southwest corner. A one story gabled wing is located at the rear elevation and has early 20th century wood windows. Typical windows are single, tall, 1/1 double-hungs with rectangular sash, many of which remain. The frames have been clad and small rectangular basement windows pierce the foundation. Alterations and a lack of surviving decoration obscure the sub-type of this Queen Anne house and have compromised its integrity.

NR ELIGIBILITY Individual Eligibility ☐ District Eligibility: ⊠ District Name:	LOCAL ELIGIBILITY Individual Eligibility: District Eligibility: District Name:
Belvidere Old Town NRHP District	
Contributing: ⊠ Non-Contributing: ☐	Contributing: ⊠ Non-Contributing: □
☐ Events (NR-A) ☐ Persons (NR-B) ☐ Architecture (NR-C) ☐ Archaeology (NR-D)	☐ Events 2 ☐ Persons 3 ☐ Architecture 4, 5, 6, 8 ☐ Archaeology ☐ Other 1, 7, 9, 10, 11

No. 133

Survey Date: 3/29/2014

Property Information	
Address: 120 E Perry	PIN: 05-26-280-007
Building Names:	
Important Dates:	
Historic Function: Residence Current Function: Residence	
Color Code Criteria: Yellow	
Outbuildings	
	ignificant: 🔲
Architectural Style: Greek Reviv	<del>-</del>
Property Type: Residential	
Approximate Age: 1850-1859	
Condition: Heavily Altered	
Potential for Integrity?	
Structure Information	
Structure: Frame	
Foundation: Stone Conc	rete Not Visible
☐ Brick     Parge	ed
Cladding: Clapboard	Asphalt
Siding	Stucco
Shake	Stone
☐ Board-and-Batten	Brick
☐ Aluminum/Vinyl	Concrete Block
☐ Asbestos	☐ Metal
Additions Type: Location	
	··
│ │ │ │ │ │ │ │ │ │ │ │ │ │ │ │ │ │ │	t ⊠Rear □ Roof
Mon-mistoric \triangle Side	K00i
Porch	Matorial
Туре:	Material:
Type:  Enclosed Porte Coche	ere Stone Wood
Type:  Enclosed Porte Coche Stoop Wraparound	ere Stone Wood
Type:  Enclosed Porte Coche Stoop Wraparound Veranda Multi-Story	ere Stone Wood Brick Concrete
Type:  Enclosed Porte Coche Stoop Wraparound Veranda Multi-Story Significance:	ere Stone Wood Brick Concrete  Location:
Type:  ☐ Enclosed ☐ Porte Coche ☐ Stoop ☐ Wraparound ☐ Veranda ☐ Multi-Story  Significance: ☐ Historic ☐ Altered	Ere Stone Wood Brick Concrete  Location: Rear
Type:  Enclosed Porte Coche Stoop Wraparound Veranda Multi-Story Significance:	ere Stone Wood Brick Concrete  Location:
Type:  Enclosed Porte Coche Stoop Wraparound Veranda Multi-Story  Significance: Historic Altered  Doors  Leaf: One-Leaf Material: Wood	Ere Stone Wood Brick Concrete  Location: Rear
Type:    Enclosed   Porte Coche     Stoop   Wraparound     Veranda   Multi-Story     Significance:     Historic   Altered     Doors     Leaf: One-Leaf	Ere Stone Wood Brick Concrete  Location: Front Rear Side Balcony  Type:
Type:  Enclosed Porte Coche Stoop Wraparound Veranda Multi-Story  Significance: Historic Altered  Doors Leaf: One-Leaf Material: Wood Significance: Arrange Historic Side	Location: Side Balcony  Type:  ment: Paneled Brick Concrete
Type:  Enclosed Porte Coche Stoop Wraparound Veranda Multi-Story  Significance: Historic Altered  Doors Leaf: One-Leaf Material: Wood Significance: Arrange	Location: Side Balcony  Type:  ment: Paneled Brick Concrete
Type:  Enclosed Porte Coche Stoop Wraparound Veranda Multi-Story  Significance: Historic Altered  Doors  Leaf: One-Leaf Material: Wood Significance: Arrange Historic Side	Location: Stone Wood Brick Concrete  Location: Front Rear Side Balcony  Type: ment: Paneled Paneled w/Lights som Glazed
Type:    Enclosed   Porte Coche   Stoop   Wraparound   Veranda   Multi-Story     Significance:   Altered     Doors   Leaf: One-Leaf   Material: Wood   Significance:   Arrange   Arrange   Side   Tran     Historic   Side   Tran   Tran     Windows   Type:   Material:	Ere Stone Wood Definition: Concrete  Location: Front Rear Side Balcony  Type: Paneled Paneled Paneled w/Lights Som Glazed  Significance:
Type:    Enclosed   Porte Coche   Stoop   Wraparound   Veranda   Multi-Story     Significance:   Altered     Doors   Leaf: One-Leaf   Material: Wood   Significance:   Arrange   Arrange   Historic   Side   Tran     Historic   Side   Tran   Tran     Windows   Type:   Material:   Steel	Ere Stone Wood Definition: Concrete  Location: Front Rear Side Balcony  Type: Paneled Paneled w/Lights som Glazed  Significance: Original Windows
Type:  Enclosed Porte Coche Stoop Wraparound Veranda Multi-Story  Significance: Historic Altered  Doors  Leaf: One-Leaf Material: Wood Significance: Arrange Historic Side Replacement Tran  Windows Type: Material: Double-Hung Steel Sliding Wood	Ere Stone Wood Brick Concrete  Location: Front Rear Side Balcony  Type: Paneled Paneled w/Lights som Glazed  Significance: Original Windows Original Storms
Type:  Enclosed Porte Coche Stoop Wraparound Veranda Multi-Story  Significance: Historic Altered  Doors  Leaf: One-Leaf Material: Wood Significance: Arrange Historic Sidee Replacement Tran  Windows Type: Material: Double-Hung Steel Sliding Wood Casement Vinyl	Ere Stone Wood Brick Concrete  Location: Front Rear Side Balcony  Type: ment: Paneled Paneled w/Lights som Glazed  Significance: Original Windows Original Storms Replaced Windows
Type:    Enclosed   Porte Coche   Stoop   Wraparound   Veranda   Multi-Story     Significance:   Altered     Doors   Leaf: One-Leaf   Material: Wood   Significance:   Arrange   Arrange   Tran     Historic   Side   Tran   Tran     Windows   Type:   Material:   Steel   Wood   Vinyl   Casement   Vinyl   Aluminu	Ere Stone Wood Brick Concrete  Location: Front Rear Side Balcony  Type: ment: Paneled Paneled w/Lights som Glazed  Significance: Original Windows Original Storms Replaced Windows
Type:  Enclosed Porte Coche Stoop Wraparound Veranda Multi-Story  Significance: Historic Altered  Doors  Leaf: One-Leaf Material: Wood Significance: Arrange Historic Sidee Replacement Tran  Windows  Type: Material: Double-Hung Steel Sliding Wood Casement Vinyl	Ere Stone Wood Brick Concrete  Location: Front Rear Side Balcony  Type: ment: Paneled Paneled w/Lights som Glazed  Significance: Original Windows Original Storms Replaced Windows
Type:  Enclosed Porte Coche Stoop Wraparound Veranda Multi-Story  Significance: Historic Altered  Doors  Leaf: One-Leaf Material: Wood Significance: Arrange Historic Side Replacement Tran  Windows Type: Material: Double-Hung Steel Sliding Casement Vinyl Fixed  Roof	Ere Stone Wood Brick Concrete  Location: Front Rear Side Balcony  Type: Paneled Paneled w/Lights Som Glazed  Significance: Original Windows Coriginal Storms Replaced Windows Replaced Storms
Type:    Enclosed   Porte Coche   Stoop   Wraparound   Veranda   Multi-Story   Significance:   Historic   Altered   Doors   Leaf: One-Leaf   Material: Wood   Significance:   Arrange   Arrange   Historic   Side   Tran   Tran   Windows   Type:   Material:   Steel   Sliding   Steel   Vinyl   Aluminu   Roof   Type:   Aluminu   Roof   Type:   Material:   Casement   Aluminu   Roof   Type:   Material:   Casement   Aluminu   Roof   Type:   Porte   Coche   Aluminu   Roof   Type:   Material:   Aluminu   Roof   Type:   Aluminu   Roof   Type:   Material:   Aluminu   Roof   Type:   Aluminu   Roof   Type:   Aluminu   Roof   Type:   Aluminu   Aluminu   Roof   Type:   Aluminu   Alumi	Ere Stone Wood Definition: Concrete  Location: Front Rear Side Balcony  Type: Paneled Significance: Original Windows Original Storms Replaced Windows Replaced Storms  Material: Dormers:
Type:    Enclosed   Porte Coche   Stoop   Wraparound   Veranda   Multi-Story   Significance:   Historic   Altered   Doors   Leaf: One-Leaf   Material: Wood   Significance: Arrange   Historic   Side   Tran   Tran   Windows   Type:   Material:   Steel   Wood   Sliding   Steel   Wood   Vinyl   Fixed   Aluminu   Roof   Type:   Mansard   M	Ere Stone Wood Definition Wood
Type:  Enclosed Porte Coche Stoop Wraparound Veranda Multi-Story  Significance: Historic Altered  Doors  Leaf: One-Leaf Material: Wood Significance: Arrange Historic Side Replacement Tran  Windows Type: Material: Double-Hung Steel Sliding Wood Casement Vinyl Fixed Aluminu  Roof  Type: Gable Mansard Hipped Shed	Ere Stone Wood Brick Concrete  Location: Front Rear Side Balcony  Type: Paneled Significance: Original Windows Original Storms Replaced Windows Replaced Storms  Material: Dormers: Asphalt Gable Metal Hipped Slate Shed Shake Jerkin
Type:  Enclosed Porte Coche Stoop Wraparound Veranda Multi-Story  Significance: Historic Altered  Doors  Leaf: One-Leaf Material: Wood Significance: Arrange Historic Side Replacement Tran  Windows Type: Material: Double-Hung Steel Sliding Wood Casement Vinyl Fixed Aluminu  Roof  Type: Gable Mansard Hipped Shed Jerkinhead Flat	Ere Stone Wood Brick Concrete  Location: Front Rear Side Balcony  Type: ment: Paneled Paneled w/Lights Som Glazed  Significance: Original Windows Original Storms Replaced Windows Replaced Storms  Material: Dormers: Asphalt Gable Metal Hipped Slate Shed
Type:  Enclosed Porte Coche Stoop Wraparound Veranda Multi-Story  Significance: Historic Altered  Doors  Leaf: One-Leaf Material: Wood Significance: Arrange Historic Side Replacement Tran  Windows Type: Material: Double-Hung Steel Sliding Wood Casement Vinyl Fixed Aluminu  Roof  Type: Gable Mansard Hipped Shed Jerkinhead Flat Gambrel  Chimney	Ere Stone Wood Brick Concrete  Location: Front Rear Side Balcony  Type: Paneled Significance: Original Windows Original Storms Replaced Windows Replaced Storms  Material: Dormers: Asphalt Gable Metal Hipped Slate Shed Shake Jerkin



Photo: 120\_E\_Perry\_St\_SURVEY\_Photo.tif

**Description** 

The Greek Revival, single-family house is two stories with a hipped roof and a two bay square plan. The foundation and walls of the main massing are covered in stucco and a brick chimney is located at the northwest corner. A wide cornice board encircles the shallow eaves. At the primary elevation, facing south, there is a full-width porch with a hipped roof. Two thirds of the porch is enclosed and lined with bands of 6/1 wood double-hung windows. The remaining third is a recessed open porch at the front entry door. Large square columns support the roof, and the single-leaf half-lite and paneled entry door is contemporary with the porch addition. Above the porch, two evenly spaced window opening have been cut short by the porch roof. Several other irregularly spaced windows at the secondary facades have also been replaced with several generations of double-hung windows. At the rear elevation, a one story hipped roof addition with concrete block foundation has a one-and-one-half story gabled connection to the second floor. The addition is covered in stucco with early 20th century wood windows, and an enclosed gabled porch is attached at the northwest corner. Small rectangular basement windows pierce...

NR ELIGIBILITY	LOCAL ELIGIBILITY
Individual Eligibility	Individual Eligibility:
District Eligibility:	District Eligibility: 🖂
District Name:	District Name:
Belvidere Old Town NRHP District	Belvidere Courthouse Square Local Historic District
Contributing:	Contributing:
Non-Contributing:	Non-Contributing:
Events (NR-A)	Events 2
Persons (NR-B)	Persons 3
Architecture (NR-C)	Architecture 4, 5, 6, 8
Archaeology (NR-D)	Archaeology
M2 6 2	Other 1 7 9 10 11

Courthouse Square Area

134 No.

3/30/2014 Survey Date:

**Property Information** Address: 313 E Perry PIN: 05-26-283-003 **Building Names:** Important Dates: Historic Function: Old Jailhouse? Current Function: Residence Color Code Criteria: Orange Outbuildings Any Significant: ⊠ Number: 2 Architectural Style: Settlement Property Type: Residential Approximate Age: 1840-1849 Condition: Good/Excellent Potential for Integrity? Structure Information Structure: Frame Foundation: Stone Concrete Not Visible Brick Parged Asphalt Siding Stucco Shake Stone Board-and-Batten Brick



Photo: 313\_E\_Perry\_St\_SURVEY\_Photo.tif

Description

The single-family home is one-and-one-half stories tall with a front-gabled roof and a rectangular plan spanning two bays wide and deep. The first floor is raised on a parged masonry foundation, the walls are clad in siding, and a brick chimney is located at the southwest corner. The front facade, facing north, has a door to one side and two windows at the first floor with two windows centered above. The Victorian era front porch is set at a low concrete stoop with a short mansard roof, spindlework brackets, and square posts. The single-leaf front entrance door is paneled with a half lite. The front gable has short cornice returns and scalloped trim and spindlework has been added to the eaves. Windows are evenly spaced at the sided walls. An original one story gabled rear wing extends to the south and has short cornice returns at the gable end wall. Shed roof additions and enclosed porches have been added at the wing's east and west sides. All the original windows have been replaced with 1/1 double-hungs. The property is dotted with several small gabled outbuildings, most prominently a small two story carriage house. It is clad in siding and has a clipped gable roof with doublehung windows in the gables...

⊠ Asbestos	
Additions	
Type: Location:	
⊠ Historic	
□ Non-Historic □ Side □ Roof	
Porch Type: Material:	
☐ Enclosed ☐ Porte Cochere ☐ Stone ☐ Wood	7
Stoop Wraparound Brick Concrete	Н
☐ Veranda ☐ Multi-Story	J
Significance: Location:	
⊠ Historic ⊠ Altered ⊠ Front □ Rear	
Doors Side Balcony	- 1
Leaf: One-Leaf	
Material: Wood Type:	_
Significance: Arrangement: Paneled	
☐ Historic   ☐ Sidelights   ☐ Paneled w/Lights	11
Replacement Transom Glazed	
Windows	
Type: Material: Significance:	ñ
☑ Double-Hung ☐ Steel ☑ Original Windows	П
Sliding Wood Criginal Storms	Н
☐ Casement ☐ Vinyl ☐ Replaced Windows	Н
Fixed Aluminum Replaced Storms	
Roof Type: Material: Dormers:	
☐ Gable ☐ Mansard ☐ Asphalt ☐ Gable	1
Hipped Shed Metal Hipped	П
Jerkinhead Flat Slate Shed	П
Gambrel Shake Jerkin	
Chimney Clay Tile	
Material: ⊠ Brick ☐ Concrete Block ☐ Stone	
	_

NR ELIGIBILITY	LOCAL ELIGIBILITY Individual Eligibility:
Individual Eligibility U	District Eligibility:
District Name:	District Name:
Belvidere Old Town NRHP District	
Contributing:	Contributing:
Non-Contributing:	Non-Contributing:
Events (NR-A)	Events 2
Persons (NR-B)	Persons 3
	Architecture 4, 5, 6, 8
Archaeology (NR-D)	☐ Archaeology
	Other 1, 7, 9, 10, 11

**Courthouse Square Area** 

**Belvidere Historic Resources Inventory: Property Information** Address: 404 PIN: 05-26-278-004 E Perry **Building Names:** Important Dates: Historic Function: Residence Current Function: Residence Color Code Criteria: None Outbuildings Number: 1 Any Significant: Architectural Style: None Property Type: Residential Approximate Age: 1890-1899 Condition: Good/Excellent Potential for Integrity? Structure Information Structure: Frame Foundation: Stone Concrete Not Visible Brick □ Parged Asphalt Siding Stucco Stone Shake Board-and-Batten Brick ⊠ Aluminum/VinvI Concrete Block Asbestos Metal Additions Location: Type: Historic Non-Historic Side Roof Porch Type: Material: ⊠ Enclosed Porte Cochere Stone Wood Stoop Wraparound Brick Concrete Veranda Multi-Story Significance: Location: Historic Altered ⊠ Front ☐ Rear Doors Side Balcony Leaf: One-Leaf Material: Wood Type: Significance: Arrangement: Paneled ⊠ Paneled w/Lights Historic Sideliahts □ Replacement Transom Glazed Windows Material: Significance: Type: Double-Hung Steel Original Windows Sliding ⊠ Wood **Original Storms** Replaced Windows Casement ☐ Vinvl Replaced Storms

Aluminum Fixed

Roof

Type:

Material:

Material: ⊠ Gable Mansard Asphalt Hipped Shed Metal Jerkinhead Flat Slate

Gambrel Shake Clay Tile Chimney

⊠ Brick ☐ Concrete Block Stone

Dormers:

Gable

Hipped

Shed

Jerkin

135 No.

3/29/2014 Survey Date:



Photo: 404 E Perry St SURVEY Photo.tif Description

The single-family home is one-and-one-half stories tall with upright and wing massing. The first floor set on a parged masonry foundation, the walls are clad in siding, and a brick chimney is located on the west elevation. The front gable, facing south, has centered window openings: a Chicago style window at the first floor and a pair of 1/1 double-hung windows at the second floor gable. This section is two window bays deep, with evenly spaced windows at the first floor and shorter windows at the eaves. The long side wing is one bay deep, and an enclosed entry porch is situated on a concrete slab at the wing's south elevation. It has a shed roof and is lined with 3-lite louvered windows. The front entry door is not visible. At the rear elevation, there is a shed roof addition and a hipped roof enclosed porch to the north. Many of the original 2/2 double-hung wood windows with simple framing remain. Many have had mid-20th century metal awnings installed. A two car, hipped roof garage is located at the north edge of the property. It is clad in siding and has a band of multi-lite windows. The size and configuration suggest that this is a late settlement dwelling with Greek Revival detailing, many of which have been modified.

NR ELIGIBILITY Individual Eligibility District Eligibility: District Name:	LOCAL ELIGIBILITY Individual Eligibility:  District Eligibility:  District Name:
Contributing:   Non-Contributing:   Events (NR-A)  Persons (NR-B)  Architecture (NR-C)  Archaeology (NR-D)	Contributing:  Non-Contributing:  Events 2 Persons 3 Architecture 4, 5, 6, 8 Archaeology Other 1, 7, 9, 10, 11

No. 136

Survey Date: 3/29/2014

Property Information	
Address: 410 E Perry	PIN: 05-26-278-005
Building Names:	
Important Dates:	
Historic Function: Residence	
Current Function: Residence	
Color Code Criteria: Yellow	
Outbuildings Number: 1 Any Sig	unificant:
	ınificant: 🗌
Architectural Style: Queen Anne Property Type: Residential	
Approximate Age: 1900-1909	
Condition: Good	
Potential for Integrity?	
Structure Information	
Structure: Frame	Ph:
Foundation: Stone Concre	ete 🗌 Not Visible 📗 📗 🗖 🗖 🗎
🗌 Brick 🛮 🖾 Parged	d   [T
Cladding: Clapboard	☐ Asphalt
Siding	Stucco   re
Shake	Stone
☐ Board-and-Batten	Brick   el
⊠ Aluminum/Vinyl	Concrete Block
Asbestos	Metal   la
Additions	do
Type: Location:	l e
☐ Historic	Rear
Non-Historic ☐ Side	Roof
Porch	e
Type:	Material:
Enclosed Porte Cocher	
⊠ Stoop ☐ Wraparound	☐ Brick ☐ Concrete ☐ Sa
☐ Veranda ☐ Multi-Story	
Significance:	Location:
☐ Historic ☐ Altered	
Doors	
Leaf: One-Leaf	, , ,
Material: Metal	Type: ga
Significance: Arrangen	
Historic Sidelig	
Replacement Trans	-   -
Windows	
Type: Material:	Significance: N
□ Double-Hung □ Steel	⊠ Original Windows III
Sliding	Original Storms
Casement Vinyl	Replaced Windows
⊠ Fixed ⊠ Aluminun	
Roof	
Type:	Material: Dormers: C
Carried Total	M Acabalt   Cable
☐ Hipped ☐ Shed	Metal Hipped
☐ Jerkinhead ☐ Flat	Slate
Gambrel	Shake Jerkin
Chimney	Clay Tile
Material: Rrick Concre	
Material IX Prior I (Conord	DIG KINCK   INTONA



Photo: 410\_E\_Perry\_St\_SURVEY\_Photo.tif Description

he Queen Anne, single-family frame house is two stories ith a steeply pitched cross-gabled roof. The first floor is aised on a parged foundation, the exterior is clad in siding, nd a brick chimney is centrally located. At the primary evation, facing south, there is a gable-front section with entered window openings and a canted first floor. A large indscape window is at the first floor, with a pair of 1/1 ouble-hung window at the second floor. A one-story nclosed gabled front porch is situated to the east side. It as a brick and concrete base, a single-leaf entrance door, ctagonal window and a metal awning. The east and west evation gable windows are typically centered. A one-story pped-roof wing is located at the rear elevation. Typical indows are single, tall, 1/1 double-hungs with rectangular ash, many of which remain. Some frames retain ecorative corner block, but many have been clad. Small ectangular basement windows pierce the foundation. At e north edge of the property there is a mid-20th century ne car garage clad in siding with vertical boards in the able end. Much of the home's original fabric and ecorative elements have been altered, compromising its tegrity.

NR ELIGIBILITY Individual Eligibility District Eligibility: District Name:	LOCAL ELIGIBILITY Individual Eligibility:  District Eligibility:  District Name:
Contributing:  Non-Contributing:  Events (NR-A) Persons (NR-B) Architecture (NR-C) Archaeology (NR-D)	Contributing:   Non-Contributing:   Events 2  Persons 3  Architecture 4, 5, 6, 8  Archaeology  Other 1, 7, 9, 10, 11

**Courthouse Square Area** 

137 No. **Survey Date:** 

3/29/2014

Property Information		
Address: 412 E Perry	PIN: 05-26-278-006	
Building Names:		
Important Dates:	E	
Historic Function: Residence		
Current Function: Residence Color Code Criteria: Yellow		
Outbuildings	y	
<u> </u>	ificant: ⊠	
Architectural Style: Colonial Revival		
Property Type: Residential		
Approximate Age: 1900-1909		
Condition: Good/Excellent		
Potential for Integrity?		
Structure Information		
Structure: Frame	P	
Foundation: Stone Concret	e 🗌 Not Visible 📗 🗖 🗖	
🗌 Brick 🛮 🖾 Parged	I T	
Cladding: Clapboard	Asphalt	
Siding	Stucco	
Shake	Stone	
Board-and-Batten	Brick	
⊠ Aluminum/Vinyl	Concrete Block	
Asbestos L	∫Metal     a	
Type: Location:		
Historic Front	Rear	
Non-Historic Side	Roof	
Porch		
Type:	Material:	
Enclosed Porte Cochere		
Stoop Wraparound	☐ Brick ☐ Concrete	
☐ Veranda ☐ Multi-Story		
Significance:	Location:	
☐ Historic	⊠ Front □ Rear	
Doors	☐ Side ☐ Balcony	
Leaf: One-Leaf		
Material: Metal Significance: Arrangeme	Type:	
☐ Historic ☐ Sideligi ☐ Replacement ☐ Transo		
Windows	Glazed	
Type: Material:	Significance:	
□ Double-Hung    □ Steel	Original Windows	
Sliding Wood	Original Storms	
☐ Casement ⊠ Vinyl	Replaced Windows	
☐ Fixed ☐ Aluminum	Replaced Storms	
Roof	eterial: Darmara:	
	aterial: Dormers:	
☐ Gable ☐ Mansard ☐ Shed	Asphalt Gable Hipped	
Jerkinhead Flat	Metal Hipped Slate Shed	
Gambrel	Shake   Jerkin   Jerkin	
Chimney	Clay Tile	
Material: Brick Concret		



hoto: 412\_E\_Perry\_St\_SURVEY\_Photo.tif escription

The single-family dwelling is one-and-one-half stories with a steeply pitched side-gabled roof and rectangular, one-room deep plan. The first floor is raised on a parged masonry foundation and the exterior is clad in siding. The primary elevation, facing south, there are three bays. A one-story gabled front porch is situated off-center at a concrete stoop, and has a simple wood railing. The single-leaf entrance door is a replacement. The west elevation has one centered window at each floor, while the east elevation has an off-center window at the first floor and a centered window at the second floor. A one story hipped roof entrance is located at the rear elevation. Typical windows are single 1/1 double-hungs with rectangular sash, many of which have been replaced. The frames have been clad and faux shutters added. Small rectangular basement windows pierce the foundation. At the north edge of the property there is a mid-20th century one-car garage clad in siding with vertical boards in the gable end. The size and configuration suggest that this turn of the century I-house had simple detailing. Much of the home's original fabric has been altered, compromising its integrity.

NR ELIGIBILITY Individual Eligibility District Eligibility: District Name:	LOCAL ELIGIBILITY Individual Eligibility: District Eligibility: District Name:
Contributing:  Non-Contributing:  Events (NR-A) Persons (NR-B) Architecture (NR-C) Archaeology (NR-D)	Contributing:  Non-Contributing:  Events 2 Persons 3 Architecture 4, 5, 6, 8 Archaeology

**Courthouse Square Area** 

**Belvidere Historic Resources Inventory: Property Information** Address: 415 E Perry PIN: 05-26-284-004 **Building Names:** Important Dates: Historic Function: Residence Current Function: Residence Color Code Criteria: None Outbuildings Number: 0 Any Significant: Architectural Style: Queen Anne Property Type: Residential Approximate Age: 1910-1919 Condition: Good Potential for Integrity? Structure Information Structure: Frame Foundation: Stone Concrete Not Visible Brick Parged Asphalt Siding Stucco Shake Stone Board-and-Batten Brick ⊠ Aluminum/Vinyl Concrete Block Asbestos Metal Additions Type: Location: Mistoric | Non-Historic Side Roof Porch Type: Material: Porte Cochere Stone ⊠ Wood Brick ⊠ Concrete Stoop Wraparound ⊠ Veranda ■ Multi-Story Significance: Location:

Leaf: Or	ne-Leaf
Material:	Metal
Significan	ce:
Histor	ic
⊠ Repla	cement

Sliding

Fixed

Material:

Historic

Doors

Windows

Roof

Type:

Material: Significance: Original Windows

Arrangement:

Sidelights Transom

 □ Double-Hung Steel Wood ⊠ VinvI Casement

**Original Storms** Replaced Windows Aluminum Replaced Storms ners:

⊠ Front

Side

Type:

Paneled

Glazed

Rear

Paneled w/Lights

Balconv

Root				
Type:			Material:	Dormers:
⊠ Gab	le	Mansard	⊠ Asphalt	⊠ Gable
Hipp		Shed	Metal	Hipped
Jerk	inhead	Flat	Slate	Shed
☐ Gan	nbrel		Shake	Jerkin
Chimney			Clay Tile	

⊠ Brick ☐ Concrete Block ☐ Stone

138 No.

3/30/2014 Survey Date:



Photo: 415\_E\_Perry\_St\_SURVEY\_Photo.tif Description

The single-family home is one-and-one-half stories tall with a gabled roof and side-facing "T" shaped plan. The first floor set on a rock-faced concrete block foundation, the walls are clad in siding, and a brick chimney is centrally located. The front gable, facing north, has centered window openings at each floor. The side wing is one bay deep, and an enclosed entry porch is situated at the wing's north elevation. It has a shed roof, paired windows and a unoriginal single-leaf entrance door. At the rear elevation. there is a shed roof addition Many of the original 1/1 double-hung windows have been replaced and their frames have been clad. Small rectangular basement windows pierce the foundation. At the west edge of the property there is a two car, hipped roof garage with cross buck paneled carriage doors. The size and configuration suggest a modest Queen Anne dwelling, though many of the home's original features have been updated or modified, causing a loss of integrity.

	·
NR ELIGIBILITY Individual Eligibility  District Eligibility:  District Name:	LOCAL ELIGIBILITY Individual Eligibility: District Eligibility:
Belvidere Old Town NRHP	
District	
Contributing:	Contributing:
Non-Contributing:	Non-Contributing:
Events (NR-A)	Events 2
Persons (NR-B)	Persons 3
Architecture (NR-C)	Architecture 4, 5, 6, 8
Archaeology (NR-D)	Archaeology
	I X Other 1 7 9 10 11

**Belvidere Historic Resources Inventory:** Courthouse Square Area **Property Information** Address: 416 E Perry PIN: 05-26-278-007 **Building Names:** Important Dates: Historic Function: Residence Current Function: Residence Color Code Criteria: Yellow Outbuildings Number: 1 Any Significant: X Architectural Style: Queen Anne Property Type: Residential Approximate Age: 1900-1909 Condition: Good/Excellent Potential for Integrity? Structure Information Structure: Frame Foundation: Stone Concrete Not Visible Brick N Parged Cladding: Clapboard Asphalt Stucco Siding Shake Stone Board-and-Batten Brick ⊠ Aluminum/Vinvl Concrete Block Asbestos Metal Additions Type: Location: Historic Front Rear Non-Historic Side Roof Porch Type: Material: Enclosed Porte Cochere Stone Wood Stoop Wraparound Brick Concrete Veranda Multi-Story Significance: Location: Historic ⊠ Front Rear Doors Side Balconv Leaf: One-Leaf Material: Metal Type: Significance: Arrangement: Paneled Paneled w/Lights Historic Sidelights Replacement Transom Glazed Windows Material: Significance: Type: Double-Hung Steel Original Windows Sliding ⊠ Wood Original Storms ⊠ Vinvl Replaced Windows Casement Fixed Aluminum Replaced Storms Roof Material: Dormers: Type:

X Asphalt

Metal

Slate

Shake

Clay Tile

Gable

Shed

Jerkin

Stone

Hipped

Mansard

⊠ Brick ☐ Concrete Block

Shed

Flat

⊠ Gable

Hipped

Gambrel

Material:

Chimney

Jerkinhead

No. 139

Survey Date: 3/29/2014



Photo: 416\_E\_Perry\_St\_SURVEY\_Photo.tif **Description** 

The single-family frame cottage is two stories with a wide front gabled roof massing and a rectangular floor plan. The first floor is raised on a concrete block foundation, the exterior is clad in siding, and a brick chimney is centrally located. The primary elevation, facing south, has a full width enclosed front porch with a short, mansard, flat roof. The porch is sided and lined with 1/1 storm windows. The replaced single-leaf entrance door is located off-center flanked by two 6/6 double-hung windows. Two additional 6/6 windows are centered above at the second floor, and a 9-lite sash is located on center in the gable end. The east and west elevations have small, irregularly spaced doublehung windows and small rectangular basement windows pierce the foundation. Almost all the original windows have been replaced. Adjacent to the northeast corner there is a side gabled one-car garage clad in siding and with wood carriage doors. Built at the turn of the century with plain and simple detailing, this house has been heavily altered,

and much of this middle or working class cottage's integrity

has been compromised.

NR ELIGIBILITY Individual Eligibility District Eligibility: District Name:	LOCAL ELIGIBILITY Individual Eligibility: District Eligibility: District Name:
Contributing:   Non-Contributing:	Contributing:   Non-Contributing:
☐ Events (NR-A) ☐ Persons (NR-B) ☐ Architecture (NR-C) ☐ Archaeology (NR-D)	☐ Events 2 ☐ Persons 3 ☐ Architecture 4, 5, 6, 8 ☐ Archaeology ☐ Other 1, 7, 9, 10, 11

**No.** 140

Survey Date: 3/29/2014

Property Information	
Address: 418 E Perry	PIN: 05-26-278-011
Building Names:	
Important Dates:	
Historic Function: Residence	
Current Function: Residence	
Color Code Criteria: None Outbuildings	
	ignificant:
Architectural Style: None	igrimourit
Property Type: Residential	
Approximate Age: 1850-1859	
Condition: Good	
Potential for Integrity? 🔀	
Structure Information	
Structure: Masonry	> ·
· ·	rete Not Visible
Brick Parg	
_	
Cladding: Clapboard	∐ Asphalt
⊠ Siding	Stucco
Shake	Stone
Board-and-Batten	Brick
☐ Aluminum/Vinyl	Concrete Block
Additions Asbestos	∐ Metal
Type: Location	n:
Historic X Fron	t Rear
⊠ Non-Historic ⊠ Side	
Porch	
Porch Type:	Material:
Туре:	
Type:  Enclosed Porte Coche	ere Stone Wood
Type:  ☐ Enclosed ☐ Porte Coche ☐ Stoop ☐ Wraparound	ere Stone Wood
Type:  Enclosed Porte Coche Stoop Wraparound Veranda Multi-Story	ere Stone Wood  Brick Concrete
Type:  Enclosed Porte Coche Stoop Wraparound Veranda Multi-Story  Significance:	ere Stone Wood Brick Concrete  Location:
Type:  Enclosed Porte Coche Stoop Wraparound Veranda Multi-Story  Significance: Historic Altered	ere Stone Wood Description:  Location: Front Rear
Type:  Enclosed Porte Coche Stoop Wraparound Veranda Multi-Story  Significance:	ere Stone Wood Brick Concrete  Location:
Type:  Enclosed Porte Coche Stoop Wraparound Veranda Multi-Story  Significance: Historic Altered  Doors	ere Stone Wood Description:  Location: Front Rear
Type:  Enclosed Porte Coche Stoop Wraparound Veranda Multi-Story  Significance: Historic Altered  Doors Leaf: One-Leaf	Ere Stone Wood  Brick Concrete  Location: Front Rear Side Balcony  Type:
Type:  Enclosed Porte Coche Stoop Wraparound Veranda Multi-Story  Significance: Historic Altered  Doors Leaf: One-Leaf Material: Metal Significance: Arrange	Ere Stone Wood  Brick Concrete  Location:  Front Rear  Side Balcony  Type:
Type:  Enclosed Porte Coche Stoop Wraparound Veranda Multi-Story  Significance: Historic Altered  Doors Leaf: One-Leaf Material: Metal Significance: Arrange	Ere Stone Wood  Brick Concrete  Location:  Front Rear  Side Balcony  Type:  Paneled  Paneled w/Lights
Type:    Enclosed   Porte Coche   Stoop   Wraparound   Wulti-Story     Significance:   Altered     Doors   Leaf: One-Leaf   Material: Metal     Significance:   Arrange   Arrange   Side   Replacement   Tran	Ere Stone Wood  Brick Concrete  Location: Front Rear Side Balcony  Type: Paneled    Paneled w/Lights
Type:    Enclosed   Porte Coche   Stoop   Wraparound   Wulti-Story     Significance:   Altered     Doors   Leaf: One-Leaf   Material: Metal     Significance:   Arrange   Arrange   Side   Tran     Historic   Replacement   Tran     Windows   Type:   Material:	Ere Stone Wood  Brick Concrete  Location: Front Rear Side Balcony  Type: Paneled    Paneled w/Lights
Type:  Enclosed Porte Coche Stoop Wraparound Veranda Multi-Story  Significance: Historic Altered  Doors Leaf: One-Leaf Material: Metal Significance: Arrange Historic Replacement Side Tran  Windows Type: Material: Double-Hung Steel	Ere Stone Wood  Brick Concrete  Location: Front Rear Side Balcony  Type: Paneled Significance: Original Windows
Type:  Enclosed Porte Coche Stoop Wraparound Veranda Multi-Story  Significance: Historic Altered  Doors  Leaf: One-Leaf Material: Metal Significance: Arrange Historic Replacement Side Tran  Windows Type: Material: Double-Hung Steel Sliding Wood	Ere Stone Wood  Brick Concrete  Location: Front Rear Side Balcony  Type: Paneled Paneled w/Lights som  Significance: Original Windows Original Storms
Type:  Enclosed Porte Coche Stoop Wraparound Veranda Multi-Story  Significance: Historic Altered  Doors Leaf: One-Leaf Material: Metal Significance: Arrange Historic Replacement Side Tran  Windows Type: Material: Double-Hung Sliding Wood Casement Vinyl	Ere Stone Wood Description: Concrete  Location: Front Rear Description: Paneled Paneled Whights Som Paneled Whights Som Glazed  Significance: Original Windows Original Storms Replaced Windows
Type:  Enclosed Porte Coche Stoop Wraparound Veranda Multi-Story  Significance: Historic Altered  Doors  Leaf: One-Leaf Material: Metal Significance: Arrange Historic Replacement Side Tran  Windows Type: Material: Double-Hung Steel Sliding Wood	Ere Stone Wood Description: Concrete  Location: Front Rear Description: Side Balcony  Type: Paneled Paneled WLights Som Clazed  Significance: Original Windows Original Storms Replaced Windows
Type:  Enclosed Porte Coche Stoop Wraparound Veranda Multi-Story  Significance: Historic Altered  Doors  Leaf: One-Leaf Material: Metal Significance: Arrange Historic Replacement Side Tran  Windows Type: Material: Double-Hung Sliding Casement Vinyl Fixed  Roof  Roof	Ere Stone Wood Deficition: Concrete  Location: Front Rear Deficition: Side Balcony  Type: Paneled Paneled w/Lights Som Glazed  Significance: Original Windows Original Storms Replaced Windows Replaced Storms
Type:  Enclosed Porte Coche Stoop Wraparound Veranda Multi-Story  Significance: Historic Altered  Doors Leaf: One-Leaf Material: Metal Significance: Arrange Historic Side Replacement Tran  Windows Type: Material: Double-Hung Steel Sliding Wood Casement Vinyl Fixed  Roof Type:	Ere Stone Wood Deficition: Concrete  Location: Front Rear Deficition: Side Balcony  Type: Paneled Whights Som Clazed  Significance: Original Windows Original Storms Replaced Windows Replaced Storms  Material: Dormers:
Type:  Enclosed Porte Coche Stoop Wraparound Veranda Multi-Story  Significance: Historic Altered  Doors  Leaf: One-Leaf Material: Metal Significance: Arrange Historic Side Replacement Tran  Windows Type: Material: Double-Hung Steel Sliding Wood Casement Vinyl Fixed Aluminu  Roof  Type: Gable Mansard	Ere Stone Wood  Brick Concrete  Location: Front Rear Side Balcony  Type: Paneled Paneled WLights som Glazed  Significance: Original Windows Original Storms Replaced Windows Replaced Storms  Material: Dormers: Asphalt Gable
Type:  Enclosed Porte Coche Stoop Wraparound Veranda Multi-Story  Significance: Historic Altered  Doors  Leaf: One-Leaf Material: Metal Significance: Arrange Historic Replacement Side Type: Material: Double-Hung Sliding Sliding Casement Vinyl Fixed  Mansard Hipped Shed	Ere Stone Wood Deficit Concrete  Location: Front Rear Side Balcony  Type: Paneled WLights Som Glazed  Significance: Original Windows Original Storms Replaced Windows Replaced Storms  Material: Dormers: Asphalt Gable Metal Hipped
Type:  Enclosed Porte Coche Stoop Wraparound Veranda Multi-Story  Significance: Historic Altered  Doors  Leaf: One-Leaf Material: Metal Significance: Arrange Historic Replacement Side Tran  Windows Type: Material: Double-Hung Steel Sliding Casement Vinyl Fixed Aluminu  Roof  Type: Gable Mansard Hipped Shed Jerkinhead Flat	Ere Stone Wood Deficition: Concrete  Location: Front Rear Deficition: Paneled Balcony  Type: Paneled W/Lights Doriginal Windows Original Storms Replaced Windows Replaced Windows Replaced Storms  Material: Dormers: Material: Dormers: Metal Hipped Slate Stone Wood Wood Wood Concrete
Type:  Enclosed Porte Coche Stoop Wraparound Veranda Multi-Story  Significance: Historic Altered  Doors Leaf: One-Leaf Material: Metal Significance: Arrange Historic Side Replacement Tran  Windows Type: Material: Double-Hung Steel Sliding Wood Casement Vinyl Fixed Aluminu  Roof  Type: Gable Mansard Hipped Shed Jerkinhead Flat Gambrel	Ere Stone Wood Deficition: Concrete  Location: Front Rear Deficition: Side Balcony  Type: Paneled Wlights Som Driginal Windows Original Storms Replaced Windows Replaced Storms  Material: Dormers: Material: Dormers: Material: Dormers: Slate Shake Derkin
Type:  Enclosed Porte Coche Stoop Wraparound Veranda Multi-Story  Significance: Historic Altered  Doors  Leaf: One-Leaf Material: Metal Significance: Arrange Historic Replacement Side Tran  Windows Type: Material: Double-Hung Steel Sliding Wood Casement Vinyl Fixed Aluminu  Roof  Type: Gable Mansard Hipped Shed Jerkinhead Flat Gambrel  Chimney	Ere Stone Wood Deficition: Concrete  Location: Front Rear Deficition: Side Balcony  Type: Paneled Wlights Som Driginal Windows Original Storms Replaced Windows Replaced Storms  Material: Dormers: Material: Dormers: Metal Hipped Slate Stone Wood Wood Wood Concrete



Photo: 418\_E\_Perry\_St\_SURVEY\_Photo.tif **Description** 

418\_E\_Perry\_St\_Property\_Description\_DRAFT The single-family home is one-and-one-half stories tall with upright and wing massing. The foundation is not visible, the walls are clad in siding and stone veneer, and a brick chimney is located on the north elevation. Much of the home is obstructed by the lot's dense trees and landscaping. The front gable, facing south, has centered window openings: two at the first floor and one at the second floor gable. The one-story side wing has been enlarged with a front facing gabled entry vestibule. Here the single-leaf entry door is flaked with sidelights. Further east, a one-car gabled garage has been added. There are also additions to the rear elevation. None of the original windows remain. The size and configuration suggest that this is a settlement dwelling, but significant remodeling and alterations have compromised its integrity.

NR ELIGIBILITY Individual Eligibility  District Eligibility:  District Name:	LOCAL ELIGIBILITY Individual Eligibility:  District Eligibility:  District Name:
Contributing:  Non-Contributing:	Contributing:  Non-Contributing:
Events (NR-A) Persons (NR-B) Architecture (NR-C) Archaeology (NR-D)	Events 2 Persons 3 Architecture 4, 5, 6, 8 Archaeology Other 1, 7, 9, 10, 11

No. 141

Survey Date: 3/30/2014

Property Information
Address: 419 E Perry PIN: 05-26-284-005
Building Names: 1955 (date of construction)
Important Dates:
Historic Function: Residence Current Function: Residence
Color Code Criteria: Orange
Outbuildings
Number: 1 Any Significant: ⊠
Architectural Style: Mid-Century
Property Type: Residential
Approximate Age: 1950-1959  Condition: Fair
Potential for Integrity?
Structure Information
Structure: Frame/Masonry
Foundation: Stone Concrete Not Visible  Brick Parged
Cladding: Clapboard Asphalt
☐ Siding ☐ Stucco
☐ Shake ⊠ Stone
☐ Board-and-Batten ☐ Brick
Additions Metal
Additions Type: Location:
Historic Front Rear
□ Non-Historic □ Side □ Roof
Porch
Type: Material:
Type: Material:  Enclosed Porte Cochere Stone Wood
Type: Material:  Enclosed Porte Cochere Stone Wood Stoop Wraparound Brick Concrete
Type: Material:  Enclosed Porte Cochere Stoop Wraparound Veranda Multi-Story  Material:  Stone Wood Brick Concrete
Type: Material:  Enclosed Porte Cochere Stone Wood Stoop Wraparound Brick Concrete Veranda Multi-Story  Significance: Location:
Type: Material:  Enclosed Porte Cochere Stone Wood Stoop Wraparound Veranda Multi-Story  Significance: Location:  Historic Altered Front Rear
Type: Material:  Enclosed Porte Cochere Stone Wood Stoop Wraparound Brick Concrete  Veranda Multi-Story  Significance: Location: Historic Altered Front Rear  Doors
Type: Material:  Enclosed Porte Cochere Stone Wood Stoop Wraparound Veranda Multi-Story  Significance: Location: Historic Altered Front Rear Doors
Type: Material:  Enclosed Porte Cochere Stone Wood Stoop Wraparound Veranda Multi-Story  Significance: Location: Historic Altered Front Rear Doors Leaf: One-Leaf
Type: Material:  Enclosed Porte Cochere Stone Wood Stoop Wraparound Brick Concrete  Veranda Multi-Story  Significance: Location: Historic Altered Front Rear  Doors Side Balcony Leaf: One-Leaf Material: Wood Type: Significance: Arrangement: Paneled Historic Sidelights Paneled w/Lights
Type: Material:  Enclosed Porte Cochere Stone Wood Stoop Wraparound Brick Concrete  Veranda Multi-Story  Significance: Location: Historic Altered Front Rear  Doors Side Balcony Leaf: One-Leaf Material: Wood Type: Significance: Arrangement: Paneled
Type: Material:    Enclosed   Porte Cochere   Stone   Wood   Brick   Concrete   Porte Cochere   Stone   Wood   Brick   Concrete   Porte Cochere   Stone   Wood   Brick   Concrete   Porte Cochere   Porte Cochere   Porte Cochere   Porte Concrete   Porte Cochere   Porte Concrete   Porte Cochere   P
Type: Material:    Enclosed   Porte Cochere   Stone   Wood   Brick   Concrete   Porte Cochere   Stone   Wood   Brick   Concrete   Porte Cochere   Stone   Wood   Brick   Concrete   Porte Cochere   Porte Coch
Type: Material:  Enclosed Porte Cochere Stone Wood Stoop Wraparound Brick Concrete  Veranda Multi-Story  Significance: Location: Historic Altered Front Rear  Doors Side Balcony  Leaf: One-Leaf Material: Wood Significance: Arrangement: Paneled Historic Sidelights Paneled WLights Replacement Transom Glazed  Windows  Type: Material: Significance: Double-Hung Steel Original Windows
Type: Material:    Enclosed   Porte Cochere   Stone   Wood   Stoop   Wraparound   Brick   Concrete   Veranda   Multi-Story   Significance: Location:   Historic   Altered   Front   Rear   Paneled   Balcony   Leaf: One-Leaf   Material: Wood   Type:   Significance:   Arrangement:   Paneled   Panele
Type: Material:    Enclosed   Porte Cochere   Stone   Wood   Stoop   Wraparound   Brick   Concrete   Veranda   Multi-Story   Significance: Location:   Historic   Altered   Front   Rear   Balcony   Leaf: One-Leaf   Material: Wood   Type: Significance:   Arrangement:   Paneled   Paneled
Type: Material:    Enclosed   Porte Cochere   Stone   Wood   Stoop   Wraparound   Brick   Concrete   Veranda   Multi-Story   Significance: Location:   Historic   Altered   Front   Rear   Paneled   Balcony   Leaf: One-Leaf   Material: Wood   Type:   Significance:   Arrangement:   Paneled   Panele
Type: Material:    Enclosed   Porte Cochere   Stone   Wood   Brick   Concrete   Porte Cochere   Stone   Wood   Brick   Concrete   Porte Cochere   Stone   Wood   Brick   Concrete   Porte Cochere   Porte Coch
Type: Material:    Enclosed   Porte Cochere   Stone   Wood   Brick   Concrete   Porte Cochere   Porte Co
Type: Material:    Enclosed   Porte Cochere   Stone   Wood   Brick   Concrete   Porte Cochere   Stone   Wood   Brick   Concrete   Poore   Poor
Type:
Type:
Type:



Photo: 419\_E\_Perry\_St\_SURVEY\_Photo.tif **Description** 

The single-family sprawling Ranch home is one story tall with a side-gabled roof and rectangular plan. The walls are set on a concrete foundation and clad in siding and stone veneer, with a brick chimney on center at the rear elevation. A central gable projects from the front façade, facing north, and is clad with stone veneer and scalloped edge vertical boards in the gable end. A very wide picture window is flanked with thin 2/2 double-hung windows. Located at a low concrete stoop to the east of the gabled projection is the main entrance, which features the original single-leaf slab door with 3 stepped lites. Two large 2/2 double-hung windows are placed at each corner of the front façade with smaller versions appearing at the gable end. To the west is an enclosed gabled hyphen that connects to a front gabled wing with a square plan. A pair of 1/1 double-hung windows is centered on the front wing façade. The original wood windows remain, as well as several wood storm windows. Further west there is a gabled two car garage with siding and scalloped boards to match the house. The size, configuration and details have been well maintained, making this a fine example of a sprawling mid-20th century Ranch home.

NR ELIGIBILITY Individual Eligibility District Eligibility:  District Name:	LOCAL ELIGIBILITY Individual Eligibility: District Eligibility: District Name:
Belvidere Old Town NRHP District	
Contributing:   Non-Contributing:   Events (NR-A)  Persons (NR-B)	Contributing:   Non-Contributing:   Events 2  Persons 3
Architecture (NR-C) Archaeology (NR-D)	Architecture 4, 5, 6, 8  Archaeology  Other 1, 7, 9, 10, 11

No. 142

Survey Date: 3/29/2014

Property Information	
Address: 119 E Boone	PIN: 05-26-280-004
Building Names:	
Important Dates: 1928 (constructi	ion date)
Historic Function: Residence	
Current Function: Residence	
Color Code Criteria: Red	
Outbuildings Number: 2 Any Sig	m:F:===#: \\
, ,	nificant: 🔀
Architectural Style: Colonial Revi Property Type: Residential	vai
Approximate Age: 1920-1929	
Condition: Good/Excellent	
Potential for Integrity?	
Structure Information	
Structure: Masonry	
Foundation: Stone Concre	
Brick Parged	t l
Cladding: Clapboard	Asphalt
☐ Siding	Stucco
Shake	Stone
☐ Board-and-Batten	Brick
Aluminum/Vinyl	Concrete Block
Asbestos	Metal
Additions	
Type: Location:	
Historic Front	⊠ Rear
	Roof
Porch	
Porch Type:	Material:
Type:  ☐ Enclosed ☐ Porte Cocher	
Type: ☐ Enclosed ☐ Porte Cocher ☐ Stoop ☐ Wraparound	
Type:  Enclosed Porte Cocher	e Stone Wood
Type:  ☐ Enclosed ☐ Porte Cocher ☐ Stoop ☐ Wraparound ☐ Veranda ☐ Multi-Story	e Stone Wood
Type:  ☐ Enclosed ☐ Porte Cocher ☐ Stoop ☐ Wraparound	e Stone ⊠ Wood □ Brick ⊠ Concrete □ Location:
Type: ☐ Enclosed ☐ Porte Cocher ☐ Stoop ☐ Wraparound ☐ Veranda ☐ Multi-Story  Significance:	E Stone Wood Brick Concrete  Location: Rear
Type:  ☐ Enclosed ☐ Porte Cocher ☐ Stoop ☐ Wraparound ☐ Veranda ☐ Multi-Story  Significance: ☐ Historic ☐ Altered  Doors  Leaf: One-Leaf	Stone Swood Brick Concrete  Location: Rear
Type:  ☐ Enclosed ☐ Porte Cocher ☐ Stoop ☐ Wraparound ☐ Veranda ☐ Multi-Story  Significance: ☐ Historic ☐ Altered  Doors  Leaf: One-Leaf Material:	E Stone Wood Brick Concrete  Location: Front Rear Side Balcony  Type:
Type:  Enclosed Porte Cocher  Stoop Wraparound  Veranda Multi-Story  Significance:  Historic Altered  Doors  Leaf: One-Leaf  Material:  Significance: Arrangem	E Stone Wood Brick Concrete  Location: Front Rear Side Balcony  Type: Paneled
Type:  Enclosed Porte Cocher  Stoop Wraparound  Veranda Multi-Story  Significance:  Historic Altered  Doors  Leaf: One-Leaf  Material:  Significance: Arrangem  Historic Sidelig	Stone
Type:  Enclosed Porte Cocher  Stoop Wraparound  Veranda Multi-Story  Significance:  Historic Altered  Doors  Leaf: One-Leaf  Material:  Significance: Arrangem	Stone
Type:  Enclosed Porte Cocher  Stoop Wraparound  Veranda Multi-Story  Significance:  Historic Altered  Doors  Leaf: One-Leaf Material: Significance: Arrangem  Historic Replacement Sidelig  Transo  Windows	Stone
Type:  Enclosed Porte Cocher  Stoop Wraparound  Veranda Multi-Story  Significance:  Historic Altered  Doors  Leaf: One-Leaf  Material:  Significance: Arrangem  Historic Sidelig  Replacement Sidelig  Transc  Windows  Type: Material:	E Stone Wood Brick Concrete  Location: Front Rear Side Balcony  Type: Paneled Paneled w/Lights Glazed  Significance:
Type:    Enclosed   Porte Cocher   Stoop   Wraparound   Wraparound   Multi-Story     Significance:   Altered     Doors   Leaf: One-Leaf   Material: Significance:   Arrangem   Significance:   Arrangem   Transcomplete   Transcomplete   Material:     Windows   Type:   Material:   Steel	Stone
Type:  Enclosed Porte Cocher  Stoop Wraparound Veranda Multi-Story  Significance: Historic Altered  Doors  Leaf: One-Leaf Material: Significance: Arrangem Historic Replacement Sidelig Transc  Windows  Type: Material: Double-Hung Steel Sliding Wood	E Stone Wood Brick Concrete  Location: Front Rear Side Balcony  Type: Paneled Paneled w/Lights Glazed  Significance: Original Windows Original Storms
Type:  Enclosed Porte Cocher Stoop Wraparound Veranda Multi-Story  Significance: Historic Altered  Doors  Leaf: One-Leaf Material: Significance: Arrangem Historic Sidelig Transc  Windows Type: Material: Double-Hung Steel Sliding Wood Casement Vinyl	E Stone Wood Brick Concrete  Location: Front Rear Side Balcony  Type: Paneled W/Lights Com Glazed  Significance: Original Windows Coriginal Storms Replaced Windows
Type:  Enclosed Porte Cocher  Stoop Wraparound Veranda Multi-Story  Significance: Historic Altered  Doors  Leaf: One-Leaf Material: Significance: Arrangem Historic Replacement Sidelig Transc  Windows  Type: Material: Double-Hung Steel Sliding Wood	E Stone Wood Brick Concrete  Location: Front Rear Side Balcony  Type: Paneled W/Lights Com Glazed  Significance: Original Windows Coriginal Storms Replaced Windows
Type:  Enclosed Porte Cocher Stoop Wraparound Veranda Multi-Story  Significance: Historic Altered  Doors Leaf: One-Leaf Material: Significance: Arrangem Historic Sidelig Transc  Windows Type: Material: Double-Hung Steel Sliding Wood Casement Vinyl Fixed  Roof	E Stone Wood Brick Concrete  Location: Front Rear Side Balcony  Type: Paneled WLights M Glazed  Significance: Original Windows Replaced Windows Replaced Storms
Type:    Enclosed   Porte Cocher   Stoop   Wraparound   Veranda   Multi-Story     Significance:   Altered     Doors   Leaf: One-Leaf   Material: Significance:   Arrangem   Sidelig   Transcomplete   Transcomplete   Sliding   Steel   Wood   Casement   Vinyl   Fixed   Aluminum     Roof   Type:   Material:   Replacement   Roof   Type:   Material:   Roof   Replacement   Repla	E Stone Wood Brick Concrete  Location: Front Rear Side Balcony  Type: Paneled Hights Mindows Original Windows Replaced Windows Replaced Storms  Material: Dormers:
Type:    Enclosed   Porte Cocher   Stoop   Wraparound   Veranda   Multi-Story   Significance:   Altered	Location:  Front Rear Side Balcony  Type:  Paneled W/Lights Om Glazed  Significance:  Original Windows Original Storms Replaced Windows Replaced Storms  Material: Dormers:  Asphalt Gable
Type:  Enclosed Porte Cocher Stoop Wraparound Veranda Multi-Story  Significance: Historic Altered  Doors  Leaf: One-Leaf Material: Significance: Arrangem Historic Replacement Sidelig Transc  Windows Type: Material: Double-Hung Steel Sliding Wood Casement Vinyl Fixed Aluminum  Roof  Type: Mansard Hipped Shed	E Stone Wood Brick Concrete  Location: Front Rear Side Balcony  Type: Paneled W/Lights Com Glazed  Significance: Original Windows Original Storms Replaced Windows Replaced Storms  Material: Dormers: Asphalt Gable Metal Hipped
Type:  Enclosed Porte Cocher Stoop Wraparound Veranda Multi-Story  Significance: Historic Altered  Doors Leaf: One-Leaf Material: Significance: Arrangem Historic Sidelig Transc  Windows Type: Material: Double-Hung Steel Sliding Wood Casement Vinyl Fixed Aluminum  Roof  Type: Gable Mansard Hipped Shed Jerkinhead Flat	E Stone Wood Brick Concrete  Location: Front Rear Side Balcony  Type: Paneled W/Lights Glazed  Significance: Original Windows Original Storms Replaced Windows Replaced Storms  Material: Dormers: Asphalt Gable Metal Hipped Slate Shed
Type:  Enclosed Porte Cocher Stoop Wraparound Veranda Multi-Story  Significance: Historic Altered  Doors Leaf: One-Leaf Material: Significance: Arrangem Historic Sidelig Replacement Transc  Windows Type: Material: Double-Hung Steel Sliding Wood Casement Vinyl Fixed Aluminum  Roof  Type: Gable Mansard Hipped Shed Jerkinhead Flat Gambrel	E Stone Wood Brick Concrete  Location: Front Rear Side Balcony  Type: Paneled WLights Glazed  Significance: Original Windows Coriginal Storms Replaced Windows Replaced Storms  Material: Dormers: Asphalt Gable Metal Gable Slate Shed Shake Jerkin
Type:  Enclosed Porte Cocher Stoop Wraparound Veranda Multi-Story  Significance: Historic Altered  Doors Leaf: One-Leaf Material: Significance: Arrangem Historic Sidelig Transc  Windows Type: Material: Double-Hung Steel Sliding Wood Casement Vinyl Fixed Aluminum  Roof  Type: Gable Mansard Hipped Shed Jerkinhead Flat	E Stone Wood Brick Concrete  Location: Front Rear Side Balcony  Type: Paneled W/Lights Glazed  Significance: Original Windows Original Storms Replaced Windows Replaced Storms  Material: Dormers: Asphalt Gable Metal Hipped Slate Shed



Photo: 119\_E\_Boone\_St\_SURVEY\_Photo.tif **Description** 

The Colonial Revival, single-family brick home is two stories tall with a rectangular footprint, a symmetrical facade of five window bays and a side-gabled roof. Its features reference the Adams Style of American Colonial architecture . The asphalt roof of French method shingles are laid in a large diamond pattern. The main entrance, centered on the front façade, is composed of a paneled door with an elliptical fanlight and sidelights of leaded glass. The door assembly is set under a curved wood portico (under construction with temporary supports). A simple iron baluster lines the flat portico roof. The original wood windows are 6/1 and have paneled shutters with "topiary" cut outs. A small one story wing with 6/1 ganged windows and a flat roof is attached at the west elevation. A small, rectangular, enclosed threeseason porch with brick foundation and hipped roof is centered on the rear façade. A detached two-car, sidegabled garage is located on the west end of the property. Contemporaneous with the main house, it maintains the same brick, roofing and details. A small, one-car garage/shed with siding and a low asphalt shingled roof was built adjacent at a later date.

NR ELIGIBILITY	LOCAL ELIGIBILITY
Individual Eligibility 🛛	Individual Eligibility:⊠
District Eligibility:	District Eligibility: 🖂
District Name:	District Name:
Belvidere Old Town NRHP District	Belvidere Courthouse Square Local Historic District
Contributing: ⊠ Non-Contributing: □	Contributing:   Non-Contributing:
☐ Events (NR-A) ☐ Persons (NR-B) ☐ Architecture (NR-C) ☐ Archaeology (NR-D)	☐ Events 2 ☐ Persons 3 ☐ Architecture 4, 5, 6, 8 ☐ Archaeology ☑ Other 1, 7, 9, 10, 11

#### Courthouse Square Area Survey Date: 3/29/2014 **Property Information** Address: 404 E Boone PIN: 05-26-239-003 **Building Names:** Important Dates: **Historic Function:** Current Function: County Building Color Code Criteria: Outbuildings Any Significant: Number: Architectural Style: Property Type: Approximate Age: Condition: Potential for Integrity? Structure Information Structure: Photo: Foundation: Stone Concrete Not Visible Description Brick Parged See Record No.: 49A Cladding: Clapboard Asphalt Stucco Siding Shake Stone Brick Board-and-Batten Aluminum/Vinvl Concrete Block Asbestos Metal Additions Location: Type: Historic ☐ Front ☐ Rear Non-Historic Side Roof Porch Type: Material: Enclosed Porte Cochere Stone Wood Stoop Brick Concrete Wraparound Veranda Multi-Story Significance: Location: Historic Altered ☐ Front ☐ Rear Doors Side Balcony Leaf: Material: Type: Significance: Arrangement: Paneled Historic Sidelights Paneled w/Lights Replacement Transom Glazed Windows **LOCAL ELIGIBILITY NR ELIGIBILITY** Type: Material: Significance: Individual Eligibility: Individual Eligibility Double-Hung Steel **Original Windows** District Eligibility: District Eligibility: Wood **Original Storms** Slidina **District Name: District Name:** Casement Vinyl Replaced Windows Fixed Aluminum Replaced Storms Roof Type: Material: Dormers: Contributing: Contributing: Gable Mansard Asphalt Gable Non-Contributing: Non-Contributing: \_\_ Metal Hipped Shed Hipped Events 2 Events (NR-A) ☐ Jerkinhead ☐ Flat Slate Shed Persons (NR-B) Persons 3 Gambrel Shake Jerkin Architecture 4, 5, 6, 8 Architecture (NR-C) Clay Tile Chimney Archaeology (NR-D) Archaeology Material: ☐ Brick ☐ Concrete Block ☐ Stone Other 1, 7, 9, 10, 11

143

No.

**Belvidere Historic Resources Inventory:** 

No. 145 Survey Date:

3/29/2014

Property Information	
Address: 204 E Menominee	PIN: 05-26-258-005
Building Names:	
Important Dates:	
Historic Function: Residence	
Current Function: Residence	
Color Code Criteria: Red	
Outbuildings	
Number: 1 Any Signific	cant: 🔀
Architectural Style: Queen Anne	
Property Type: Residential	
Approximate Age: 1900-1909	
Condition: Good	
Potential for Integrity?	
Structure Information	
Structure: Frame	
Foundation: Stone Concrete	Not Visible
☐ Brick ☐ Parged	
Cladding: 🖂 Clapboard 🗀 A	sphalt
	Stucco
	stone
	Brick
	Concrete Block
	Metal
Additions	ictai
Type: Location:	
☐ Historic ☐ Front 🖂	Rear
⊠ Non-Historic ☐ Side ☐	Roof
Porch	
	Material:
Enclosed Porte Cochere	Stone Wood
Stoop Wraparound	Brick Concrete
☐ Veranda ☐ Multi-Story	
	Location:
Doors	= =
Leaf: One-Leaf	Side Balcony
Material: Wood	Type:
Significance: Arrangement	
	——————————————————————————————————————
Replacement Transom	Glazed
Windows	
	Significance:
□ Double-Hung    □ Steel    □	⊠ Original Windows
☐ Sliding ☑ Wood	Original Storms
Casement Vinyl	Replaced Windows
☐ Fixed ☐ Aluminum	Replaced Storms
Roof	
Type: Mate	
	Asphalt 🛛 🖾 Gable
	∕letal
	Slate
	Shake
Chimney	Clay Tile
Material: Srick Concrete E	Block Stone



Photo: 204\_E\_Menomonie\_St\_SURVEY\_Photo.tif **Description** 

The Queen Anne, single-family frame house is two-andone-half stories with a steeply pitched roof and crossgabled massing. The first floor is raised on a foundation of dressed, rusticated limestone, the exterior is clad in wood clapboard and a brick chimney stack is centrally located. At the primary elevation, facing south, a large gabled dormer is offset to give an asymmetrical arrangement. The east/west cross gables extend one window bay beyond the main hipped roof massing, forming rectangular window bays. A single-leaf paneled and lited entry door is situated at the southeast corner of the main façade, and a wood porch wraps around the south and east sides. At the east window bay, a paneled, lighted door provides a side entrance. The wood-framed porch is raised to first floor level with a hipped roof. Supported by turned columns and decorative brackets, there are spindled spandrel panels, a simple wood railing, and plain lattice. The north elevation, two-paneled doors are accessed from a central, raised wood porch with metal supports and a hipped roof. A paneled door at grade gives additional access. The attic level gables/gabled dormers are enclosed with pent roofs. At the primary façade, the...

NR ELIGIBILITY Individual Eligibility ⊠ District Eligibility: ⊠	LOCAL ELIGIBILITY Individual Eligibility:	
District Name:	District Name:	
Belvidere Old Town NRHP District	Belvidere Courthouse Square Local Historic District	
Contributing: ⊠ Non-Contributing: □	Contributing:  Non-Contributing:	
☐ Events (NR-A) ☐ Persons (NR-B) ☐ Architecture (NR-C) ☐ Archaeology (NR-D)	Events 2 Persons 3 Architecture 4, 5, 6, 8 Archaeology Other 1, 7, 9, 10, 11	

Building Names: Dr. Daniel Whitney Residence

PIN: 05-26-258-010

**Property Information** 

Address: 210-212E Menominie

No. 146

Survey Date: 3/29/2014

Important Dates: Historic Function: Residence Current Function: Residence Color Code Criteria: Red Outbuildings Number: 1 Any Significant:  Architectural Style: Greek Revival Property Type: Residential Approximate Age: 1850-1859 Condition: Fair Potential for Integrity?	
Structure Information	Men
Structure: Masonry	Photo: 2
Foundation: Stone Concrete Not Visible  Brick Parged	Descrip
Cladding: Clapboard Asphalt	front-g
Siding Stucco	Windov
Shake Stone	gabled
☐ Board-and-Batten ☐ Brick	the we
☐ Aluminum/Vinyl ☐ Concrete Block	of crea
Asbestos	commo
Additions	table.
Type: Location:	wide w
☐ Historic ☐ Front ☐ Rear	facing
Non-Historic ⊠ Side □ Roof	two wi
Porch	second
Type: Material:	with br
Enclosed Porte Cochere Stone Wood	suppor
Stoop Wraparound Brick Concrete Veranda Multi-Story	large s
	by side
Significance: Location:	single
Historic Altered Front Rear	once d
Doors ☐ Side ☐ Balcony Leaf: One-Leaf	origina   lights.
Material: Wood Type:	lights.     windov
Significance: Arrangement: Paneled	windov
☐ Historic ☐ Sidelights ☐ Paneled w/Lights	****
Replacement Transom Glazed	
Windows	NR EL
Type: Material: Significance:	Individ
Double-Hung Steel Original Windows	Distric
Sliding Wood Original Storms	Distric
Casement Vinyl Replaced Windows	11
Fixed Aluminum Replaced Storms	Belvide District
Roof Type: Material: Dormers:	Contrik
Gable Mansard Asphalt Gable	Non-C
☐ Hipped ☐ Shed ☐ Metal ☐ Hipped	
☐ Jerkinhead ☐ Flat ☐ Slate ☐ Shed	Ev
☐ Gambrel ☐ Shake ☐ Jerkin	∐ ☐ Pe
Chimney Clay Tile	│
Material: Stone Concrete Block Stone	
	I II II



Photo: 210-212\_E\_Menomonie\_St\_SURVEY\_Photo.tif

Description

reek Revival duplex is two-and-one-half stories with a abled roof and a rectangular plan spanning three ws bays wide and three bays deep. There is one rear addition and two side gabled additions extending to st. The original front gabled massing is constructed am colored brick (now painted), laid evenly in a on bond with a brick foundation and projecting water The cornice, discontinuous across the gable ends, is vith several bands of trim moldings. The front façade, south, has the main entrance placed to one side with ndow bays to one side and two above. A third d floor window above the entrance has been infilled rick. The entrance doorway has a simple entablature rted by square corner pilasters, and topped with a stone lintel. The single door, now replaced, is flanked elites with low, paneled bulkheads. Though now panes of obscured glass, the original sidelites were livided lites. In the front gable pediment there is an I triangular attic window with sunburst-like divided Along the east elevation, there are three first floor w openings and two at the second floor. The original N...

IR ELIGIBILITY	LOCAL ELIGIBILITY	
ndividual Eligibility 🛛	Individual Eligibility:	
District Eligibility: 🖂	District Eligibility: 🛚	
District Name:	District Name:	
selvidere Old Town NRHP District	Belvidere Courthouse Square Local Historic District	
Contributing: 🖂	Contributing:	
lon-Contributing:	Non-Contributing:	
Events (NR-A)	Events 2	
Persons (NR-B)	Persons 3	
⊠ Architecture (NR-C)		
Archaeology (NR-D)	Archaeology	

Other 1, 7, 9, 10, 11

Courthouse Square Area **Property Information** Address: 218 PIN: 05-26-258-008 E Menominee **Building Names:** Important Dates: Historic Function: Residence Current Function: Residence Color Code Criteria: Yellow Outbuildings Any Significant: X Number: 1 Architectural Style: Craftsman Property Type: Residential Approximate Age: 1910-1919 Condition: Poor Potential for Integrity? Structure Information Structure: Frame Foundation: Stone Concrete Not Visible Brick Parged Cladding: Clapboard ⊠ Asphalt Stucco Siding Shake Stone Board-and-Batten Brick Aluminum/Vinyl Concrete Block Asbestos Metal Additions Location: Type: Historic Front Rear Non-Historic Side Roof Porch Type: Material: Porte Cochere Wood Enclosed Stone Brick Concrete Stoop Wraparound Veranda Multi-Story Significance: Location: ⊠ Historic ⊠ Altered ⊠ Front Rear Doors Side Balcony Leaf: One-Leaf Material: Wood Type: Significance: Arrangement: Paneled Sidelights Mistoric | Paneled w/Lights Replacement Transom Glazed Windows Material: Significance: Type: Steel Original Windows Double-Hung Sliding ⊠ Wood Original Storms Replaced Windows Casement ⊠ Vinyl Fixed Aluminum Replaced Storms Roof Material: Dormers: Type: ⊠ Gable Mansard X Asphalt Gable Hipped Shed Metal Hipped

Jerkinhead Flat

Gambrel

Material:

Chimney

Slate

Shake

🗌 Clay Tile

⊠ Brick ☐ Concrete Block

Shed

Jerkin

147 No.

3/29/2014 Survey Date:




Photo: 218\_E\_Menomonie\_St\_SURVEY\_Photo.tif Description

The one-and-one-half story frame Bungalow cottage has a rectangular footprint and a broad side gabled roof with deep eaves. The first floor is raised on a rock-faced concrete block foundation, the walls are clad in asphalt siding and an internal brick chimney is located near the northwest corner. At the front elevation, facing south, the roof extends to cover a full width porch. The block foundation continues and forms tall piers at the roof supports. To one side there is a landscape window flanked by double-hung windows. The single leaf entry has a full, multi-lite original door with a double-hung window adjacent. At the roof there are large gabled dormers with a band of three double-hung windows. The side elevations typically have centered window placement at the second floor with irregularly placed window groupings at the first floor. Small rectangular windows pierce the foundation. Almost all of the original 4/1 and 3/1 double-hung wood windows remain. At the northwest corner of the lot there is a small-one car hippedroof garage with an original access door. Though modified, this cottage Bungalow has maintained moderate integrity.

· Po	
NR ELIGIBILITY	LOCAL ELIGIBILITY
Individual Eligibility	Individual Eligibility:
District Eligibility: ⊠	District Eligibility: 🖂
District Name:	District Name:
Belvidere Old Town NRHP District	Belvidere Courthouse Square Local Historic District
Contributing:   Non-Contributing:	Contributing:   Non-Contributing:
☐ Events (NR-A) ☐ Persons (NR-B) ☑ Architecture (NR-C) ☐ Archaeology (NR-D)	☐ Events 2 ☐ Persons 3 ☐ Architecture 4, 5, 6, 8 ☐ Archaeology ☐ Other 1, 7, 9, 10, 11

148 No.

3/29/2014 Survey Date:

Property Information		
Address: 222 E Menominee	PIN: 05-26-258-009	
Building Names:		
Important Dates:		
Historic Function: Residence Current Function: Residence		
Color Code Criteria: Orange		
Outbuildings		
Number: 1 Any Significant:	$\boxtimes$	
Architectural Style: Queen Anne		
Property Type: Residential		
Approximate Age: 1880-1889		
Condition: Good		
Potential for Integrity?		
Structure Information		
Structure: Frame	i	
Foundation: Stone Concrete	Not Visible I	
☐ Brick ⊠ Parged	1	
Cladding: Clapboard Asph	alt	
Siding Stuce		
☐ Shake ☐ Stone	e	
☐ Board-and-Batten ☐ Brick		
	rete Block	
Asbestos Metal		
Type: Location:		
Historic Front Rea	ar	
Non-Historic Side Roo		
	·	
Porch Type: Mate	erial:	
	Stone Wood	
	Brick Concrete	
☐ Veranda ☐ Multi-Story		
	ation:	
☐ Historic ☐ Altered ☐ F		
	ide Balcony	
Leaf: One-Leaf		
Material: Wood	Type:	
Significance: Arrangement:	Paneled	
Historic Sidelights	Paneled w/Lights	
Replacement Transom	Glazed	
Windows Type: Material: Sign	ificance:	
	Original Windows	
	Original Storms	
	Replaced Windows	
Lamber -	Replaced Storms	
Roof	.sp.acoa otomio	
Type: Material	: Dormers:	
☐ Gable ☐ Mansard ☐ Asph	nalt Gable	
☐ Hipped ☐ Shed ☐ Meta	ıl 🔲 Hipped 📗	
☐ Jerkinhead ☐ Flat ☐ Slate		
Gambrel Shake Jerkin		
Chimney Clay	Tile	
Material: Serick Concrete Bloc	k Stone	



Photo: 222\_E\_Menomonie\_St\_SURVEY\_Photo.tif

escription

The Queen Anne cottage is one-and-one-half stories with a cross gabled roof and plan. The first floor is raised on parged masonry foundation and the walls are clad in wood clapboards with corner boards. An internal brick chimney is located on center at the gable junction. At the primary elevation, facing south, there is a shaped front gable section with a one story front porch. Set on a concrete slab stoop, square posts support a flat roof. A single-leaf side entry door has one full lite, and a picture window assembly with flanking double-hungs is adjacent off center. Above is a pair of centered double-hung windows. The east/west cross gables have a shingled spandrel with typically centered window placement at the second floor with irregularly placed window groupings at the first floor. Small rectangular windows pierce the foundation. Almost all of the original double-hung windows have been replaced, but their plain wood frames remain. A wood deck at the northwest corner provides access to a rear entrance. At the north edge of the lot there is a two car gabled roof garage with exposed rafter tails and small windows. This Queen Anne cottage has been modified and altered, leaving it with a moderate to low level of integrity.

NR ELIGIBILITY Individual Eligibility   District Eligibility:	LOCAL ELIGIBILITY Individual Eligibility:  District Eligibility:
District Name:	District Name:
Belvidere Old Town NRHP District	Belvidere Courthouse Square Local Historic District
Contributing:   Non-Contributing:	Contributing: ⊠ Non-Contributing: □
☐ Events (NR-A) ☐ Persons (NR-B) ☐ Architecture (NR-C) ☐ Archaeology (NR-D)	☐ Events 2 ☐ Persons 3 ☐ Architecture 4, 5, 6, 8 ☐ Archaeology ☐ Other 1, 7, 9, 10, 11

No. 149

Survey Date: 3/29/2014

Address: 330 E Menominee	PIN: 05-26-258-008
Building Names:	
Important Dates:	
Historic Function: Residence	
Current Function: Residence Color Code Criteria: Blue	
Outbuildings	
	gnificant:
Architectural Style: Mid-Century	
Property Type: Residential	
Approximate Age: 1970-1979	
Condition: Good	
Potential for Integrity?	
Structure Information	ĭ
	1
Structure: Masonry	
Foundation: Stone Concr	
☐ Brick ☐ Parge	ed [
Cladding: Clapboard	Asphalt
☐ Siding	Stucco
☐ Shake	Stone
☐ Board-and-Batten	⊠Brick
☐ Aluminum/Vinyl	Concrete Block
Asbestos	Metal
Additions	
Type: Location	·
Historic Front	= · · · · · · I
Non-Historic	Roof
Daniel.	
Porch	l l
Type:	Material:
Type: Porte Coche	re Stone Wood
Type:  Enclosed Porte Coche Stoop Wraparound	re Stone Wood
Type: Porte Coche	re Stone Wood
Type:  Enclosed Porte Coche Stoop Wraparound	re Stone Wood
Type:  ☐ Enclosed ☐ Porte Coche ☐ Stoop ☐ Wraparound ☐ Veranda ☐ Multi-Story	re Stone Wood Brick Concrete
Type:  Enclosed Porte Coche Stoop Wraparound Veranda Multi-Story  Significance: Historic Altered  Doors	re Stone Wood Brick Concrete  Location: Front Rear
Type:  Enclosed Porte Coche Stoop Wraparound Veranda Multi-Story  Significance: Historic Altered  Doors Leaf: One-Leaf	re Stone Wood □ Brick Concrete  Location: □ Front □ Rear □ Side □ Balcony
Type:  Enclosed Porte Coche Stoop Wraparound Veranda Multi-Story  Significance: Historic Altered  Doors Leaf: One-Leaf Material: Wood	re Stone Wood Brick Concrete  Location: Front Rear Side Balcony  Type:
Type:  Enclosed Porte Coche Stoop Wraparound Veranda Multi-Story  Significance: Historic Altered  Doors Leaf: One-Leaf Material: Wood Significance: Arranger	re Stone Wood Brick Concrete  Location: Front Rear Side Balcony  Type: nent: Paneled
Type:  Enclosed Porte Coche Stoop Wraparound Veranda Multi-Story  Significance: Historic Altered  Doors Leaf: One-Leaf Material: Wood Significance: Arranger  Historic Sideli	re Stone Wood Brick Concrete  Location: Front Rear Side Balcony  Type: ment: Paneled ghts Paneled w/Lights
Type:    Enclosed   Porte Coche   Stoop   Wraparound   Veranda   Multi-Story     Significance:   Altered     Doors   Leaf: One-Leaf   Material: Wood   Significance:   Arranger   Arranger   Sidelia   Replacement   Trans	re Stone Wood Brick Concrete  Location: Front Rear Side Balcony  Type: ment: Paneled ghts Paneled w/Lights
Type:  Enclosed Porte Coche Stoop Wraparound Veranda Multi-Story  Significance: Historic Altered  Doors Leaf: One-Leaf Material: Wood Significance: Arranger  Historic Sideli Replacement Trans  Windows	re Stone Wood □ Brick Concrete  Location: □ Front □ Rear □ Side □ Balcony  Type: nent: □ Paneled □ Paneled w/Lights som □ Glazed
Type:  Enclosed Porte Coche Stoop Wraparound Veranda Multi-Story  Significance: Historic Altered  Doors Leaf: One-Leaf Material: Wood Significance: Arranger Historic Sideli Replacement Trans  Windows Type: Material:	re Stone Wood Brick Concrete  Location: Front Rear Side Balcony  Type: Paneled Sphts Of Balcony  Type: Glazed  Significance:
Type:  Enclosed Porte Coche Stoop Wraparound Veranda Multi-Story  Significance: Historic Altered  Doors  Leaf: One-Leaf Material: Wood Significance: Arranger Historic Sideli Replacement Trans  Windows Type: Material: Double-Hung Steel	re Stone Wood Brick Concrete  Location: Front Rear Side Balcony  Type: Paneled Paneled w/Lights Glazed  Significance: Original Windows
Type:  Enclosed Porte Coche Stoop Wraparound Veranda Multi-Story  Significance: Historic Altered  Doors Leaf: One-Leaf Material: Wood Significance: Arranger Historic Sideli Replacement Trans  Windows Type: Material: Double-Hung Steel Sliding Wood	re Stone Wood Brick Concrete  Location: Front Rear Side Balcony  Type: Paneled Paneled WLights Glazed  Significance: Original Windows Original Storms
Type:  Enclosed Porte Coche Stoop Wraparound Veranda Multi-Story  Significance: Historic Altered  Doors  Leaf: One-Leaf Material: Wood Significance: Arranger Historic Sideli Replacement Trans  Windows Type: Material: Double-Hung Steel Sliding Sliding Casement Vinyl	re Stone Wood Brick Concrete  Location: Front Rear Side Balcony  Type: Paneled Paneled w/Lights Glazed  Significance: Original Windows Original Storms Replaced Windows
Type:    Enclosed   Porte Coche   Stoop   Wraparound   Veranda   Multi-Story     Significance:	re Stone Wood Brick Concrete  Location: Front Rear Side Balcony  Type: Paneled Paneled w/Lights Glazed  Significance: Original Windows Original Storms Replaced Windows
Type:  Enclosed Porte Coche Stoop Wraparound Veranda Multi-Story  Significance: Historic Altered  Doors Leaf: One-Leaf Material: Wood Significance: Arranger Historic Sideli Replacement Trans  Windows Type: Material: Double-Hung Steel Sliding Wood Casement Vinyl Fixed Aluminur  Roof	re Stone Wood Brick Concrete  Location: Front Rear Side Balcony  Type: Paneled Paneled w/Lights Glazed  Significance: Original Windows Original Storms Replaced Windows Replaced Storms
Type:    Enclosed   Porte Coche   Stoop   Wraparound   Veranda   Multi-Story     Significance:	re Stone Wood Brick Concrete  Location: Front Rear Side Balcony  Type: Paneled W/Lights Glazed  Significance: Original Windows Original Storms Replaced Windows Replaced Storms  Material: Dormers:
Type:    Enclosed   Porte Coche   Stoop   Wraparound   Veranda   Multi-Story   Significance:   Historic   Altered   Altered   Doors   Leaf: One-Leaf   Material: Wood   Significance: Arranger   Sideli   Trans   Trans     Historic   Sideli   Trans   Sideli   Trans   Windows   Type: Material:   Steel   Wood   Sliding   Steel   Wood   Aluminur   Roof   Type:   Gable   Mansard   Mansard	re Stone Wood Brick Concrete  Location: Front Rear Side Balcony  Type: Paneled Paneled WLights Glazed  Significance: Original Windows Original Storms Replaced Windows Replaced Storms  Material: Dormers: Asphalt Gable
Type:  Enclosed Porte Coche Stoop Wraparound Veranda Multi-Story  Significance: Historic Altered  Doors  Leaf: One-Leaf Material: Wood Significance: Arranger Historic Sideli Replacement Trans  Windows Type: Material: Double-Hung Steel Sliding Wood Casement Vinyl Fixed Aluminur  Roof  Type: Gable Mansard Hipped Shed	re Stone Wood Brick Concrete  Location: Front Rear Side Balcony  Type: Paneled Paneled w/Lights Glazed  Significance: Original Windows Original Storms Replaced Windows Replaced Storms  Material: Dormers: Asphalt Gable Hipped
Type:  Enclosed Porte Coche Stoop Wraparound Veranda Multi-Story  Significance: Historic Altered  Doors Leaf: One-Leaf Material: Wood Significance: Arranger Historic Sideli Replacement Trans  Windows Type: Material: Double-Hung Steel Sliding Wood Casement Vinyl Fixed Aluminur  Roof  Type: Gable Mansard Hipped Shed Jerkinhead Flat	re Stone Wood Brick Concrete  Location: Front Rear Side Balcony  Type: Paneled Paneled w/Lights Glazed  Significance: Original Windows Original Storms Replaced Windows Replaced Storms  Material: Dormers: Asphalt Gable Metal Hipped Slate Shed
Type:    Enclosed   Porte Coche   Stoop   Wraparound   Veranda   Multi-Story   Significance: Altered   Altered	re Stone Wood Brick Concrete  Location: Front Rear Side Balcony  Type: Paneled WLights Glazed  Significance: Original Windows Original Storms Replaced Windows Replaced Storms  Material: Dormers: Asphalt Gable Slate Shed Jerkin
Type:  Enclosed Porte Coche Stoop Wraparound Veranda Multi-Story  Significance: Historic Altered  Doors  Leaf: One-Leaf Material: Wood Significance: Arranger Historic Sideli Replacement Trans  Windows Type: Material: Double-Hung Steel Sliding Wood Casement Vinyl Fixed Aluminur  Roof  Type: Gable Mansard Hipped Shed Jerkinhead Flat Gambrel  Chimney	re Stone Wood Brick Concrete  Location: Front Rear Side Balcony  Type: Paneled Paneled w/Lights Glazed  Significance: Original Windows Original Storms Replaced Windows Replaced Storms  Material: Dormers: Asphalt Gable Metal Hipped Slate Shed



Photo: 330\_E\_Menomonie\_St\_SURVEY\_Photo.tif **Description** 

home.

The single-family standard Ranch home is one story tall with a hipped roof and rectangular plan. The walls are set on a concrete foundation and clad in a pink brick veneer with an internal brick chimney on center at the rear elevation. At the east, the front facing two car garage extends forward of the front façade. A wide picture window is flanked by two one-lite casement windows. Located on center at a low concrete stoop is the main entrance, which features the original single leaf slab door with a diamond lite and a diamond pane sidelight. The remaining window openings are pairs of 1-lite casements with cast stone slip sills. The size and configuration have been maintained, making this a modest example of a mid-20th century Ranch

NR ELIGIBILITY Individual Eligibility District Eligibility: District Name:	LOCAL ELIGIBILITY Individual Eligibility: District Eligibility: District Name:
Contributing:  Non-Contributing:  Events (NR-A) Persons (NR-B) Architecture (NR-C) Archaeology (NR-D)	Contributing:  Non-Contributing:  Events 2 Persons 3 Architecture 4, 5, 6, 8 Archaeology

**No.** 150A

Survey Date: 3/29/2014

Property Information		
Address: PIN: 05-26-276-001		24
Building Names: Big Thunder Park		N.
Important Dates: 1910 Historic Function: Park		
Current Function: Park		selfan M. L
Color Code Criteria: Red		
Outbuildings		WHI.
Number: Any Significant: ⊠		
Architectural Style: Classical Revival		
Property Type: Public		
Approximate Age: 1880-1889		
Condition: Good/Excellent		
Potential for Integrity?		7
Structure Information		
Structure: Masonry	Photo: Big Thunder Park Sol	diers_Sailors_SURVEY_Photo.tif
Foundation: Stone Concrete Not Visible	Description	
☐ Brick ☐ Parged	Big Thunder Park, a public pa	rk located in the original
	1 -	_
	public square, comprises two	
☐ Siding ☐ Stucco ☐ Shake ☐ Stone	land bordered by E. Menonon Street to the east, E. Perry to	
☐ Board-and-Batten ☐ Brick	to the west. Though named for	
☐ Aluminum/Vinyl ☐ Concrete Block	attributed to Big Thunder's gra	-
Asbestos Metal	in front of the court house and	
Additions	Several monuments and a ba	
Type: Location:	center and northern sections,	
☐ Historic ☐ Front ☐ Rear	and basketball courts have be	
☐ Non-Historic ☐ Side ☐ Roof	Towards the northeast corner	
Porch	monument, the Soldiers and S	
Type: Material:	in 1910, the inscription tells th	
Enclosed Porte Cochere Stone Wood	John Ramsey. Constructed o	I
Stoop Wraparound Brick Concrete	stepped, square base with slo	*
☐ Veranda ☐ Multi-Story	The low inscription panel is de	. •
Significance: Location:	and bands of five-point stars.	
☐ Historic ☐ Altered ☐ Front ☐ Rear	with an entablature decorated	with palmettes. Raised at
Doors Side Balcony	the high pedestal is the figure	
Leaf:	holding a flag in one hand and	d reaching for his sword with
Material: Type:	the other.	
Significance: Arrangement: Paneled		
Historic Sidelights Paneled w/Lights		
Replacement Transom Glazed		
Windows	NR ELIGIBILITY	LOCAL ELIGIBILITY
Type: Material: Significance:	Individual Eligibility 🖂	Individual Eligibility: 🖂
Double-Hung Steel Original Windows	District Eligibility:	District Eligibility:
Sliding Wood Original Storms	District Name:	District Name:
Casement Vinyl Replaced Windows		Belvidere Courthouse Square
Fixed Aluminum Replaced Storms	Belvidere Old Town NRHP	Local Historic District
Roof Type: Material: Dormers:	District	
Gable Mansard Asphalt Gable	Contributing:	Contributing:
Hipped Shed Metal Hipped	Non-Contributing:	Non-Contributing:
☐ Jerkinhead ☐ Flat ☐ Slate ☐ Shed	Events (NR-A)	Events 2
Gambrel Shake Jerkin	Persons (NR-B)	Persons 3
Chimney Clay Tile	Architecture (NR-C)	Architecture 4, 5, 6, 8
	Archaeology (NR-D)	Archaeology
Material: Brick Concrete Block Stone		⊠ Other 1, 7, 9, 10, 11

Courthouse Square Area

No. 150B

Survey Date: 3/29/2014

Property Information
Address: PIN: 05-26-276-001
Building Names: Big Thunder Park
Important Dates: 1910
Historic Function: Park
Current Function: Park
Color Code Criteria: Red
Outbuildings
Number: Any Significant: Architectural Style: Stick
Property Type: Public
Approximate Age: 1880-1889
Condition: Good/Excellent
Potential for Integrity?
Structure Information
Structure: Frame
Foundation: Stone Concrete Not Visible Brick Parged
Cladding: Clapboard Asphalt
Siding Stucco
☐ Shake ☐ Stone
Board-and-Batten Brick
Aluminum/Vinyl Concrete Block
Asbestos Metal
Additions
Type: Location:
☐ Historic ☐ Front ☐ Rear
☐ Non-Historic ☐ Side ☐ Roof
Porch
Type: Material:
Enclosed Porte Cochere Stone Wood
Stoop Wraparound Brick Concrete
☐ Veranda ☐ Multi-Story
Significance: Location:
☐ Historic ☐ Altered ☐ Front ☐ Rear
Doors Side Balcony
Leaf:
Material: Type:
Significance: Arrangement: Paneled
☐ Historic ☐ Sidelights ☐ Paneled w/Lights
Replacement Transom Glazed
Windows
Type: Material: Significance:
Double-Hung Steel Original Windows
Sliding Wood Original Storms
Casement Vinyl Replaced Windows
Fixed Aluminum Replaced Storms
Roof Type: Material: Dormers:
Gable Mansard Asphalt Gable
☐ Hipped ☐ Shed ☐ Metal ☐ Hipped ☐ Jerkinhead ☐ Flat ☐ Slate ☐ Shed
Gambrel Shake Jerkin
Material: Brick Concrete Block Stone



Photo: Big\_Thunder\_Park\_Bandstand\_SURVEY\_Photo.tif **Description** 

Big Thunder Park, a public park located in the original public square, comprises two city blocks of gently graded land bordered by E. Menonomie St to the north, N. Main Street to the east, E. Perry to the south, and Van Buren St. to the west. Though named for Chief Big Thunder, the site attributed to Big Thunder's grave is located across Main St. in front of the court house and present-day police station. Several monuments and a bandstand are located at the center and northern sections, while a modern playground and basketball courts have been installed at the south. Located in the center of the park is the small, Queen Anne style bandstand. Raised on a foundation of open, rockfaced blocks is a poured concrete floor. The hipped and cross-gabled roofline is picturesque, with small shed roof hoods extending from the north and south gables. Turned columns and simple decorative brackets and braces support the roof and a simple metal railing has been installed around the edge. An historic post card shows the bandstand on wood posts with an enclosed base of vertical batten boards. A plain railing with turned posts and a decorative ridge roll at the hipped roof are also missing.

NR ELIGIBILITY	LOCAL ELIGIBILITY
Individual Eligibility 🔀	Individual Eligibility:⊠
District Eligibility:	District Eligibility: 🖂
District Name:	District Name:
Belvidere Old Town NRHP District	Belvidere Courthouse Square Local Historic District
Contributing: 🖂	Contributing:
Non-Contributing:	Non-Contributing:
Events (NR-A)	Events 2
Persons (NR-B)	Persons 3
Architecture (NR-C)	Architecture 4, 5, 6, 8
Archaeology (NR-D)	Archaeology
	Other 1 7 9 10 11

**No.** 150C

Survey Date: 3/29/2014

Property Information	E 12.3.3.33	
Address: PIN: 05-26-276-001 Building Names: Big Thunder Park Important Dates: 1910 Historic Function: Park Current Function: Park Color Code Criteria: Red Outbuildings Number: Any Significant:  Architectural Style: Varied		
Property Type: Public Approximate Age: 1880-1889		
Condition: Good/Excellent	A CONTRACTOR OF THE PARTY OF TH	<b>建设是不可能。</b>
Potential for Integrity?		
Structure Information		THE STATE OF THE S
Structure: Masonry	Photo: Big_Thunder_Park_Hurlbut_SURVEY_Photo.tif	
Foundation: Stone Concrete Not Visible	Description	
☐ Brick ☐ Parged	Big Thunder Park, a public park located in the original	
Cladding: Clapboard Asphalt Siding Stucco Shake Stone Board-and-Batten Brick Aluminum/Vinyl Concrete Block Asbestos Metal  Additions Type: Location: Historic Front Rear Non-Historic Side Roof  Porch Type: Material: Enclosed Porte Cochere Stoop Wraparound Veranda Multi-Story Significance: Location: Historic Altered Front Rear Doors Leaf: Material: Type: Significance: Arrangement: Paneled Historic Sidelights Replacement Transom Glazed	public square, comprises two city blocks of gently graded land bordered by E. Menonomie St to the north, N. Main Street to the east, E. Perry to the south, and Van Buren St. to the west. Though named for Chief Big Thunder, the site attributed to Big Thunder's grave is located across Main St. in front of the court house and present-day police station. Several monuments and a bandstand are located at the center and northern sections, while a modern playground and basketball courts have been installed at the south. Just west of the bandstand, on axis with E. Boone St., there is a flag pole, donated by the Belvidere Woman's Club in 1976, and a large rock-mounted memorial marker. The plaque commemorates the sinking of the U.S.S. Maine, February 15th, 1898, and is cast from metal recovered from the wreckage. Along the north edge of the park there are two more small monuments. One, the Boone County Bicentennial Memorial, is made of granite and has had time capsules buried at its base. The bicentennial capsule, buried July 4, 1976, is be opened in 2076, and the sesquicentennial capsule, buried October 6, 1985, is to be opened in 2084. The	
Windows	NR ELIGIBILITY	LOCAL ELIGIBILITY
Type: Material: Significance:  Double-Hung Steel Original Windows Sliding Wood Original Storms Replaced Windows Fixed Aluminum Replaced Storms  Roof Type: Material: Dormers: Gable Mansard Asphalt Gable Hipped Shed Metal Hipped Jerkinhead Flat Slate Gambrel Shake Chimney  Material: Dormers: Gable Mansard Slate Shed Jerkin	Individual Eligibility District Eligibility: District Name: Belvidere Old Town NRHP District Contributing: Non-Contributing: Events (NR-A) Persons (NR-B) Architecture (NR-C) Archaeology (NR-D)	Individual Eligibility:  District Eligibility:  District Name:  Belvidere Courthouse Square Local Historic District  Contributing:  Non-Contributing:  Events 2  Persons 3  Architecture 4, 5, 6, 8  Archaeology
Chimney  Material: Brick Concrete Block Stone	[ ] [ ] [ ] [ ] [ ] [ ] [ ] [ ] [ ] [ ]	William Committee to the second of the secon